



status report

customer: Bank 11, Neuss
contract number: 1165406630
reference:

vehicle data

Jeep Renegade S Plug-In-Hybrid 4xe

Vehicle identification number	1C4BU0000LP006342	mileage read:	39252 km
..			
First Registration / construction year:	16.06.2021 / 2020	Visit Date / place of birth:	12.09.2025 Dahlwitz- Hoppegarten
Bodywork:	SUV	Re - import:	no
Body type:	Road /	KBA no. :	1726//ACP
Fuel / emission class:	Petrol / hybrid / € 6	transmission type:	automatic
Displacement / power:	1332 ccm / 132 kW (179 PS)	Engine:	four-wheel
paint:	COLORADO RED CLEAR COAT	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	37790 / 23.09.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	2 - Good
visit condition:	-	condition inside:	2 - Good
state general:	2 - Good		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	37790 / 23.09.2024
		yes / -	
<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> partition net	<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> AHK fixed
<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK swivel	<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> Fernbed . entertainment
<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> navigation system
<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> Xenon headlights		

☒ available

☒ not available

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Pirelli	235/45/R19/99Y 6 mm
1st axis - right / states .	Pirelli	235/45/R19/99Y 6 mm
2nd axis - Left / states .	Pirelli	235/45/R19/99Y 6 mm
2nd axis - right / states .	Pirelli	235/45/R19/99Y 6 mm
traffic Safety:	not roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Airbag • Trailer Stabilization Program • front armrest • Automatic driving light / light sensor • Power side mirrors . adjustable and heated, both • • Flashing light integrated in exterior mirrors • Electron. Stability Program (ESP) • Driving Assistance System Collision Warning (Forward Collision Warning)
<i>Geschwindigkeits-Regelanlage (Tempomat) mit Abstandsregelung</i> • Driving Assistance System High-Beam Assistant • Driver assistance system Lane Keeping Assist • Rollover protection system (ERM) • Electric window lift at the front • Foot mats • Cruise control system (cruise control) • Information Center (EVIC) with 7 display • Isofix admissions for child seat • License plate light LED • 3-zone automatic climate control • Charging cable with Schuko plug (Mode 2) • • Steering wheel (leather) • Steering wheel with multifunction • Light and rain sensor • model refinement • Fog lamps with integrated cornering • Park brake electro-mechanical • Plug-in Hybrid-Technologie | <ul style="list-style-type: none"> • Driver's airbag • Drive type all-wheel drive • Audio-Navigationssystem UConnect Smarttouch VP4 Navigation (Touchscreen 8,4")
<i>DAB-Tuner (Radioempfang digital), Mobile Online Dienste Live Service, Smartphone Schnittstelle (Apple CarPlay & Android Auto)</i> • Power side mirrors . anklappbar • Exterior mirrors with Blind Spot Assist • Passenger airbag can be switched off • roof rails • Electron. traction control • Hill Start Assist • • Driver assistance system traffic sign recognition (TSR) • • Control for central locking • • Transmission automatic - (6-step) • Rearview mirror with auto dip • Body 5-door • Air conditioning 2-zone • Head airbag system (Windowbag), front and rear • LED package
<i>Matrix-LED-Scheinwerfer, Heckleuchten LED, Nebelscheinwerfer LED, Tagfahrlicht LED</i> • steering wheel (leatherette) • heated steering wheel • Steering column (steering wheel) mechan . adjustable |
|---|---|

<ul style="list-style-type: none"> • Wheelbase 2570 mm • Tire Pressure Monitoring System • • • Close / start system Keyless Go • Side airbag in front • Electronically controlled power steering • <i>Sitz vorn rechts verstellbar (4-fach)</i> • Seatback folding front right • Socket 12V connector • Glazing behind darkened • Central locking with remote control 	<ul style="list-style-type: none"> • LM rims • Engine 1.3 Ltr. - 132 kW Turbo Hybrid <i>Hybrid 177 kW (Motor 1,3 Ltr. - 132 kW)</i> • • Park Pilot system, front and rear • Radio preparation , 6 Speaker • Tire repair kit • Rear View Camera • • LED headlights • side airbags • power steering • • Heated front seats • Start / stop system • Door handle exterior body color • Central
--	--

special Features

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	no no
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body



outer skin. The measured values ??were within the tolerances of original finishes .
Evidence that points to a repaired accident damage or repainting carried out , were
identified.

Existing collision damage:

Not established


On the vehicle body shell were on visual examination found no existing accident
damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			Out of order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. motor	Error message	Carry out a fault diagnosis
3. Reifendrucküberwachung	Error message	Carry out a fault diagnosis
4. tailgate	Deformed (slightly)	Smart repair
5. Rear bumper	Scratch(es)	Smart repair
6.	Scratch(es)	Paint
7. tire front - right	Damaged	Replace
8.	Scratch(es)	Paint
9. exterior body	Sticker	
10. battery	Empty battery	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims




engine compartment



service book



Others



Navigation system



2. motor



3. Reifendrucküberwachung



4. tailgate



5. Rear bumper



6.



7. tire front - right



8.



8.



9. exterior body



9. exterior body