

status report

customer: Bank 11, Neuss
contract number: 943375930
reference:

vehicle data

Jeep Grand Cherokee 3.0 CRD Overland

Vehicle identification number	1C4RJFCM8JC435290	mileage read:	147299 km
First Registration / construction year:	10.01.2019 / 2018	Visit Date / place of birth:	01.09.2025 Dorfmark
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	1004//AAZ
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2987 ccm / 184 kW (250 PS)	Engine:	four-wheel
paint:	gray	Number of previous owners:	-
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	11.2026 / 11.2026	cushion type:	leather
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	83615 / 03.04.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	83615 / 03.04.2023

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Bridgestone	265/60/R18/-H 3 mm
1st axis - right / states .	Bridgestone	265/60/R18/-H 3 mm
2nd axis - Left / states .	Bridgestone	265/60/R18/-H 4 mm
2nd axis - right / states .	Bridgestone	265/60/R18/-H 4 mm
traffic Safety:	not roadworthy	
spare wheel:	vorhanden	
state spare wheel:	Gebraucht	

standard equipment	
• Airbag Driver / passenger side • Trailer Stabilization Program • Acceleration skid control (ASR) • Display for tire pressure display • Audio controls on steering wheel • Power side mirrors . anklappbar • Exterior mirrors with auto dip • Body color door mirrors • board computer • CD drive in the center armrest • Theft alarm system with interior monitoring • Electron. Stability Program (ESP) • Driving Assistance System Collision Warning (Forward Collision Warning) • Hill Start Assist • Driving Assistance System Brake Assist • Rollover protection system (ERM) • UConnect hands-free kit (with Bluetooth interface) • Cruise control system (cruise control) with distance control • Tailgate opening electrically • Interior monitoring • Isofix admissions for child seat • 2-zone automatic climate control • Head airbag system (Windowbag), front and rear • Lumbar support front right seat • Steering column (steering wheel) electr. height / longitudinally adjustable • Air suspension (Quadra -Lift) • Model maintenance (2) • Fog Lights	• Active head restraints • Anti- lock braking system (ABS) • Engine Quadra - Drive II (wheel) • Audio navigation system Smartouch UConnect multimedia system with navigation system • Automatic driving light / light sensor • Power side mirrors . adjustable and heated, both • Exterior mirrors with Blind Spot Assist • Bi -xenon headlights <i>Scheinwerfer-Reinigungsanlage (SRA)</i> • brake Assist • Chrome roof rails • Sill plates (Chrome) • Electron. traction control • Driving Assistance System hill descent assist • Driving Assistance System High-Beam Assistant • • Electric windows front + rear • Luggage compartment cover / shade • Automatic transmission - (8-step) • Interior burl wood • Rearview mirror with auto dip • Body 5-door • Knee airbag , driver's side • Lumbar support front left seat • heated steering wheel • LM rims • Memory function - mirrors, seat • Engine 3.0 ltr. - 184 kW CRD KAT • Rear fog light • Park Pilot system, front and rear

• Panoramic roof front electric, rear fixed • Wheelbase 2915 mm • Spare wheel • Rear View Camera • Low pollutant according to the Euro 6d-TEMP emissions standard • Windscreen wipers with rain sensor • side airbags • power steering • Front right seat electr. adjustable • Seat cover / Nappa leather upholstery • Heated front seats • Sun visors with mirrors (illuminated) • Sport seats • LED daytime running lights • Underrun protection • Glazing behind darkened • Heat -insulating glass (insulating glass)	• Tire Pressure Monitoring System • Rußpartikelfilter • Rear seat split / folding • Gearshift / selector lever leather • Close / start system Keyless Go • Side moldings chrome look • Front left seat electr. adjustable • Front seat ventilation • Heated rear • Smartphone interface (Apple CarPlay & Android Auto) • Alpine Premium Sound System • Body color bumpers • Outside Door Handle chrome • USB port • immobilizer • Central locking with remote control
--	--

special Features	
• Trailer regulation <i>Niveauregulierung</i>	• Metallic paint

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Parkbremse Fehlermeldung

Farbabweichung Plastikteile

Accident injury assessment
Rep. Predamages / -height gross: If not properly repaired



The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

**Layers of paint thickness
measurement:**

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Karosserie Außen komplett Nachlackiert Lackbild teilweise nicht Fachgerecht instandgesetzt und lackiert Parkbremse Fehlermeldung Fehlerdiagnose durchführen lassen Schaden und Kosten Erweiterung möglich

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. Front fender - right	Subsequently painted	acceptable
3. A-pillar Front - right	Subsequently painted	acceptable
4. Front door - right	Subsequently painted	acceptable
5. roof	Subsequently painted	acceptable
6. Door Rear - right	Subsequently painted	acceptable
7. Roof frame - right	Subsequently painted	acceptable
8. Sidewall - Rear - right	Subsequently painted	acceptable
9. tailgate	Subsequently painted	acceptable
10. Sidewall - Rear - Left	Subsequently painted	acceptable
11. Roof frame - left	Subsequently painted	acceptable
12. Rear door - left	Subsequently painted	acceptable
13. Front door - left	Subsequently painted	acceptable
14. A-pillar Front - Left	Subsequently painted	acceptable
15. Front fender - left	Subsequently painted	acceptable
16. maintenance	Due	Replace
17. Parkbremse	Error message	Carry out a fault diagnosis
18. Sidewall - Rear - Left		Refurbish and paint
19. Felge (Aluminium) hinten links	Scratch(es)	Paint
20. Front door - left	Scrape	Smart repair
21. tailgate	Delle	Smart repair
22. A-pillar Front - Left	Chipping from stones	Smart repair
23.	Scrape	Smart repair
24. Front bumper	Scrape	Smart repair
25.	Worn	Replace
26.	Worn	Replace
27. roof	Delle	Smart repair
28. exterior body	Surface scratch(es)	
29.	Wear and tear	acceptable
30.	Dirty	
31.	Damaged	Replace
32.	Dirty (animal hair)	
33.	Odour	Ozone treatment
34.	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for

fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. hood



2. Front fender - right



3. A-pillar Front - right



4. Front door - right



5. roof



6. Door Rear - right



7. Roof frame - right



8. Sidewall - Rear - right



9. tailgate



10. Sidewall - Rear - Left



11. Roof frame - left



12. Rear door - left



13. Front door - left



14. A-pillar Front - Left



15. Front fender - left



17. Parkbremse



17. Parkbremse



18. Sidewall - Rear - Left



18. Sidewall - Rear - Left



18. Sidewall - Rear - Left



19. Felge (Aluminium) hinten links



19. Felge (Aluminium) hinten links




20. Front door - left



20. Front door - left



20. Front door - left



21. tailgate



21. tailgate



22. A-pillar Front - Left



22. A-pillar Front - Left



23.



23.



24. Front bumper



24. Front bumper



24. Front bumper



25.



26.



27. roof



27. roof



28. exterior body



29.



29.



30.



30.




31.




31.



32.



32.



32.



34.



34.