



status report

customer: Bank 11, Neuss
contract number: 903930931
reference:

vehicle data

Dodge Ram 1500

Vehicle identification number	1C6RR7LG3MS589304	mileage read:	50389 km
∴			
First Registration / construction year:	10.11.2021 / 2021	Visit Date / place of birth:	18.09.2025 Neuss
Bodywork:	SUV	Re - import:	yes
Body type:	Road /	KBA no. :	1726//000
Fuel / emission class:	Petrol / Gas / € 6	transmission type:	automatic
Displacement / power:	3604 ccm / 227 kW (309 PS)	Engine:	four-wheel
paint:	-	Number of previous owners:	Unbekannt
Doors / seats:	4 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	-
Service book available:	no	Interior Color:	-
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	- / -
		no / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Goodyear	275/60/R20/-S 4 mm
1st axis - right / states .	Goodyear	275/60/R20/-S 4 mm
2nd axis - Left / states .	Goodyear	275/60/R20/-S 4 mm
2nd axis - right / states .	Goodyear	275/60/R20/-S 4 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

special Features

standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • ABS • Power side mirrors . • board computer • Power windows • LNG plant • Climate Control • Mult-function Comfort seat front right • Multimedia modules • side airbags • Heated seats • immobilizer • Central locking with remote control | <ul style="list-style-type: none"> • four-wheel • Power side mirrors . anklappbar • ESP • Driver and passenger airbags • air Conditioning • Mult-function Comfort seat front left • Multifunction steering wheel • PDC / H • power steering • cruise control • central locking |
|--|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Die Reifen haben keine gesetzliche Kennzeichnung.

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited	 examined limited	
air conditioning:			examined limited	lighting system:	
coupling:			examined limited	 examined limited	
engine running:			examined limited	exhaust System:	
transmission:			examined limited	shock absorber:	
				 not possible	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Alters-, Transport- und Laufleistungsbedingte Gebrauchsspuren vorhanden. Kosten- und Schadensenerweiterung möglich. Die Lackschichtdicke ist rundum erhöht. Ein Importfahrzeug ist nicht ausgeschlossen. Die Reifen haben keine Gesetzliche Kennzeichnung. Das Fahrzeug hat eine Gasanlage nachgerüstet. Schäden und Folgeschäden sind nicht ausgeschlossen. Das Fahrzeug wurde verschmutzt besichtigt. Schäden sind nicht ausgeschlossen.

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. Front fender - right	Subsequently painted	acceptable
3. Front door - right	Subsequently painted	acceptable
4. A-pillar Front - right	Subsequently painted	acceptable
5. Door Rear - right	Subsequently painted	acceptable
6. Roof frame - right	Subsequently painted	acceptable
7. Sidewall - Rear - right	Subsequently painted	acceptable
8. tailgate	Subsequently painted	acceptable
9. Sidewall - Rear - Left	Subsequently painted	acceptable
10. Rear door - left	Subsequently painted	acceptable
11. Front door - left	Subsequently painted	acceptable
12. Front fender - left	Subsequently painted	acceptable
13. A-pillar Front - Left	Subsequently painted	acceptable
14. roof	Subsequently painted	acceptable
15. Rim rear - left	Scratch(es)	Paint
16. tire front - right	Damaged	Replace
17. tire front - left	Not safe for road traffic	Replace
18. tire rear - left	Not safe for road traffic	Replace
19. tire rear - right	Not safe for road traffic	Replace
20. tailgate	Execution defect	Paint
21.	Wear and tear	acceptable
22. Sidewall - Rear - Left	Execution defect	Refurbish and paint
23. Taillight left	Scratch(es)	Replace
24. C-pillar back - left	Execution defect	Refurbish and paint
25. Rear door - left	Execution defect	Refurbish and paint
26. Türeinstieg Hinten - Links	Execution defect	Paint
27. Roof frame - left	Execution defect	Refurbish and paint
28. Front door - left	Execution defect	Refurbish and paint
29. Türeinstieg Vorne - Links	Execution defect	Paint
30. Front fender - left	Execution defect	Refurbish and paint
31. hood	Execution defect	Refurbish and paint
32. Front fender - right	Execution defect	Refurbish and paint
33. Windshield	Chipping from stones in field of view	Replace
34. side skirt - right	Scratch(es)	Paint
35. Türeinstieg Vorne - Rechts	Execution defect	Paint
36. roof	Execution defect	Refurbish and paint
37. Roof frame - right	Execution defect	Refurbish and paint
38. Dachleiste Rechts	Scrape	Replace

39.	exterior body	Damaged	
40.	Door Rear - right	Execution defect	Refurbish and paint
41.	Sidewall - Rear - right	Execution defect	Refurbish and paint
42.	exterior body	Wear and tear	acceptable
43.	maintenance	Due	Replace
44.	proof of maintenance	Missing	Replace
45.		Missing	Replace
46.		Scratch(es)	Replace
47.	B-säule Mitte - Rechts Folierung	Damaged	Replace
48.		Dirty	
49.	covering	Damaged	Replace
50.		Scratch(es)	Replace
51.		Scratch(es)	Replace
52.	Türeinstieg Hinten - Rechts	Execution defect	Paint
53.	Front door - right	Execution defect	Refurbish and paint
54.		Odour	Ozone treatment

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. hood



2. Front fender - right



3. Front door - right



4. A-pillar Front - right



5. Door Rear - right



6. Roof frame - right



7. Sidewall - Rear - right



7. Sidewall - Rear - right




8. tailgate



9. Sidewall - Rear - Left



9. Sidewall - Rear - Left



10. Rear door - left



11. Front door - left



12. Front fender - left



13. A-pillar Front - Left



14. roof



15. Rim rear - left



16. tire front - right



16. tire front - right



17. tire front - left




18. tire rear - left



19. tire rear - right



20. tailgate



20. tailgate



20. tailgate



21.



21.




21.



21.



22. Sidewall - Rear - Left



22. Sidewall - Rear - Left




22. Sidewall - Rear - Left



23. Taillight left




23. Taillight left




24. C-pillar back - left




24. C-pillar back - left



25. Rear door - left



25. Rear door - left



25. Rear door - left



26. Türeinstieg Hinten - Links



26. Türeinstieg Hinten - Links



27. Roof frame - left




27. Roof frame - left




27. Roof frame - left



28. Front door - left



28. Front door - left



28. Front door - left




29. Türeinstieg Vorne - Links



29. Türeinstieg Vorne - Links




30. Front fender - left



30. Front fender - left



30. Front fender - left



30. Front fender - left



31. hood




31. hood




31. hood



31. hood



31. hood



31. hood



32. Front fender - right




32. Front fender - right



32. Front fender - right




33. Windshield



33. Windshield



33. Windshield




33. Windshield



34. side skirt - right



34. side skirt - right



35. Türeinstieg Vorne - Rechts



35. Türeinstieg Vorne - Rechts




36. roof



36. roof



36. roof



36. roof



36. roof



36. roof



36. roof



37. Roof frame - right



37. Roof frame - right



37. Roof frame - right



37. Roof frame - right



38. Dachleiste Rechts



38. Dachleiste Rechts



39. exterior body



40. Door Rear - right



40. Door Rear - right



40. Door Rear - right




41. Sidewall - Rear - right



41. Sidewall - Rear - right



41. Sidewall - Rear - right



42. exterior body



42. exterior body



42. exterior body



46.



46.



47. B-säule Mitte - Rechts Folierung




47. B-säule Mitte - Rechts Folierung



48.



49. covering



49. covering



50.



50.



51.



51.




52. Türeinstieg Hinten - Rechts




52. Türeinstieg Hinten - Rechts




52. Türeinstieg Hinten - Rechts




53. Front door - right



53. Front door - right



53. Front door - right



53. Front door - right



53. Front door - right