



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Cadillac Escalade

Vehicle identification number	1GYFK63868R257108	mileage read:	199113 km
..			
First Registration / construction year:	05.09.2008 /	Visit Date / place of birth:	20.08.2025 Hoppegarten
Bodywork:	SUV	Re - import:	unknown
Body type:	Road /	KBA no. :	1006//AAP
Fuel / emission class:	gasoline / -	transmission type:	automatic
Displacement / power:	6162 ccm / 301 kW (409 PS)	Engine:	four-wheel
paint:	black	Number of previous owners:	3
Doors / seats:	5 / 6	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	no
Submitted vehicle	Eg II (veh - letter)	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
CD / DVD	2	maintained:	- / -
		no / -	
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Anderer	305/40/R22/-W 6 mm
1st axis - right / states .	Anderer	305/40/R22/-W 6 mm
2nd axis - Left / states .	Anderer	305/40/R22/-W 6 mm
2nd axis - right / states .	Anderer	305/40/R22/-W 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

special Features

standard equipment

- | | |
|--------------------------------|-----------------------------------|
| • ABS | • four-wheel |
| • Power side mirrors . | • Power side mirrors . anklappbar |
| • CD - changer | • Power windows |
| • Driver and passenger airbags | • air Conditioning |
| • Fog Lights | • radio |
| • power steering | • central locking |

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Bremsanlage stark verrostet

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces
---	--

**Layers of paint thickness
measurement:**

accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

-
-

reference:

Overview conducted technology audit					
Alternator / Generator:			not possible	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
					examined limited
coupling:			unavailable	exhaust System:	
					not possible
engine running:			not possible	shock absorber:	
					not possible
transmission:			not possible		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) could not be verified .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system could not be checked during the inspection .
engine running:	A field test of the engine could not be performed
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could not be checked for visiting time .
reference:	*Fzg. startet nicht, Wegfahrsperre aktiv; Oberflächenkratzer/Kratzer rundum

damage



component	Damage	Rep kind
1. Front door - left	Subsequently painted	acceptable
2. Front fender - left	Subsequently painted	acceptable
3. Door Rear - right	Subsequently painted	acceptable
4. Sidewall - Rear - right	Subsequently painted	acceptable
5. maintenance	Missing	Replace
6. proof of maintenance	Missing	Replace
7.	Missing	Replace
8. battery	Not okay	Replace
9. elektr. Heckklappe	No functionality	Carry out a fault diagnosis
10. Unterboden	Rust	acceptable
11. Sidewall - Rear - right	Execution defect	Paint
12. Front door - right	Wear and tear	acceptable
13. Door Rear - right	Wear and tear	acceptable
14. hood	Wear and tear	acceptable
15. Front bumper	Execution defect	Paint
16. Felgen	Wear and tear	acceptable
17. brake system	Not okay	Replace
18. Front fender - left	Execution defect	Paint
19. Front door - left	Wear and tear	acceptable
20. Rear door - left	Wear and tear	acceptable
21.	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Front door - left



2. Front fender - left



3. Door Rear - right



4. Sidewall - Rear - right



7.



9. elektr. Heckklappe



10. Unterboden



11. Sidewall - Rear - right



12. Front door - right



13. Door Rear - right



14. hood



15. Front bumper



16. Felgen



17. brake system



18. Front fender - left



19. Front door - left




20. Rear door - left



21.



21.



21.



21.