



Tesla 3: G929TJ

Vinnumber:	5YJ3E7EAXLF588830	Versionname:	Model 3 50kWh Standard Range Plus automaat
First Registrationdate:	7/01/2020	Fiscalpower:	
Expertise Mileage:	92561	Power Kw:	211
Bodytype:		Body colour:	Solid Black
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	383
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Panoramic roof
Windows electric F		Central consol F
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Degree of wear

235/40/19/96 W				
Summer tyres:	Fr.L.	Hankook: 5,2 mm	Fr.R.	Hankook: 5,2 mm
	Re.L.	Hankook: 3,7 mm	Re.R.	Hankook: 3,2 mm
Tyre profile depth FL				5.2
Tyre profile depth FR				5.2
Tyre profile depth RL				3.7
Tyre profile depth RR				3.2
Tyre size FL				235/40 R 19 096 W
Tyre size FR				235/40 R 19 096 W
Tyre size RL				235/40 R 19 096 W
Tyre size RR				235/40 R 19 096 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Polish



Windscreen, Stone chip(s), Windscreen repair



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Stone chip(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Bad repair, Repair and paint (complete)



Rear light L, Waterinfiltration, Replace



Rear light L tailgate, Waterinfiltration, Replace



Shutter / cover R, Broken, Replace

