



Hüsges Gruppe®
Die Gutachter

status report

customer:	Bank 11, Neuss
contract number:	143799230
reference:	

vehicle data			
Ford Ranger Wildtrak Doppelkabine 4x4			
Vehicle identification number	6FPXJM2PLD18117	mileage read:	96499 km
∴			
First Registration / construction year:	15.10.2020 / 2020	Visit Date / place of birth:	23.09.2025 Dorfmark
Bodywork:	cars	Re - import:	unknown
Body type:	Road /	KBA no. :	1566//AAN
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1996 ccm / 157 kW (213 PS)	Engine:	four-wheel
paint:	gray	Number of previous owners:	2
Doors / seats:	4 / 5	number keys:	2 2
Next HU / AU:	02.2026 / 02.2026	cushion type:	leather
Service book available:	yes	Interior Color:	Multicolor
smoking vehicle:	no	Last service km / on the:	64541 / 07.08.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2 2	yes / -	64541 / 07.08.2023
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	polished aluminum
1st axis - Left / states .	Falken	265/60/R18/110H 3 mm
1st axis - right / states .	Falken	265/60/R18/110H 3 mm
2nd axis - Left / states .	Falken	265/60/R18/110H 3 mm
2nd axis - right / states .	Falken	265/60/R18/110H 3 mm
traffic Safety:	not roadworthy	
spare wheel:	vorhanden	
state spare wheel:	Gebraucht	

standard equipment	
• 3rd brake light • Trailer Stabilization Program (TSA) • Drive all-wheel drive • Electric wing mirror . anklappbar • Outside temperature display • Flashing light integrated in exterior mirrors • Floor lamp in the exterior mirrors • Spectacles compartment in roof liner / roof console • Roof rails (aluminum) • Driving Assistance System Brake Assist • Power windows rear • Heated front window • Transmission automatic - Type 10R80 (10-speed) • rear window heatable • Intelligent Protection System (IPS) <i>Airbag Fahrer-/Beifahrerseite, Kopf-Schulter-Airbag vorn und hinten, Seitenairbag vorn, 3-Punkt-Sicherheitsgurt hinten</i> • Body / body platform, double cab • Parental control electrically • Grille in sports design • Bedliner • Steering column (steering wheel) height adjustable • Facelift (2) • Off-Road-Package <i>Unterfahrschutz, Unterfahrschutz hinten, Sperrdifferential</i> • Rad-Paket 20 <i>Reserverad in Fahrbereifung</i> • Tire Pressure Monitoring System • Rear seat package 11 <i>Mittelarmlehne hinten, 2.Sitzreihe mit Sitzbank, Sitzausstattung: 5-Sitzer, Kopfstützen hinten, 3-Punkt-</i>	• Airbag deactivated • Anti -lock braking system (ABS) • Audio Pack 129 <i>Radioempfang digital (DAB), FordPass Connect inkl. eCall, Audio-Navigationssystem Ford SD (mit Ford SYNC), Sprachsteuerung und Bluetooth-Schnittstelle, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, AUX-IN-Anschluss, USB-Anschluss, Farbdisplay (8 Zoll), Rückfahrkamera, Lenkrad (Leder) mit Multifunktion</i> • Electric wing mirror . adjustable and heatable • enhanced battery • Bluetooth interface • board computer • Overhead console with reading lights • Elektron . Stability Program (ESP) <i>Aktives Überrollschutzsystem, Fahrassistenten-System: Bergabfahr-Assistent, Fahrassistenten-System: Berganfahr-Assistent (Hill-Holder)</i> • Vehicle key (2) foldable • Electric windows front • Premium floor mats • pretensioners • Interior mirror with auto dip • Isofix admissions for child seat • KeyFree system • Knee airbag , driver's side • Cargo package 8 <i>Sportbügel hinten (aerodynamisch geformt, schwarz, Ladefläche), Laderaumschienen</i> • Lumbar support front left seat • Center console Premium <i>Getränkehalter vorn</i>

<i>Sicherheitsgurt hinten</i> • Gearshift / selector lever leather • Mudflap rear • Side skirts with running boards • Seat front left electr. adjustable (8-fold) • Sun visor with mirror left (illuminated) • Start / Stop system • • Bumper Sport design • Daytime Running Lights • Prep Package Tachograph • Wildtrack Package <i>Sitz-Paket 3 / 14 / 39 / 48, Seitenairbag vorn, Sitzheizung vorn, Warnanlage für Sicherheitsgurte vorn, Außenspiegel lackiert, Scheinwerfer-Assistent mit Tag-/Nachtsensor, Scheibenwischer mit Regensensor, Parkpilotsystem hinten, Geschwindigkeits-Regelanlage (Tempomat), Intelligenter Geschwindigkeits-Begrenzer, Fahrassistenz-System: Auffahrwarnsystem, Fahrassistenz-System: Verkehrsschildassistent, Fahrassistenz-System: Spurhalteassistent, Teppichboden in Fahrgast-/Laderaum, Klimaautomatik 2-Zonen, Heckklappenbetätigung elektrisch, Türgriffe außen lackiert, Diebstahl-Warnanlage, Rückfahrkamera</i>	• Motor 2,0 Ltr. - 156 kW TDCi Panther KAT • Parking pilot system in front • Wheelbase 3220 mm • Rußpartikelfilter • • Headlight LED <i>Nebelscheinwerfer LED</i> • Mud flaps, front • Electric power steering • Seat relation / upholstery leather • Sun visor with mirror right (lit) • Socket (12V connection) in the boot / load compartment • Rear bumper black (steel) • Body color bumpers • tinted glazing • immobilizer • Central locking with remote control
---	---

special Features	
• Towbar <i>Anhänger-Stabilisierungs-Programm (TSA)</i>	• Metallic paint

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifen VA und HA verschlissen

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Stoßfänger Hinten. Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Marderbiss Motorraum Schaden und Kosten Erweiterung möglich

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2.	Worn	Replace
3.	Worn	Replace
4.	Worn	Replace
5.	Worn	Replace
6. tailgate	Sticker	
7. Rear bumper	Accident damage	Replace
8. Rim rear - left	Damaged	Replace
9. C-pillar back - left		Smart repair
10. Front door - left	Scrape	Smart repair
11. Rim front - left	Damaged	Replace
12. Trittstufe links	Damaged	Replace
13. Front bumper	Damaged	Replace
14. Rim front - right	Damaged	Replace
15. Front door - right	Scrape	Smart repair
16. C-pillar rear - right		Smart repair
17. Sidewall - Rear - right	Scratch(es)	Smart repair
18. Rim rear - right	Damaged	Replace
19. exterior body	Surface scratch(es)	
20.	Wear and tear	acceptable
21.	Dirty (animal hair)	
22.	Odour	Ozone treatment
23.	Damaged	Replace
24. Front door seal - left	Damaged	Replace
25. Front door trim - left	Scratch(es)	Replace
26. Türeinstieg Vorne - Links	Scrape	Smart repair
27. Rear door trim - left	Damaged	Replace
28. Door trim Front - right	Damaged	Replace
29.	Damaged	Replace
30. Door trim Rear - right	Scrape	Replace
31. Türeinstieg Hinten - Rechts		Smart repair
32. Ladefläche	Wear and tear	acceptable
33. Ladefläche	Dirty	
34. motor insulation		Replace
35.		Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,rlnand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



2.



3.



4.



5.



6. tailgate



6. tailgate



7. Rear bumper



7. Rear bumper



7. Rear bumper



7. Rear bumper



8. Rim rear - left



8. Rim rear - left



8. Rim rear - left



9. C-pillar back - left



9. C-pillar back - left



9. C-pillar back - left



10. Front door - left



10. Front door - left



11. Rim front - left



11. Rim front - left



11. Rim front - left



12. Trittstufe links



12. Trittstufe links



13. Front bumper



13. Front bumper



13. Front bumper




13. Front bumper



14. Rim front - right



14. Rim front - right



15. Front door - right



15. Front door - right



16. C-pillar rear - right



16. C-pillar rear - right



16. C-pillar rear - right



17. Sidewall - Rear - right



17. Sidewall - Rear - right



18. Rim rear - right




18. Rim rear - right



19. exterior body



20.



20.



21.



21.



21.



21.



23.



23.



24. Front door seal - left



24. Front door seal - left



25. Front door trim - left



25. Front door trim - left



26. Türeinstieg Vorne - Links




26. Türeinstieg Vorne - Links



27. Rear door trim - left



27. Rear door trim - left



27. Rear door trim - left



28. Door trim Front - right



28. Door trim Front - right



29.



29.



30. Door trim Rear - right



30. Door trim Rear - right



30. Door trim Rear - right



31. Türeinstieg Hinten - Rechts



31. Türeinstieg Hinten - Rechts



32. Ladefläche



33. Ladefläche




34. motor insulation



34. motor insulation



35.



35.