

MITSUBISHI Outlander Outlander 2.0 DI-D 4WD

VIN NO JMBXJCW8W7U022065 Registration Number 8W7U022065



MOT Date

2026-08-01

Last Service

#-

Number of Owners

2

Last Service Mileage

2

Number of Keys

P2

First Registration Date

2007-09-24

Odometer Reading

279822 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924140823
Inspection Date / Place	2025-09-24 / BCA Oberndorf	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive switchable
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	183
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			



























Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Diesel particulate filter
Remote adjusting wing mirrors	Roof rails	Stability control	CD Player
Electrically folding wing mirrors	Radio	Driver Seat Electrically adjustable	Tow ball
Alloys wheels	Cruise control	Front fog lamps	Remote central locking
Split folding rear seats	Sunroof	Central locking	Leather steering wheel

Rear parking sensors


Equipment Details

Tow Ball Type	Detachable	Air Conditioning	Climate Control
Alloy Wheel Size	18	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front	Sunroof Type	Tilt/Slide Glass

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Right Front Tyre Depth	2	Left Front Tyre Depth	2
Right Rear Tyre Depth	2	Left Rear Tyre Depth	2

Cosmetic Damage



13	Fender / Back Right	Bodywork / Dent / Dent
14	Door / Back Right	Bodywork / Dent / Dent
15	Rim / Front Right	Out of Bodywork / Scratch



1. Anomalyon Element -

2. Hood Bodywork / Dent / Dent -



3. Bumper / Front Bodywork / Breakage / Crack -

4. Rim / Front Left
Out of Bodywork / Scratch -



5. Door / Front Left Bodywork / Dent / Dent -

6. Door / Back Left Bodywork / Dent / Dent -




7. Seat / Front Left Interior / Scratched -

8. Steering Wheel / Front Interior / Scratched -



9. Interior / Scratched -

10. Bumper / Back Bodywork / Breakage / Crack -



11. Fender / Back Left Paint / Scratch / Line -

12. Rim / Back Right Out of Bodywork / Scratch -



13. Fender / Back Right Bodywork / Dent / Dent -

14. Door / Back Right Bodywork / Dent / Dent -



15. Rim / Front Right Out of Bodywork / Scratch -

Mechanical Condition

Equipments Test			
Central Locking	⊘	Audio Equipment	⊘
AC / Heating System	•	Main & Spare Keys Functioning	•
Electric Windows	•	Parking Sensors / Cameras Functioning	
Other Equipments	•		
Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	•	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
All - wheel Drive	•	No Dashboard Lights	•
Display Defect	⊘	Service Light	⊘
Engine			
Engine Status / EML		Engine Leak Visible	
Engine Starts	⊘		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** Clutch **Clutch Functioning** General Not Performed **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide