

MAZDA CX-3 CX-3 SKYACTIV-G 120 FWD



VIN NO JMZDK6W7610179193 Registration Number 7610179193

MOT Date

. . .

Number of Keys

Odometer Reading

☆-

2:2

22

₹ 75821 km

Last Service

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

-

= 2016-11-29

=-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250917133205
Inspection Date / Place	2025-09-17 / ARS Altmann AG Riedstadt	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	137
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







































Equipment

Tinted Glass USB Socket Alloys wheels Auxiliary Socket Cruise control Remote adjusting wing mirrors Satellite navigation Stability control				
mirrors Satellite navigation Stability control	Tinted Glass	USB Socket	Alloys wheels	Auxiliary Socket
	Cruise control	, ,	Satellite navigation	Stability control
Central locking Leather steering wheel Rear parking sensors Trip Computer	Central locking	Leather steering wheel	Rear parking sensors	Trip Computer
Airbag Status Anti-lock braking Bluetooth telephone interface Digital Radio	Airbag Status	Anti-lock braking	Bluetooth telephone interface	Digital Radio
Remote central locking Split folding rear seats CD Player Electrically folding wing mirrors	Remote central locking	Split folding rear seats	CD Player	, ,

Radio


Equipment Details

Air Conditioning	Climate Control	Alloy Wheel Size	16	
Seat Heating	Front			


Wheels & Tyres

Right Front Tyre Depth	8	Left Front Tyre Depth	8
Right Rear Tyre Depth	9	Left Rear Tyre Depth	9

Cosmetic Damage



Component	Damage	Comments
1 Bumper / Front	Paint / Scratch / Scuff	
2 Door / Back Left	Bodywork / Dent / Dent	
3 Luggage Space Cover / Back	Interior / Dysfunctional	
4 Roof	Bodywork / Dent / Hail Area	



1. Bumper / Front Paint / Scratch / Scuff -

2. Door / Back Left Bodywork / Dent / Dent -



3. Luggage Space Cover / Back Interior / Dysfunctional -

4. Roof Bodywork / Dent / Hail Area -

Mechanical Condition

Control Lights			
Display Defect	•	Service Light	•
ABS Warning Light	⊘	ESP Fault/Traction Control Malfunction Light	•
Airbag Warning Light	•	Oil Pressure Warning Light	•
Brake Warning Light	•	Power Steering Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Tire Pressure Monitoring System	⊘		
Equipments Test			
Central Locking	⊘	Main & Spare Keys Functioning	(1)
Electric Windows	©	Navigation System	•
Audio Equipment	•		
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	•		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	⊘

Test Drive Inspection

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss** Clutch **Clutch Functioning Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide

description.