



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Suzuki Swift Comfort

Vehicle identification number	JSAAZC23S00300486	mileage read:	59189 km
First Registration / construction year:	12.12.2019 / 2019	Visit Date / place of birth:	16.05.2025 Heidenheim
Bodywork:	cars	Re - import:	no
Body type:	limousine	KBA no. :	7102//AEO
Fuel / emission class:	Petrol / hybrid / € 6	transmission type:	5 speed manual transmission
Displacement / power:	998 ccm / 82 kW (111 PS)	Engine:	front-wheel drive
paint:	black	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	-	state outside:	3 - Average
visit condition:	in the parking garage	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Bridgestone	185/55/R16/83V 6.5 mm
1st axis - right / states .	Bridgestone	185/55/R16/83V 6.5 mm
2nd axis - Left / states .	Bridgestone	185/55/R16/83V 5 mm
2nd axis - right / states .	Bridgestone	185/55/R16/83V 5 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Vollwertig	

standard equipment	
• • Airbag Driver / front passenger and side airbags • Drive Front Wheel Drive • GLX version • Power side mirrors . adjustable • Body color door mirrors • rear Parking Sensors • • • Fahrassistenz-System Totwinkel-Assistent • Electric windows front • Luggage office cover / shade • Belt tensioners • pollen filter • Body 5-door • Rear headrests • Steering wheel (leather) • Lichtassistent (Coming Home, Leaving Home) • Center console with storage compartment <i>Getränkehalter</i> • Multi-function display • Tire repair kit • Rear View Camera • Low emissions Euro 6 emission standards • Side impact protection • Front left seat height adjustment • Sun visors with mirrors • Exterior door handles body color • USB port • Glazing behind darkened • Warning system for safety	• Airbag switched off • Anti- lock braking system (ABS) • Audio system Radio with CD player (MP3 -capable) <i>Radioempfang digital (DAB+), Audiobedienung am Lenkrad, 4 Lautsprecher, Freisprechanlage Bluetooth</i> • Automatic driving light / light sensor • Heated exterior mirrors • brake Assist • Electron. Stability Program (ESP) • Driver assistance system Rear parking assistant • • Driver assistance system traffic sign recognition • Remote unlock the fuel filler flap • Transmission 5-speed • • Isofix admissions for child seat in back seat • air Conditioning • Front head restraints • Steering column (steering wheel) adjustable in height • LM rims • Motor 1,0 Ltr. - 82 kW 12V BoosterJet KAT • Fog Lights • Tire Pressure Monitoring System • Rear seat backrest split / folding • • power steering • Heated front seats • LED daytime running lights • Chrome interior door handles • tinted glazing

- Central locking with remote control

- Curtain airbags , front and rear
- Immobiliser (electronic)

special Features

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			examined limited	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug war zum Zeitpunkt der Begutachtung Verschmutzt/Nass/Vereist/Zugeparkt oder wurde bei unzureichender bzw schlechter Beleuchtung besichtigt.Manche Bereiche waren unter Umständen verdeckt oder zugesagt.Unter Umständen waren nicht alle Fahrzeugsysteme und Ausstattung prüfbar.Versteckte Schäden oder Schadensenerweiterung möglich.

damage



	component	Damage	Rep kind
1.	Wartung	Due	Replace
2.	Amaturen Brett	Sticker	
3.	hood	Scratch(es)	Smart repair
4.	Front bumper	Scratch(es)	Paint
5.	roof		Smart repair
6.	Front door - left	Scratch(es)	Smart repair
7.	Felge vorn links	Scratch(es)	Replace
8.	Sidewall - Rear - Left	Scratch(es)	Paint
9.	Felge Hinten links	Scratch(es)	Replace
10.	Rear bumper	Scratch(es)	Paint
11.	Sidewall - Rear - right	Scratch(es)	Paint
12.	Door Rear - right	Scratch(es)	Paint
13.	Felge Hinten rechts	Scratch(es)	Replace
14.	Front door - right	Scratch(es)	Paint
15.	Felge vorn rechts	Scratch(es)	Replace
16.	Türeinstieg Vorne rechts	Scratch(es)	Smart repair
17.	Türverkleidung Vorne rechts	Scratch(es)	Smart repair
18.	Türeinstieg Hinten links	Scratch(es)	Smart repair
19.	Türverkleidung Hinten links	Scratch(es)	Smart repair
20.	Rear door - left	Scratch(es)	Paint
21.	Fahrersitz	Wear and tear	acceptable
22.	Dachhimmel	Dirty	
23.	Front fender - left	Scratch(es)	Refurbish and paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment




service book



Others



Navigation system



1. Wartung



2. Amaturenbrett



3. hood




3. hood



3. hood



4. Front bumper



4. Front bumper



5. roof



5. roof



6. Front door - left



6. Front door - left



7. Felge vorn links



7. Felge vorn links



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



9. Felge Hinten links



9. Felge Hinten links



10. Rear bumper



10. Rear bumper



10. Rear bumper



11. Sidewall - Rear - right



11. Sidewall - Rear - right



11. Sidewall - Rear - right



12. Door Rear - right



12. Door Rear - right



12. Door Rear - right



13. Felge Hinten rechts



13. Felge Hinten rechts



14. Front door - right



14. Front door - right



14. Front door - right



15. Felge vorn rechts



15. Felge vorn rechts



16. Türeinstieg Vorne rechts




16. Türeinstieg Vorne rechts



17. Türverkleidung Vorne rechts



17. Türverkleidung Vorne rechts



18. Türeinstieg Hinten links



18. Türeinstieg Hinten links



19. Türverkleidung Hinten links



19. Türverkleidung Hinten links



20. Rear door - left



20. Rear door - left



20. Rear door - left



20. Rear door - left



20. Rear door - left



21. Fahrersitz



22. Dachhimmel



23. Front fender - left



23. Front fender - left



23. Front fender - left