



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Suzuki SWIFT

Vehicle identification number	JSAAZCA3S00585216	mileage read:	22065 km
First Registration / construction year:	16.06.2023 / 2022	Visit Date / place of birth:	18.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	7102//AFF
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	1197 ccm / 61 kW (83 PS)	Engine:	front-wheel drive
paint:	gray	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	11670 / 08.08.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	4 - moderate
documents:		condition inside:	4 - moderate
visit condition:	-		
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	11670 / 08.08.2024

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	summer tires	steel
1st axis - Left / states .	Yokohama	175/65/R15/84H 3 mm
1st axis - right / states .	Yokohama	175/65/R15/84H 3 mm
2nd axis - Left / states .	Yokohama	175/65/R15/84H 5 mm
2nd axis - right / states .	Yokohama	175/65/R15/84H 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

special Features

standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • ABS • board computer • Power windows • air Conditioning • radio CD • Hightadjustable • Central locking with remote control | <ul style="list-style-type: none"> • Power side mirrors . • ESP • Driver and passenger airbags • Multimedia modules • power steering • cruise control |
|--|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartung Fällig
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
---	--

**Layers of paint thickness
measurement:**

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine run out of round.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1.	Damaged	Replace
2. maintenance	Due	Replace
3. Motor läuft im Standgas Unrund	Engine running roughly	Carry out a fault diagnosis
4. Front bumper	Scrape	Paint
5. hood	Delle	Smart repair
6. Türeinstieg Vorne - Links	Damaged	Refurbish and paint
7. Rear door - left	Scratch(es)	Paint
8. Front door - left	Scratch(es)	Smart repair
9. Sidewall - Rear - Left	Scratch(es)	
10. Rear bumper	Damaged	Refurbish and paint
11. Sidewall - Rear - right	Deformed	Refurbish and paint
12. Door Rear - right	Deformed	Refurbish and paint
13. Front door - right	Scratch(es)	Paint
14. Mittelkonsole	Dirty	

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book




Others



1.



4. Front bumper



4. Front bumper



4. Front bumper



4. Front bumper



5. hood



6. Türeinstieg Vorne - Links



6. Türeinstieg Vorne - Links



6. Türeinstieg Vorne - Links



7. Rear door - left



7. Rear door - left



8. Front door - left



8. Front door - left



8. Front door - left



9. Sidewall - Rear - Left




9. Sidewall - Rear - Left



10. Rear bumper



10. Rear bumper



11. Sidewall - Rear - right



11. Sidewall - Rear - right



12. Door Rear - right



12. Door Rear - right



13. Front door - right



13. Front door - right



14. Mittelkonsole