



Hüsges Gruppe®
Die Gutachter

status report

customer: Santander Consumer Bank AG

reference:

vehicle data

Hyundai Ioniq Style Hybrid

Vehicle identification number	KMHC851CGNU287621	mileage read:	244419 km
..			
First Registration / construction year:	30.05.2022 / 2022	Visit Date / place of birth:	02.09.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	8252//AHM
Fuel / emission class:	Petrol / hybrid / € 6	transmission type:	automatic
Displacement / power:	1580 ccm / 77 kW (105 PS)	Engine:	front-wheel drive
paint:	Polar White / SOL	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	83318 / 24.07.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	Eg II (veh - letter)	state outside:	5 - neglected
documents:			
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	83318 / 24.07.2023
		yes / 6	
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Goodyear	225/45/R17/94W 5 mm
1st axis - right / states .	Anderer	225/45/ZR17/94W 4 mm
2nd axis - Left / states .	Fulda	225/45/R17/94V 7 mm
2nd axis - right / states .	Goodyear	225/45/R17/94W 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • 3rd brake light • Airbag • Airbag driver • Ambient lighting • Audio / radio remote control on steering wheel • Power side mirrors . anklappbar • painted mirrors • Indicator integrated into mirrors • brake Assist • Off switch for driving light / light sensor • Electron. Stability Control (ESC) with Brake Assist • <i>Fahrassistenz-System: Autonome Notbremsfunktion inkl. Fußgängererkennung (FCA-Ped.), Fahrassistenz-System: Autonome Notbremsfunktion inkl. Fahrradfahrererkennung (FCA-Cyc.)</i> • Driving Assistance System Driving profile selection (Drive Mode) • Driver assistance system Safety system with automatic emergency call (ERA GLONASS / eCall) • Fahrassistenz-Stauassistent System • Electric window . with trap • Window moldings chromed • handsfree Bluetooth • Cargo net in the trunk / cargo area • Cruise control system (cruise control) with distance control ACC • Belt tensioners • heated rear window • Hybrid 104 kW (Motor 1,6 Ltr. - 77 kW) • Rearview mirror with auto dip | <ul style="list-style-type: none"> • Storage pocket on front seat backrests • Airbag switched off • alarm system • Anti- lock braking system (ABS) • Audio Navigation System
<i>Touchscreen-Farbdisplay (10,25 Zoll)</i> • Power side mirrors . adjustable and heated, both • Exterior mirrors with perimeter light • board computer
<i>Smartphone Schnittstelle (Apple CarPlay & Android Auto), Fahrer-Informationen-System (Display 7,0 Zoll)</i> • rear Parking Sensors • Electr . Brakeforce Distribution • Driver Assistance System Attention Assistant • Hill Start Assist • Driving Assistance System High-beam assistant • Driving Assistance System Lane Departure Warning • Driving Assistance System traffic sign assistant • Electric windows front + rear • Remote unlocking tank and / or tailgate • Counter- steering assist (Vehicle Stability Management , VSM) • Luggage compartment cover / shade • Transmission 6-speed - dual-clutch transmission • LED Taillights • Rear spoiler with integrated brake light • Induction charging cup for smartphone • Isofix admissions for child seat • 2-zone automatic climate control
<i>Innenraumfilter: Pollenfilter</i> |
|--|---|

• Body 5-door • Head airbag system • Lumbar support front left seat , electric. adjustable • heated steering wheel • reading Light • Headlamp leveling automatically • LM rims • Rear center armrest with cupholders • model refinement • Radio reception digital (DAB +) • Tire Pressure Monitoring System • Rear seat backrest split / folding • Gearshift / selector lever leather • Windscreen wipers with rain sensor • Headlight part LED (dipped beam) • Side impact protection • Service-System Remote Services (Blue Link) • Seat belts front height adjustable • Front right seat height adjustment • Heated front seats • Sun visors with mirrors (illuminated) • Start-stop button • Body color bumpers • LED daytime running lights • Chrome interior door handles • tinted glazing • Immobiliser (electronic)	• Rear headrests adjustable • Steering wheel (leather) • Steering wheel with paddles • Headlamp leveling • Light - from - automatic • Rear air nozzles • Front center armrest with compartment • Electric parking brake (EPB) • Tire repair kit • Rear View Camera • Low in emissions according to the Euro 6d emissions standard • Window fogging detection / control • LED headlights • Front Side Airbags • Darkened side windows from the B-pillar • Power steering electronically controlled • Front left seat height adjustment • Seat cover / upholstery fabric • Smart Key • Sound System Infinity (8 speakers) <i>Hochtöner</i> • Start / Stop system • Style-Package • Exterior door handles body color (with chrome strip) • USB + AUX - IN connection • • Central locking with remote control
--	--

special Features

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	no no

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **no detectable**

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

-
-

reference:

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. tailgate	Wear and tear	acceptable
3. Rear bumper	Scratch(es)	Paint
4.	Scratch(es)	Smart repair
5. side skirt - right	Scratch(es)	Paint
6. Sidewall - Rear - right	Deformed (slightly)	Refurbish and paint
7. Door Rear - right	Deformed	Refurbish and paint
8. Front door - right	Deformed (slightly)	Refurbish and paint
9. Windshield	Wear and tear	acceptable
10.	Scratch(es)	Smart repair
11. Front fender - right	Damaged	Refurbish and paint
12.	Dirty	
13. Türeinstieg Hinten - Rechts	Damaged	Refurbish and paint
14. Türeinstieg Vorne - Rechts	Wear and tear	acceptable
15. Front bumper	Breakage	Replace
16. spoiler	Wear and tear	acceptable
17.	Wear and tear	acceptable
18.	Wear and tear	acceptable
19. roof	Wear and tear	acceptable
20.	Scratch(es)	Paint
21. Sidewall - Rear - Left	Wear and tear	acceptable
22. Rear door - left	Deformed	Refurbish and paint
23. Türeinstieg Hinten - Links	Damaged	Refurbish and paint
24. Türeinstieg Vorne - Links	Wear and tear	acceptable
25.	Burn hole	Smart repair
26. Front door trim - left	Wear and tear	acceptable
27. Reifendrucküberwachung	Error message	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. maintenance



2. tailgate



3. Rear bumper



3. Rear bumper



4.



5. side skirt - right



6. Sidewall - Rear - right



7. Door Rear - right



8. Front door - right



9. Windshield



10.



11. Front fender - right




11. Front fender - right



12.



12.



12.



13. Türeinstieg Hinten - Rechts



14. Türeinstieg Vorne - Rechts



15. Front bumper



16. spoiler




17.



18.




19. roof




19. roof



20.



21. Sidewall - Rear - Left



21. Sidewall - Rear - Left



22. Rear door - left



23. Türeinstieg Hinten - Links



24. Türeinstieg Vorne - Links



25.



26. Front door trim - left



27. Reifendrucküberwachung