



Hüsge Gruppe®
Die Gutachter

status report

customer:	Santander Consumer Leasing GmbH
reference:	

vehicle data			
Hyundai Santa Fe			
Vehicle identification number	KMHS381CBLU286843	mileage read:	15242 km
..			
First Registration / construction year:	29.05.2020 / 0	Visit Date / place of birth:	19.05.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	station wagon	KBA no. :	8252//AIJ
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2199 ccm / 147 kW (200 PS)	Engine:	front-wheel drive
paint:	gray	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	leather
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	11553 / 29.09.2022
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I lu0026 II For example,	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / yes	11553 / 29.09.2022
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		



available



not available

Hüsge GmbH
Ein Unternehmen der Hüsge Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsge
Dipl.- Ing. (FH) Bernd Hüsge

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Continental	235/55/R19/101V 6 mm
1st axis - right / states .	Continental	235/55/R19/101V 6 mm
2nd axis - Left / states .	Continental	235/55/R19/101V 7 mm
2nd axis - right / states .	Continental	235/55/R19/101V 7 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Vollwertig	

standard equipment

special Features

standard equipment

- | | |
|--------------------------------|------------------------|
| • ABS | • Power side mirrors . |
| • board computer | • Power windows |
| • air Conditioning | • Climate Control |
| • Multifunction steering wheel | • Fog Lights |
| • PDC / H | • PDC / V |
| • PDC / V + H | • power steering |
| • cruise control | • central locking |

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage
---	--

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			Out of order		
oil loss:			in order		
air conditioning:			examined limited	lighting system:	
			in order		
coupling:			unavailable	exhaust System:	
			in order		
engine running:			in order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Vehicle was bridged with a jumper.
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested and apparently acoustically during the tour .
engine running:	A field test of the engine was performed.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. hood		Smart repair
2. Sitz hinten rechts	Scrape	Smart repair
3. Felge hinten rechts	Scratch(es)	Refurbish and paint
4. Einstieg Fahrerseite vorne		Refurbish and paint
5. RDK aktiv	Error message	Carry out a fault diagnosis
6. maintenance	Missing	Replace
7. key	Missing	Replace
8. battery	Not okay	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book




Others




Navigation system



1. hood




1. hood



2. Sitz hinten rechts



2. Sitz hinten rechts



2. Sitz hinten rechts



3. Felge hinten rechts



3. Felge hinten rechts



4. Einstieg Fahrerseite vorne



5. RDK aktiv