


Vehicle details

VIN	KNACC81CG L5381865	Brand	KIA	Maintenance date	01/01/1900
Licence Plate	H4-43-VX	Model	Niro 1.6 GDi Hybrid ActieAuto 5d DynamicLine APL	Maintenance mileage	-
Registration date	13/06/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	58 659 km	Engine size	1580	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	03/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 205/60/16 Summer 7.0 mm		Michelin 205/60/16 Summer 7.0 mm	
Michelin 205/60/16 Summer 5.0 mm		Michelin 205/60/16 Summer 5.0 mm	

Exterior

1		Part: Bumper Position: Front Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	2		Part: Wing Position: Back right Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair
3		Part: Lower bumper Position: Front Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	4		Part: Wing Position: Front right Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair
5		Part: Bumper Position: Back Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	6		Part: Door Position: Front right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair
7		Part: Door Position: Back right Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	8		Part: Roof Position: - Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair
9		Part: Bonnet Position: - Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	10		Part: Step plate Position: Front left Damages: Dent & Chips Severity: - Repair mode: For info
11		Part: Spoiler Position: Front Damages: Misaligned Severity: - Repair mode: Adjust			

Comments

Opslagpark : Dekra Ayvens