


Vehicle details

VIN	KNAD6817A M6508298	Brand	KIA	Maintenance date	-
Licence Plate	K4-26-LT	Model	Stonic 1.0 T-GDi MHEV 74 kW DynamicLine	Maintenance mileage	-
Registration date	21/01/2021	Year	2021	Exterior Color	White Solid
Odometer	92 501 km	Engine size	998	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	30/03/2026	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document




User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 185/65/15 Summer 5.5 mm		Michelin 185/65/15 Summer 5.5 mm	
Michelin 185/65/15 Summer 6.0 mm		Michelin 185/65/15 Summer 5.5 mm	

Exterior

1		Part	Step plate	2		Part	Alloy wheel 15"
		Position	Back right			Position	Front right
		Damages	Dent & Chips			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Lumpsum repair

<p>3</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Bumper grille</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Misaligned</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Adjust</td></tr> </tbody> </table>	Part	Bumper grille	Position	Front left	Damages	Misaligned	Severity	-	Repair mode	Adjust	<p>4</p>  <p>● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </tbody> </table>	Part	Roof	Position	-	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Bumper grille																						
Position	Front left																						
Damages	Misaligned																						
Severity	-																						
Repair mode	Adjust																						
Part	Roof																						
Position	-																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
<p>5</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </tbody> </table>	Part	Windscreen	Position	-	Damages	Stone impact	Severity	-	Repair mode	For info												
Part	Windscreen																						
Position	-																						
Damages	Stone impact																						
Severity	-																						
Repair mode	For info																						