


Vehicle details

VIN	KNAD6817A N6638296	Brand	KIA	Maintenance date	-
Licence Plate	P9-88-TL	Model	Stonic 1.0 T-GDi MHEV 74 kW DynamicLine 5d	Maintenance mileage	-
Registration date	15/06/2022	Year	2022	Exterior Color	Blue Metallic
Odometer	52 042 km	Engine size	998	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	07/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Goodyear 185/65/15 Winter 5.5 mm  Goodyear 185/65/15 Winter 5.5 mm 

Goodyear 185/65/15 Winter 6.5 mm  Goodyear 185/65/15 Winter 6.5 mm

Exterior

<p>1</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Roof</td> </tr> <tr> <td>Position</td> <td>-</td> </tr> <tr> <td>Damages</td> <td>Chemical deposit</td> </tr> <tr> <td>Severity</td> <td>-</td> </tr> <tr> <td>Repair mode</td> <td>Lumpsum repair</td> </tr> </tbody> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p>2</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Door</td> </tr> <tr> <td>Position</td> <td>Back right</td> </tr> <tr> <td>Damages</td> <td>Dented</td> </tr> <tr> <td>Severity</td> <td>Diameter (mm) > 20</td> </tr> <tr> <td>Repair mode</td> <td>Smart Repair</td> </tr> </tbody> </table>	Part	Door	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Roof																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Door																						
Position	Back right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
<p>3</p>  <p>● ● ● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Bonnet</td> </tr> <tr> <td>Position</td> <td>-</td> </tr> <tr> <td>Damages</td> <td>Stone impact</td> </tr> <tr> <td>Severity</td> <td>-</td> </tr> <tr> <td>Repair mode</td> <td>For info</td> </tr> </tbody> </table>	Part	Bonnet	Position	-	Damages	Stone impact	Severity	-	Repair mode	For info	<p>4</p>  <p>● ● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Bumper</td> </tr> <tr> <td>Position</td> <td>Front</td> </tr> <tr> <td>Damages</td> <td>Chemical deposit</td> </tr> <tr> <td>Severity</td> <td>-</td> </tr> <tr> <td>Repair mode</td> <td>Lumpsum repair</td> </tr> </tbody> </table>	Part	Bumper	Position	Front	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Bonnet																						
Position	-																						
Damages	Stone impact																						
Severity	-																						
Repair mode	For info																						
Part	Bumper																						
Position	Front																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						