

BYD

ATTO 3 COMFORT

VIN: LGXCE4CBXP2063966

Estimated repair cost

806.87 EUR
TOTAL

Description

Registration number

-

Registration date

04/08/2023

Odometer

16332 km

Year

2022

Color

-

Transmission

-

Additional costs

Total additional costs: 107.25 EUR

Name	Net cost additional cost
Paint preparation costs	107.25 EUR
Total additional costs: 107.25 EUR	

Warning lights

Active warning lights

Maintenance level 1

Statement details

Inspection loc

CAT Zülpich

Statement date

14/01/2025

Inspection approval date

22/02/2025

Control

Engine start issue

No

Is not roadworthy

No

Dirty vehicle (exterior)

No

Dirty vehicle (interior)

No

Hail dent vehicle

No

Substantial repair carried out

No

Probable structure damage

No


Probable geometry issue

No

Probable underbody damage

No

Defects & corrections

Element	Position	Defect	Correction	net cost
Service Service type : Maintenance level 1	-	Missing	Carry out	- EUR
	Bodywork time -	Paint time -	Part Price -	Lumpsum - EUR
	Bodywork cost -	Paint cost -	MaterialCost -	
Door Material : Metal / Windowed	Front Left	Dent	Smart repair	52.5 EUR
	Bodywork time 0.7 h	Paint time -	Part Price -	Lumpsum -
	Bodywork cost 52.5 EUR	Paint cost - EUR	MaterialCost -	
Door Material : Metal / Windowed	Back Left	Dent	Repair	360 EUR
	Bodywork time 1 h	Paint time -	Part Price -	Lumpsum -
	Bodywork cost 75 EUR	Paint cost 285 EUR	MaterialCost -	
Wing extension moulding Painted	Back Left	Scratched	Replace	69.62 EUR
	Bodywork time 0.2 h	Paint time -	Part Price 54.62 EUR	Lumpsum -
	Bodywork cost 15 EUR	Paint cost - EUR	MaterialCost -	
Wing Material : Metal / Windowed	Back Left	Dent	Smart repair	37.5 EUR
	Bodywork time 0.5 h	Paint time -	Part Price -	Lumpsum -
	Bodywork cost 37.5 EUR	Paint cost - EUR	MaterialCost -	
Tailgate / Boot door Material : Metal / Windowed	-	Dent	Smart repair	60 EUR

Element	Position	Defect	Correction	net cost
	Bodywork time 0.8 h	Paint time -	Part Price -	Lumpsum -
	Bodywork cost 60 EUR	Paint cost - EUR	MaterialCost -	
Wing Material : Metal / Windowed	Back Right	Dent	Smart repair	45 EUR
	Bodywork time 0.6 h	Paint time -	Part Price -	Lumpsum -
	Bodywork cost 45 EUR	Paint cost - EUR	MaterialCost -	
Door Material : Metal / Windowed	Back Right	Dent	Smart repair	37.5 EUR
	Bodywork time 0.5 h	Paint time -	Part Price -	Lumpsum -
	Bodywork cost 37.5 EUR	Paint cost - EUR	MaterialCost -	
Door Material : Metal / Windowed	Front Right	Dent	Smart repair	37.5 EUR
	Bodywork time 0.5 h	Paint time -	Part Price -	Lumpsum -
	Bodywork cost 37.5 EUR	Paint cost - EUR	MaterialCost -	
Fabric door lining Trim material : Leather/Leatherette	Front Right	Scratched	Acceptable	- EUR
	Bodywork time -	Paint time -	Part Price -	Lumpsum - EUR
	Bodywork cost -	Paint cost -	MaterialCost -	
Seat plastic trim	Front Right	Scratched	Acceptable	- EUR
	Bodywork time -	Paint time -	Part Price -	Lumpsum - EUR
	Bodywork cost -	Paint cost -	MaterialCost -	

Element	Position	Defect	Correction	net cost
Fabric door lining Trim material : Leather/Leatherette	Back Right	Scratched	Acceptable	- EUR
				Lumpsum - EUR
Bodywork time -		Paint time -	Part Price -	
Bodywork cost -		Paint cost -	MaterialCost -	

Predamages

Total repair amount -

Reparation carried out

Loose Items

- ☐ Spare wheel tyre
- ☐ Spare Key
- ☒ First aid kit
- ☐ Floor mat
- ☐ Card key
- ☒ Compressor tyre repair kit
- ☒ Slow charging cable
- ☒ Quick charging cable
- ☒ Triangle


Main set of tyres

Front Left	PIRELLI	235 / 50 / 18 / Winter	4 mm
Front Right	PIRELLI	235 / 50 / 18 / Winter	4 mm
Back Left	PIRELLI	235 / 50 / 18 / Winter	7 mm
Back Right	PIRELLI	235 / 50 / 18 / Winter	6 mm

Comments

Wartungsintervallanzeige ausgeschaltet

Pictures





Spare Tyre



cable



cable



Vin



Other



Other




Other



Other




Other




Service -



Door Front Left



Door Front Left



Door Front Left




Door Front Left



Door Back Left



Door Back Left



Door Back Left



Door Back Left



Door Back Left



Wing extension moulding Back Left



Wing extension moulding Back Left



Wing Back Left




Wing Back Left



Tailgate / Boot door -




Tailgate / Boot door -



Tailgate / Boot door -



Wing Back Right



Wing Back Right



Door Back Right



Door Back Right



Door Front Right



Door Front Right