


DEKRA Automotive Solutions

Vehicle details

VIN	LYVUZBMVD LB562412	Brand	VOLVO	Maintenance date	25/03/2025
Licence Plate	FAP56D	Model	T8 390 4WD R-Design Aut.	Maintenance mileage	120 692 km
Registration date	30/04/2020	Year	-	Exterior Color	Other
Odometer	126 708 km	Engine size	-	interior Color	Unknown
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	-	CO2	55
Doors	5	Gears	-		

Inspection Details

Inspection date	22/10/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Sliding roof	✓
Panoramic roof	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Load cover	✗
Refill emergency kit	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Charging kit	✓
Type 2 charging cables	✓

DEKRA Automotive Solutions

Tyres

Hankook 235/55/19 T Summer 7.0 mm		Hankook 235/55/19 T Summer 7.0 mm	
Hankook 235/55/19 T Summer 7.0 mm		Hankook 235/55/19 T Summer 7.0 mm	

Winter kit

Michelin 235/60/18 T Winter 9.0 mm		Michelin 235/60/18 T Winter 9.0 mm	
Michelin 235/60/18 T Winter 9.0 mm		Michelin 235/60/18 T Winter 9.0 mm	

Damages

1



Part	Service
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum

2



Part	Load cover
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Wing
Position	Front left
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

5



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

6



Part	Steering wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Fabric seat
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info

8



Part	Fabric door lining
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Lumpsum repair

9



Part	Door sill
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

10



Part	Bonnet grille
Position	Front
Damages	Pierced
Severity	-
Repair mode	Replace

DEKRA Automotive Solutions

11



Part	Windscreen
Position	-
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement