

Expertise

Protocol number: 41419817 Order No. / Reference: 25197895 Inspection date: 9 Sept 2025

Manufacturer: Volvo

Model: XC60 T6 AWD Recharge Geartronic RDesign

VIN: LYVUZH1VDNB043621





| Vehicle details | | | |
|---|---|--|--|
| Manufacturer / Type / Model / Equipment | | | |
| Volvo XC60 T6 AWD Recharge Geartro | Volvo XC60 T6 AWD Recharge Geartronic RDesign | | |
| Vehicle Identification number LYVUZH1VDNB043621 | | | |
| Mileage (Read) | 69,781 km | | |
| First registration | 30 May 2022 | | |
| Number of holders | 1 | | |
| Power / Engine displacement | 186 kw / 1,969 ccm | | |
| Fuel type / Cylinder | Hybr.B/E ext. edition / 4 | | |
| Gearbox / Number of gears | Automatic / 8 | | |
| Type of drive | All-wheel drive | | |
| Type of vehicle | SUV | | |
| Colour / colour code | Ice White | | |
| Doors / Seats | 5/5 | | |
| Upholstery type | Part leather | | |
| Colour of upholstery | Anthracite | | |



| Letter No. GJ549549 Previous damage / Accident Detectable Repainting Detectable Inspection conditions sufficient Lifting equipment / pit yes Test drive Not performed Engine function test Performed Manufacturer key number / type code number Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight Empty weight Empty weight | Vehicle details | | | |
|--|-----------------------------|------------------------------|-------------------------|---|
| Key is / should be 2 / 2 FZG documents ZB#2 (B) was available (copy), ZB#1 (S) was not | Maintenance booklet / proof | digital proof / complete | Next maintenance in | 29,813 km |
| Was not available Letter No. GJ549549 Previous damage / Accident Detectable Repainting Detectable Inspection conditions sufficient Lifting equipment / pit yes Test drive Not performed Engine function test Performed Manufacturer key number/ type code number Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight Section 1 | Last maintenance on / at | 06/2023 at 19,079 km | | |
| Previous damage / Accident Detectable Repainting Detectable Inspection conditions sufficient Lifting equipment / pit yes Test drive Not performed Engine function test Performed Manufacturer key number/ type code number Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight 2,660 kg Empty weight | Key is / should be | 2/2 | FZG documents | ZB#2 (B) was available (copy), ZB#1 (S) |
| Previous damage / Accident Detectable Repainting Detectable Inspection conditions sufficient Lifting equipment / pit yes Test drive Not performed Engine function test Performed Manufacturer key number/ type code number Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight 2,660 kg Empty weight | | | | was not available |
| Inspection conditions sufficient Lifting equipment / pit yes Test drive Not performed Engine function test Performed Manufacturer key number/ type code number Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight 2,660 kg Empty weight | | | Letter No. | GJ549549 |
| Test drive Not performed Engine function test Performed Manufacturer key number/ type code number Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight 2,660 kg Empty weight | Previous damage / Accident | Detectable | Repainting | Detectable |
| Manufacturer key number/ type code number Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight 2,660 kg Empty weight | Inspection conditions | sufficient | Lifting equipment / pit | yes |
| type code number Emission standard | Test drive | Not performed | Engine function test | Performed |
| Emission standard EURO6;WLTP;AP;PI/CI; M, N1 I Fine dust sticker Permitted total weight 2,660 kg Empty weight | Manufacturer key number/ | 9101 / BRS 00014 | | |
| Permitted total weight 2,660 kg Empty weight | type code number | | | |
| | Emission standard | EURO6;WLTP;AP;PI/CI; M, N1 I | Fine dust sticker | |
| Tyres | Permitted total weight | 2,660 kg | Empty weight | |
| | Tyres | | | |

| Mo | unted | tyres |
|----|-------|-------|
| | | |

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R19 105V | Summer tyres on Light alloy | Continental | 3mm / 3mm |
| 2) | 235/55 R19 105V | Summer tyres on Light alloy | Continental | 4mm / 3mm |

Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/60 R18 107H | Winter tyres on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 235/60 R18 107H | Winter tyres on Light alloy | Pirelli | 5mm / 5mm |

Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|-----|-----------|--------------|--------------|-------------|
| | | | | |

Tirefit Expiration date 03/2026

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- · 12 volt connection in the luggage compartment
- · ABS Anti-lock braking system
- Driver and passenger side airbags with two-stage deployment system
- Airbag, side airbags for driver and front passenger and curtain/ shoulder airbags (IC) for all occupants
- · Android infotainment system
- · Exterior mirrors electrically adjustable and heated
- · Hill Descent Control HDC
- Condensation sensor for automatic activation of the defroster function
- · Brake light, third
- · Anthracite headliner
- · Roof rails in high-gloss black (integrated)
- · Drive Mode
- · Rear parking aid with automatic braking intervention (rear)
- · Electronic Stability Control (ESC) Electronic Stability Control
- · Window frame in high-gloss black
- · Luggage compartment partition net
- · Google Services with navigation function
- · Rear window, heated
- · Interior lighting
- · ISOFIX mount for the outer rear seats
- · Child safety lock (rear doors)
- · Headrests (5) front and rear
- · Rear headrests foldable
- · Loading box under the load compartment floor
- · Stainless steel loading sill protection in the luggage compartment
- · Steering wheel adjustable for height and length
- · Steering wheel: Multifunction buttons on the steering wheel
- Make-up mirrors for driver and passenger, illuminated
- Front center armrest with integrated storage compartment and cup holders
- · Parking brake (electric)
- Radio: High Performance Sound audio system
- · Radio accessories: subwoofer
- · Rain sensor
- · Tire pressure monitoring system
- Wheels: 19" 5-spoke Sport Design diamond cut/high-gloss black alloy wheels (7.5 x 19 with 235/50 R19 tires)
- · Safety Assistance
- Whiplash Protection System (WHIPS)
- Safety braking system with disc brakes all around (internally ventilated)
- · Seats: Driver and passenger seats height adjustable (electrically)
- Seats: Lumbar support (4-way electrically adjustable) for driver and front passenger seat

- · 12 volt connection at the front
- Acoustic Vehicle Alerting System (AVAS)
- · Airbag, passenger side can be switched off
- · Airbag, knee airbag for driver
- · All-wheel drive (AWD)
- · Ambient lighting
- · Electrically foldable exterior mirrors
- · Outside temperature display
- · Hill Start Assist (HSA)
- · Indicators (LED) integrated in exterior mirrors
- · On-board computer
- · CleanZone air quality system with activated carbon filter
- · roof edge spoiler
- · Digital Instrumentation 2nd Gen.
- · Inlay aluminum inlay metal mesh
- · Aluminum door sills with Recharge lettering, front
- · Electronic differential lock
- · Electric windows front and rear
- Automatic brake
- · Transmission: 8-speed Geartronic automatic transmission
- Automatic tailgate
- · Interior and exterior mirrors automatically dimming
- · Intelligent driver information system
- · Keyless Drive
- Automatic climate control with separate temperature control for driver and front passenger
- Paint finish: Uni
- Charging cable SchuKo/Type 2 (Mode 2)
- · Load compartment blind
- LED headlights "Thor's Hammer" with high beam assistant and integrated LED daytime running lights
- Steering wheel: sports steering wheel
- · Rear center armrest (folding)
- · Package: Winter Package
- Panoramic glass sunroof with lifting function (electric)
- Upholstery: Partial leather/mesh textile sports seats
- · Radio accessories: Digital radio reception (DAB+)
- Radio accessories: Two USB-C interfaces on the back of the tunnel console
- Run-off Road Protection
- Wheels: Tire sealant (Incl. 12-volt compressor, top speed 80 km/h)
- Rear seats in 40/60 ratio or completely foldable with through-loading function
- Power steering, speed-dependent
- · Seat belts
- · Seats: Leg rest adjustable (electrically) for driver and passenger seat
- · Seats: Driver's seat electrically adjustable



- Sport front grille with horizontal struts and surround in high-gloss hlack
- · Phone: Inductive smartphone charging system
- · First aid kit and warning triangle
- · Lashing eyes in the luggage compartment (foldable)
- Preparation for Trailer Stability Control (TSA)
- Central locking with two radio remote controls and integrated emergency keys
- · Sport exterior mirrors in high-gloss black
- · Sport front and rear apron
- · Sports pedals
- · Start/Stop technology
- · Textile floor mats: Sport textile floor mats front and rear
- Glazing: Color glazing
- Volvo On Call
- Immobiliser

Extra equipment

- Driver Assistance (Adaptive Cruise Control Emergency Stop Assist
 (automatic emergency stop system if warnings are ignored due to the
 driver failing to steer, brake, or accelerate, including activation of the
 hazard warning lights and automatic braking to a standstill and
 emergency call via Volvo On Call) Pilot Assist (lane guidance
 assistant up to speeds of 130 km/h))
- Glazing: Side and rear windows tinted (from B-pillar)

- · Windscreen, heater
- Charging cable Type 2 / Type 2 (Mode 3) (7 m long, 1-phase, 16 A (for connection to a charging station with a Type 2 connector))
- Package: Parking assistance package (front and rear parking sensors - rear view camera)
- Parking camera with 360° Surround View in conjunction with parking assistance or Connect Edition package

Brief expert findings

| Documents submitted | At the time of the inspection, the re | egistration certificate Part 2 (letter |) was available, but the registration certificate |
|---------------------|---------------------------------------|--|---|
|---------------------|---------------------------------------|--|---|

Part 1 (certificate) was not. (Copy)

VIN comparison The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted

documents was verified during the inspection by the undersigned.

Inspection The inspection conditions were sufficient for the assessment of the vehicle.

Lifting equipment and a pit were available for examining the vehicle.

Test drive No test drive/maneuvering was carried out during the inspection of the vehicle.

Engine function test An engine test run was performed.

Value reducing factors

| NO. | Component group | Description |
|-----|------------------------|--|
| 1 | Door - front left side | Door - Scratch(es) - Smart repair |
| 2 | Wheel / tyres | Alloy rim - front left side - Scratched - Replace |
| 3 | Wheel / tyres | Alloy rim - front right side - Scratched - Replace |

Wear and tear

| No. | Component group | Description |
|-----|-----------------|---|
| 1 | Body | Body - Scratch(es) - No deduction |
| 2 | Vehicle glazing | Windscreen - Stone chips - No deduction |
| 3 | Front bumper | Front bumper - Stone chips - No deduction |
| 4 | 2nd wheel set | 1 alloy rim - Scratched - No deduction |
| 5 | Rear bumper | Rear bumper - Scratch(es) - No deduction |

The vehicle shows signs of wear commensurate with its age and use.

Previous damages

No. Previous damage

Extent of damage (Net)

1 Side right, Provided by user / customer, from 13 Jan 2025

2.040,62€



Repainting

No. Repainting

1 Door - rear right side, Professionally carried out

Paint coat thickness measurement

Door - rear right side

183 µm

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- · Description of core relevant information about the vehicle
- Documentation of equipment features (Delivery by third-party service providers)
- · Documentation of damage, defects, missing parts
- · Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
 (Functional tests of driver assistance systems are not included in the scope of services!)
- · a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.





Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres





Figure 13: Documents



Figure 15: Documents



Figure 17: Additional tyres



Figure 14: Documents



Figure 16: Documents



Figure 18: Navigation





Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Damage 1: Door - front left side: Door - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace







Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - front left side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace






Wear and tear 4: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 4: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 4: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Door - rear right side: 183 μm