

Vehicle details

VIN	MMCXNA05A KH218540	Brand	MITSUBISHI	Maintenance date	-
Licence Plate	H6-75-KL	Model	SPACE STAR 1.0 ClearTec Cool+ 5d	Maintenance mileage	-
Registration date	25/02/2020	Year	2020	Exterior Color	Silver Metallic
Odometer	49 428 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	18/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓

Tyres

Hankook 165/65/14 Summer 4.0 mm		Hankook 165/65/14 Summer 4.0 mm	
Bridgestone 165/65/14 Summer 4.5 mm		Bridgestone 165/65/14 Summer 4.5 mm	

Exterior

1		Part	Roof	2		Part	Bonnet
		Position	-			Position	-
3		Damages	Dent & Chips	4		Damages	Dent & Chips
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Repair
						Part	Wing
		Part	Bumper			Position	Front right
		Position	Front			Damages	Dented
		Damages	Scratched			Severity	Diameter (mm) > 20
		Severity	Length (cm) > 10			Repair mode	Smart Repair
		Repair mode	Repair				

5



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●●●

6



Part	Door
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●●

7



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●

8



Part	Roof post A/B/C
Position	Right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

9



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●

10



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●●●

11



Part	Door
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●●●


12



Part	Roof post A/B/C
Position	Left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

13



Part	Wing
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●