

Vehicle details

VIN	NLHA851AA JZ432784	Brand	HYUNDAI	Maintenance date	-
Licence Plate	SL-60-3T	Model	I10 1.0i Blue ActieAuto 5d Comfort APL	Maintenance mileage	-
Registration date	26/06/2018	Year	2018	Exterior Color	White Solid
Odometer	67 148 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	14/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Continental 155/70/13 Summer 5.0 mm



Continental 155/70/13 Summer 5.0 mm



Hankook 155/70/13 Summer 5.0 mm

Continental 155/70/13 Summer 6.0 mm

Exterior

3



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



Part	Bumper moulding
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

10



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

11



● ●

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

12



● ●

Part	Step plate
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

Interior damage

1





Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2





Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5





Part	Interior tailgate lining
Position	-
Damages	Cut
Severity	Length (cm) > 2
Repair mode	Replace

6





Part	Boot carpet
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7





Part	C-pillar trim
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Smart Repair

8





Part	Fabric door lining
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair