



# HYUNDAI BAYON

## Bayon 1.0 T-GDi 100 Hybrid 48V Creative

VIN NO NLHBR81G0SZ559854

Registration Number HB229NG



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



### Inspection Report Summary

|                         |                          |                |                 |
|-------------------------|--------------------------|----------------|-----------------|
| Customer                | BCAuto Encheres          | Report Number  | P20250520112030 |
| Inspection Date / Place | 2025-05-20 / BCA SOLOGNE | Cosmetic Grade | 3               |


### Vehicle Summary

|                    |                       |                    |                         |
|--------------------|-----------------------|--------------------|-------------------------|
| Vehicle Condition  | Not Movable           | VAT Type           | Qualified - Normal Rate |
| Fuel Type          | Petrol                | Gearbox Type       | Manual                  |
| Colour             | White                 | Engine Size (cc)   | 998                     |
| Engine Size        | 1.0                   | No of Doors        | 5                       |
| Body Type          | Stationwagon / Estate | Drive Train        | Front                   |
| Seat Colour        |                       | No of Seats        | 5                       |
| Seat Covering Name |                       | Seat Covering      | Cloth                   |
| Charging Cables    |                       | WLTP CO2 Emissions | 129                     |

### Vehicle History & Documents

|                        |            |                      |    |
|------------------------|------------|----------------------|----|
| Service Book Available | Missing    | Next Service Mileage | km |
| Previous Usage         | Normal Use | Imported             |    |
| Manufacturer Warrenty  |            |                      |    |





Equipment

|                         |                                   |                      |                   |
|-------------------------|-----------------------------------|----------------------|-------------------|
| Central locking         | Radio                             | Alloys wheels        | Cruise control    |
| Power assisted steering | Electrically folding wing mirrors | Rear parking sensors | Stability control |
| Front parking sensors   | Satellite navigation              |                      |                   |


Equipment Details

|              |                  |                  |     |
|--------------|------------------|------------------|-----|
| Seat Heating | No               | Air Conditioning | Yes |
| Sunroof Type | Tilt/Slide Steel |                  |     |




Cosmetic Damage

2 Dommages



1 Dommages



| Component |                         | Damage                        | Comments |
|-----------|-------------------------|-------------------------------|----------|
| 1         | Bumper / Back           | Bodywork / Dent / Deformation |          |
| 2         | Bumper / Back           | Bodywork / Dent / Deformation |          |
| 3         | Trunk Upholstery / Back | Interior / Dented             |          |



1. Bumper / Back  
Bodywork / Dent / Deformation -



2. Bumper / Back  
Bodywork / Dent / Deformation -



3. Trunk Upholstery / Back  
Interior / Dented -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut ✓

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.