

## TOYOTA Auris Auris 1.33 Dual-VVT-i

VIN NO NMTJT56E30R003224
Registration Number E30R003224



**MOT Date** 

Number of Owners

1

**Odometer Reading** 

╈-

**2** 2

**2**2

208994 km

Last Service

Last Service Mileage

First Registration Date

**Country First Registered** 

**2** -

2009-03-10

Number of Keys

**=**-

### **Inspection Report Summary**

Customer	BCA Online	Report Number	P20250819122929
Inspection Date / Place	2025-08-19 / BCA Berlin	Cosmetic Grade	5

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	White	Engine Size (cc)	1329
Engine Size	1.3	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	125
Gearbox Type	Manual		

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			





































# Equipment

Tinted Glass	Anti-lock braking	Remote central locking	CD Player
Radio	Alloys wheels	Remote adjusting wing mirrors	Stability control
Central locking			


## **Equipment Details**

Air Conditioning	Yes	Alloy Wheel Size	16
Extra Wheel / Tyre Set	Winter Tyres - Steel		


## Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	7	Extra Wheel - 2 Tyre Depth	7
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	5

## Cosmetic Damage




	Component	Damage	Comments
1	Hood	Paint / Chipping	
2	Roof	Bodywork / Dent / Dent	
3	Rocker Panel / Center Left	Paint / Scratch / Scuff	
4	Side Panel / Back Left	Paint / Scratch / Scuff	
5	Rim / Back Left	Out of Bodywork / Scratch	
6	Bumper / Back	Bodywork / Breakage / Crack	
7	Roof	Bodywork / Dent / Dent	
8	Bumper / Back	Bodywork / Breakage / Crack	
9	Side Panel / Back Right	Bodywork / Breakage / Crack	
10	Rim / Back Right	Out of Bodywork / Scratch	
11	Bumper / Front	Paint / Scratch / Scuff	
12	Rim / Front Right	Out of Bodywork / Scratch	



1. Hood Paint / Chipping -

2. Roof Bodywork / Dent / Dent -




3. Rocker Panel / Center Left Paint / Scratch / Scuff -

4. Side Panel / Back Left Paint / Scratch / Scuff -




5. Rim / Back Left Out of Bodywork / Scratch -

6. Bumper / Back Bodywork / Breakage / Crack -




7. Roof Bodywork / Dent / Dent -

8. Bumper / Back Bodywork / Breakage / Crack -



9. Side Panel / Back Right Bodywork / Breakage / Crack -

10. Rim / Back Right Out of Bodywork / Scratch -



11. Bumper / Front Paint / Scratch / Scuff -

12. Rim / Front Right
Out of Bodywork / Scratch -

#### **Mechanical Condition**

Control Lights			
Display Defect	•	ABS Warning Light	•
ESP Fault/Traction Control Malfunction Light	•	Airbag Warning Light	<b>⊘</b>
Oil Pressure Warning Light	•	Brake Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Equipments Test			
Main & Spare Keys Functioning	•	Audio Equipment	<b>⊘</b>
AC / Heating System	•	Other Equipments	•
Engine			
Engine Status / EML	•	Engine Leak Visible	<b>⊘</b>
Engine Starts	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•
Test Drive Inspection			
Engine		The Coore Coretal / Chin /	
Engine Noise	•	The Gears Scratch / Skip / Abnormal Operation	•
Fume Quantity	•	Power Loss	<b>②</b>
Steering Wheel			
Steering   Noise / Anomaly			
Clutch			
Clutch Functioning			
Brake			
Brake System Anomaly	•		
General			
Test Driven Status	•		

	No troubles detected, good condition or correct tests, according to vehicle age and mileage
	Damages or malfunction detected that requires repairs by the buyer
NA	Not applicable
	Not tested
Di	sclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

<u>User Guide</u>