



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Jaguar F-Pace

Vehicle identification number	SADCA2BX2KA394621	mileage read:	99231 km
First Registration / construction year:	15.11.2018 / 2018	Visit Date / place of birth:	12.09.2025 Riedstadt-Goddelau
Bodywork:	SUV	Re - import:	no
Body type:	Road /	KBA no. :	1590//AHB
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1997 ccm / 221 kW (300 PS)	Engine:	four-wheel
paint:	white	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	- / -
		no / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Pirelli	255/55/R19/111V 1 mm
1st axis - right / states .	Pirelli	255/55/R19/111V 1 mm
2nd axis - Left / states .	Pirelli	255/55/R19/111V 2 mm
2nd axis - right / states .	Pirelli	255/55/R19/111V 2 mm
traffic Safety:	not roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Vollwertig	

standard equipment

special Features

standard equipment	
• ABS • audio system • Power side mirrors . anklappbar • ESP • Power windows • air Conditioning • Mult-function Comfort seat front left • Multifunction steering wheel • PDC / V + H • Rear View Camera • power steering • Heated seats • cruise control	• four-wheel • Power side mirrors . • DSTC • Built-in GPS • Driver and passenger airbags • Climate Control • Mult-function Comfort seat front right • Multimedia modules • radio • side airbags • Hightadjustable • TCS • Central locking with remote control

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartungsnachweise Fehlen
reference:	
Note Road Safe:	Beide Reifen Vorne Verschlissen

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **no detectable**

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen. VIN Abfrage nicht möglich, Fahrzeugdaten und Ausstattung können abweichen. Kostenerweiterung möglich.

damage



	component	Damage	Rep kind
1.	Sitz Vorne Links	Damaged	Smart repair
2.	proof of maintenance	Missing	Replace
3.	Cargo cover	Missing	Replace
4.	Partition net loading space	Missing	Replace
5.	4x Reifen	Worn	Replace
6.	Front bumper	Damaged	Replace
7.	Stoßfänger Vorne 2x Grill	Damaged	Replace
8.	Outside mirror - right	Scratch(es)	Paint
9.	roof	Delle	Smart repair
10.	Rear bumper	Scrape	Paint
11.	tailgate trim	Damaged	Smart repair
12.	Sitz Vorne Rechts Gepäcknetz Rückseite	Damaged	Replace
13.	Front door - right	Clearance not exact	Uninstall/install
14.	Tankdeckel Fangband	Damaged	Replace
15.	maintenance	Due	Replace
16.	steering wheel	Damaged	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Sitz Vorne Links



1. Sitz Vorne Links



5. 4x Reifen



5. 4x Reifen



5. 4x Reifen



5. 4x Reifen



6. Front bumper



6. Front bumper



6. Front bumper



6. Front bumper



7. Stoßfänger Vorne 2x Grill



7. Stoßfänger Vorne 2x Grill




7. Stoßfänger Vorne 2x Grill



8. Outside mirror - right



8. Outside mirror - right



9. roof



10. Rear bumper



10. Rear bumper



10. Rear bumper



11. tailgate trim



11. tailgate trim



12. Sitz Vorne Rechts Gepäcknetz Rückseite



13. Front door - right



13. Front door - right



13. Front door - right



13. Front door - right



14. Tankdeckel Fangband



15. maintenance



16. steering wheel