

LAND ROVER RANGE ROVER EVOQUE Range Rover Evoque Mark VI TD4 150 BVA SE Dynamic



VIN NO SALVA2BN0KH341581 Registration Number FF268SD

MOT Date

Last Service

Number of Keys

Odometer Reading

₩-

:::-

P1

2 56447 km

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

2019-04-25

=-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250919115225
Inspection Date / Place	2025-09-19 / BCA MITRY	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	1999
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	164

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







































Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Electric Tailgate
Cruise control	Front parking sensors	Satellite navigation	Electrically adjustable seats
Radio	Alloys wheels	Stability control	Front fog lamps

Power assisted steering


Equipment Details

Seat Heating	Front	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Wheels & Tyres

Left Front Tyre Depth	6	Left Rear Tyre Depth	6
Right Rear Tyre Depth	6	Right Front Tyre Depth	6

Cosmetic Damage



	Component	Damage	Comments
1	Bumper / Back	Paint / Scratch / Line	
2	Rim Brake pads	Out of Bodywork / Scratch	
3	Door / Back Right	Paint / Scratch / Line	
4	Door / Front Right	Bodywork / Dent / Dent	
5	Rim	Out of Bodywork / Scratch	
6	Bumper / Front	Paint / Scratch / Line	
7	Door / Front Left	Paint / Scratch / Line	
8	Door / Back Left	Paint / Scratch / Line	
9	Rim	Out of Bodywork / Scratch	
10	Seat / Front Left	Interior / Scraped	
11	Roof	Paint / Scratch / Line	



TOTAL STATE OF THE PARTY OF THE

1. Bumper / Back Paint / Scratch / Line -

2. Rim Brake pads Out of Bodywork / Scratch -



3. Door / Back Right Paint / Scratch / Line -



4. Door / Front Right Bodywork / Dent / Dent -



5. Rim Out of Bodywork / Scratch -



6. Bumper / Front Paint / Scratch / Line -



7. Door / Front Left Paint / Scratch / Line -

8. Door / Back Left Paint / Scratch / Line -



9. Rim Out of Bodywork / Scratch -

11. Roof Paint / Scratch / Line -

10. Seat / Front Left Interior / Scraped -

Mechanical Condition

Tyres			
Presence Anti-Theft Lock Nut	•		
Dashboard Lights			
ABS Warning Light	•	Diesel Particulate Filter Light	•
ESP Fault/Traction Control Malfunction Light	⊘	4WD Light	•
Dashboard Working	•	Engine Light	•
Oil Pressure Warning Light	⊘	Airbag Warning Light	•
Brake Warning Light	⊘	Level - Fuel / Battery	10
Transmission Warning Light	⊘	Service Light	•
Steering Fluid Level	NA		
Equipments Test			
Electric Windows	•	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	•
Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	•
Central Locking	•	Audio Equipment	•
Navigation System	•	AC / Heating System	•
Parking Sensors / Cameras Functioning	•		
Hybrid/EV			
Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
Hybrid System Fault	NA		
Levels			
Oil - Condition	•	Level - Oil	•
Coolant Fluid - Condition	•	Coolant Fluid	•
Brakes Fluid	•		
Engine			
Cross Member	⊘	Serpentine Belt	•

Control Liquid Leak



Test Drive Inspection

Test Drive			
Engine functioning	•	Engine / Aux Belt / Pulley Noise	•
Vehicle Starts	•	Steering Noise/Gripping	•
Engine Power	•	Smoke Quantity	•
Transmission	•	Clutch Functioning	NA
Steering	•	Brakes Functionning	②
 No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer Not applicable Not tested 			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.