



LAND ROVER Range Rover Sport II 2018 Die.



Range Rover Sport 3.0d i6 mhev HSE Dynamic 249cv a

VIN NO SALWA2BW7MA784559

Registration Number GF027XD

MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



126643 km

Country First Registered



Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002102442
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	2


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified
Fuel Type	Hybrid	Gearbox Type	Sequential
Colour	Grey	Engine Size (cc)	2997
Engine Size	3.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	199

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment


Sunroof	Stability control	Power assisted steering	Parcel Shef
Digital Radio	Electrically folding wing mirrors	Satellite navigation	Front parking sensors
Electrically adjustable seats	Central locking	Cruise control	Front fog lamps
Trip Computer	Remote adjusting wing mirrors	Volante multifuncion	Alloys wheels
Rear parking sensors			

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	MICHELIN MICHELIN-PILOT SPORT 4 SUV	275/45//R21 - 110V / 2 mm
	MICHELIN MICHELIN-PILOT SPORT 4 SUV	275/45//R21 - 110V / 2 mm
	MICHELIN MICHELIN-PILOT SPORT 4 SUV	275/45//R21 - 110V / 2 mm
	MICHELIN MICHELIN-PILOT SPORT 4 SUV	275/45//R21 - 110V / 2 mm

14 Danni



7 Danni

6/12 - Report Number P20251002102442

13	Fender / Front Left	Paint / Scratch / Line
14	Door / Front Left	Paint / Scratch / Line
15	Rim / Back Left	Out of Bodywork / Scratch
16	Bumper / Back	Bodywork / Dent
17	Tailgate	Paint / Chipping
18	Rim / Back Right	Out of Bodywork / Scratch
19	Door / Front Right	Paint / Chipping
20	Panel Filling / Back Right	Interior / Scratched
21	Panel Filling / Front Right	Interior / Scratched



1. Dashboard / Front Interior / Warning Light ON -



2. Panel Filling / Front Left Interior / Scratched -



3. Seat / Front Left Interior / Scratched -




4. Seat / Front Left Interior / Scratched -



5. Panel Filling / Back Left Interior / Scratched -



6. Rim / Front Right Out of Bodywork / Scratch -



7. Fender / Front Right
Bodywork / Poor Previous Repair -



8. Mirror Shell / Front Right
Paint / Scratch / Line -



9. Bumper / Front
Paint / Scratch / Line -




10. Hood
Paint / Chipping -




11. Windshield / Front
Glass Break / Impact -




12. Rim / Front Left
Out of Bodywork / Scratch -



13. Fender / Front Left
Paint / Scratch / Line -



14. Door / Front Left
Paint / Scratch / Line -



15. Rim / Back Left
Out of Bodywork / Scratch -



16. Bumper / Back
Bodywork / Dent -



17. Tailgate
Paint / Chipping -



18. Rim / Back Right
Out of Bodywork / Scratch -



19. Door / Front Right
Paint / Chipping -



20. Panel Filling / Back Right
Interior / Scratched -



21. Panel Filling / Front Right
Interior / Scratched -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Coolant Fluid	!	Brakes Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	SPIA AVARIA GENERICA MOTORE ACCESA
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			