



status report

customer: BCA Autoauktionen GmbH
contract number: 45574661849001
reference:

vehicle data

Land Rover Range Rover Velar R-Dynamic SE

Vehicle identification number	SALYA2BV8JA746205	mileage read:	106033 km
First Registration / construction year:	26.01.2018 / 2018	Visit Date / place of birth:	26.09.2025 Riedstadt-Goddelau
Bodywork:	SUV	Re - import:	unknown
Body type:	Road /	KBA no. :	1590//AGH
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	2995 ccm / 280 kW (381 PS)	Engine:	four-wheel
paint:	Firenze Red	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / Alcantara
Service book available:	no	Interior Color:	beige
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / -	- / -

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Pirelli	255/50/R20/109W 5 mm
1st axis - right / states .	Pirelli	255/50/R20/109W 5 mm
2nd axis - Left / states .	Pirelli	255/50/R20/109W 5 mm
2nd axis - right / states .	Pirelli	255/50/R20/109W 5 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Vollwertig	

standard equipment	
• Airbag Driver / passenger side • Anti- lock braking system (ABS) • Audio system Meridian sound system (color display, 825 watts, 17 speakers, subwoofer) • Power side mirrors . adjustable and heated • Flashing lights with running light • bordmonitor • Headlining special color Ebony • Off switch for headlights • Electr . Brakeforce Distribution • Adaptive Chassis Control (Adaptive Dynamics) • Driving Assistance System hill descent control • Windscreen laminated glass • Tailgate / cover electr. pressed (open + close, sensor-controlled) • rear spoiler • Interior Decor inlays Shadow aluminum • Instrument display TFT color display (12 inches) • Keyless entry • Head airbag system front • Steering wheel with shift paddles / buttons (matt chrome) • LM rims • Motor 3.0 Ltr. - 280 kW V6 24V Kompressor KAT • Otto particle filter (GPF) • Parking brake electrically • Wheelbase 2874 mm • Tire Pressure Monitoring System • Rear View Camera • Windscreen wipers with rain sensor • Seat cover / upholstery leather / velor	• Trailer stabilization program • Drive all-wheel drive • Power side mirrors . anklappbar <i>Außenspiegel mit Umfeldleuchte, Außenspiegel mit Abblendautomatik, Außenspiegel mit Memoryfunktion</i> • Exterior mirrors with warning system blind spot • board computer • Headliner Morzine in Light Oyster • Dynamic stability control (DSC) • Side sill (aluminum) • Fahrassistentz-Paket <i>Fahrassistentz-System: Verkehrszeichenerkennung (Traffic Sign Recognition), Adaptive Geschwindigkeitsregelanlage (ACC), Fahrassistentz-System: Heckaufprall-Vermeidung inkl. Warnsystem Totwinkel, Fahrassistentz-System: Aufmerksamkeits-Assistent</i> • Driving Assistance System torque control (torque vectoring) • Driving Assistance System lane change assistant • Automatic transmission - Drive Select (8 stages) • LED taillights • InControl Pro Services (Internet-based Service) • Rearview mirror with auto dip • Body 5-door • 2-zone automatic climate control • Cornering Brake Control (CBC Corner Brake Control) • Steering column (steering wheel) height adjustable • Matrix LED headlights <i>LED-Lichtsignatur, Scheinwerfer-Reinigungsanlage (SRA)</i> • Navigation System InControl Touch

• Smartphone-Package <i>InControl Apps</i> • Daytime Running Lights • traction control • Universal interface (USB / iPod / AUX port) • Roll Stability Control (RSC)	• Parking package <i>Fahrassistenz-System: Einparkhilfe 360° (virtuelle Überwachung), Fahrassistenz-System: Heckaufprall-Vermeidung inkl. Warnsystem Totwinkel</i> • Pedal steel design • Tire repair kit • Rußpartikelfilter • Low emissions to Euro 6 emission standards • side airbags • Seats front electr. adjustable (10x, with memory) <i>Mittelarmlehne hinten, Rücksitzlehnen neigungsverstellbar, Kopfstützen vorn verstellbar, Getränkehalter hinten</i> • Start / Stop system • Terrain Response System • External door pulls extendable / retractable • Transfer box single-stage (reduction gearbox)
--	--

special Features	
• Ambient lighting adjustable / dimmable • Design Package Black <i>Lufteinlassblende Narvik Black, Luftauslass Motorhaube Narvik Black, Kühlergrill Narvik Black, Seitenschweller Narvik Black, Schriftzug in Narvik Black, Aeroblade in der Frontschürze Narvik Black, Frontschürze mit Dekorleiste Narvik Black, Heckschürze Einfassung Narvik Black, Auspuffblende (Chrom)</i> • Remote unlocking rear seats • Ionizer for air purification • Panoramic sunroof electric • Glazing behind darkened (privacy glass)	• Contrasting roof color • Driver assistance system dynamic mode configurable • Heated front window • Metallic paint • Carpet floor mats

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable Wartungsnachweise fehlen
reference:	

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: Expertly repaired

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Allwetterreifen ohne Alpine Symbol montiert.

damage



component	Damage	Rep kind
1. Front door - left	Subsequently painted	acceptable
2. Rear door - left	Subsequently painted	acceptable
3. Sidewall - Rear - Left	Subsequently painted	acceptable
4. Sidewall - Rear - right	Subsequently painted	acceptable
5. Front door - right	Subsequently painted	acceptable
6. hood	Subsequently painted	acceptable
7. proof of maintenance	Missing	Replace
8. Multimedia Display	Scratch(es)	Replace
9. tailgate	Scratch(es)	Paint
10. Elektrische Heckklappe öffnet sich nicht von selbst	Damaged	Carry out a fault diagnosis
11. Partition net loading space	Missing	Replace
12. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Front door - left



2. Rear door - left



3. Sidewall - Rear - Left



4. Sidewall - Rear - right



5. Front door - right



6. hood



8. Multimedia Display



8. Multimedia Display



8. Multimedia Display



9. tailgate



9. tailgate