



status report

customer:	BCA Autoauktionen GmbH
contract number:	
reference:	

vehicle data			
Land Rover Range Rover Evoque R-Dynamic SE			
Vehicle identification number	SALZA2BX4PH225570	mileage read:	17174 km
..			
First Registration / construction year:	14.11.2023 / 2022	Visit Date / place of birth:	21.03.2025 Riedstadt-Goddelau
Bodywork:	SUV	Re - import:	no
Body type:	Road /	KBA no. :	1590//AIJ
Fuel / emission class:	Petrol / hybrid / € 6	transmission type:	automatic
Displacement / power:	1997 ccm / 147 kW (200 PS)	Engine:	four-wheel
paint:	Ostuni Pearl White	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	1	maintained:	- / -
		no / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Pirelli	235/50/R20/104W 5 mm
1st axis - right / states .	Pirelli	235/50/R20/104W 5 mm
2nd axis - Left / states .	Pirelli	235/50/R20/104W 6 mm
2nd axis - right / states .	Pirelli	235/50/R20/104W 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag Driver / passenger side • Trailer stabilization program • Anti- lock braking system (ABS) • Power side mirrors . adjustable and heated • Exterior mirrors with auto dip • Exterior mirrors with perimeter light • Flashing lights with running light in front • brake Assist • Body color roof • Dynamic stability control (DSC) • Side sill (chrome) • Driving Assistance System All-Terrain Progress Control (ATPC) • Driving Assistance System torque control (torque vectoring) • Driving Assistance System hill descent control • Fahrassistenz-System Efficient Driveline • • Fahrassistenz-System Kollisionswarnsystem • Driving Assistance System Brake Assist • Driving Assistance System Lane Departure Warning (Lane Departure Warning) • Driver assistance system traffic sign recognition with adaptive speed limiter system • Cruise control system (cruise control) • Tailgate / lids Electric . operated (open + close) • InControl Remote Premium (Onlinedienste / Apps) • Infotainment-System Pivi Pro • Rearview mirror with auto dip • Body 5-door • Head airbag system front	• All-weather/all-season tyres • Connection package 1 <i>USB-Anschluss in Mittelkonsole, Steckdose (12V-Anschluß) im Koffer-/Laderaum</i> • Drive all-wheel drive • Outside mirror electr. adjustable, heatable and foldable, with automatic dimming and ambient light • Mirrors with memory function • Exterior mirror with warning system blind spot at door opening • • Front brake discs 349 mm • Morzine headlining in Ebony • Parking aid front and rear • Electr . Brakeforce Distribution • Driving assistance system traction help (low traction launch) • Driver Assistance System Attention Assistant • • Driver assistance system Parking assistance 360 ° (virtual monitoring) • Driver assistance system Rear impact prevention incl. Warning system blind spot • Driver assistance system, rear collision warning system • Fahrassistenz-System Park-Assistent • Driving Assistance System Traffic Sign Recognition • Chassis with coil suspension • Automatic transmission - (9 stages) • InControl Apps • InControl Touch Pro Infotainment System

• Charging cable with Schuko plug • Steering wheel with shift paddles / buttons (matt chrome) • • Pro navigation system • Pedal steel design • Wheel base 2681 mm • Spare wheel as Notrad • Rear View Camera • LED headlights <i>LED-Lichtsignatur</i> • Service-System Amazon Alexa • Seat front left electr. adjustable (14-fold, with memory) <i>Sitz vorn rechts elektr. verstellbar (12-fach)</i> • Smartphone interface (Apple CarPlay & Android Auto) • Terrain Response System 2 • traction control	(Farbdisplay) • Interior inlays in dark aluminum • Instrument display analogue • Rear curtain airbag system • Cornering Brake Control (CBC Corner Brake Control) • Steering wheel with shift paddles / buttons • Steering column (steering wheel) height adjustable • Motor drag torque regulator (MSR / EDC) • Parking brake electrically • Personalisierungssystem (Smart Settings) • Tire Pressure Monitoring System • Rußpartikelfilter • Low-emission according to the Euro 6d exhaust gas standard • SCR (AdBlue technology) • Electric Power Steering • Seat cover / upholstery duo leather (ebony) • Start / Stop system • Configurable terrain response system • Roll Stability Control (RSC)
--	---

special Features	
• Ambient lighting adjustable / dimmable • Infotainment-System Touch Pro Duo (10" Touchscreen) • Alloy rims 8x20 (5-twin-spoke, gloss black, style 5079) • Metallic paint • Carpet floor mats • Winter Package Plus <i>Scheibenwaschdüsen heizbar, Frontscheibe heizbar, Standheizung mit Fernbedienung und Zeitschaltuhr (Timer), Lenkrad heizbar (Leder) mit Multifunktion</i>	• Cup holder in front • Keyless entry • Air vents in the rear • Mobile phone interface with wireless charging function • Glazing behind darkened (privacy glass)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .

Mileage plausible:	not testable
	not testable
	Wartungsnachweise fehlen
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable
	As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances
	At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established
	On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
			unavailable		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Automatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen. Die am Fahrzeug befindliche Bereifung entspricht nicht den Anforderungen für den Winterdienst gemäß der Gesetzesänderung vom 01.10.2024. Laut §36 StVZO dürfen für den Wintereinsatz nur noch Winterreifen oder Allwetterreifen mit Alpinsymbol („Schneeflockensymbol“) verwendet werden. Da diese Kennzeichnung an den montierten Reifen fehlt, ist die Bereifung nach aktueller Gesetzeslage unzulässig.

damage



component	Damage	Rep kind
1. proof of maintenance	Missing	Replace
2. Zweitschlüssel	Missing	Replace
3. Rim rear - right	Scratch(es)	Replace
4. tire rear - right	Wear and tear	acceptable
5. Allwetterreifen ohne Alpine Symbol	Not okay	Replace
6. Front bumper	Scrape	Paint
7. Rear door - left	Scratch(es)	Smart repair
8. Rear bumper	Scrape	Paint
9. tailgate	Scratch(es)	
10. Sidewall - Rear - right	Deformed	Refurbish and paint
11. Door Rear - right	Deformed	Refurbish and paint
12. Elektrische Heckklappe öffnet nicht selbstständig	Damaged	Carry out a fault diagnosis
13. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment




service book



Others




3. Rim rear - right




4. tire rear - right




6. Front bumper



6. Front bumper



6. Front bumper



7. Rear door - left



8. Rear bumper



8. Rear bumper



8. Rear bumper




9. tailgate



9. tailgate




10. Sidewall - Rear - right



10. Sidewall - Rear - right




10. Sidewall - Rear - right




10. Sidewall - Rear - right




10. Sidewall - Rear - right




11. Door Rear - right



11. Door Rear - right



11. Door Rear - right



11. Door Rear - right



11. Door Rear - right