



TOYOTA COROLLA: 1YNJ638				
Vinnumber:	SB1K93BE80E144895	Versionname:	1.8 Hybrid Dynamic Plus e-CVT	
First Registrationdate:	9/10/2020	Fiscalpower:		
Expertise Mileage:	72469	Power Kw:	90	
Bodytype:		Parking lot	2805	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Body colour	Black	
Fueltype:	Hybrid Petrol			
Certificate of Conformity	Yes			
Type of rims (mounted)	Aluminium			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Maintenance	OK			
Options				
Radio multimedia		Luggage cover		
Steering wheel multifunctional		Rear parking sensors		
Type of GPS storage	HD	Front parking sensors		
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar	
Cruise Control				
Type of climate control	Autom climate control			
Number of keys total	2			
Type of headlighting	Headlighting LED			
Type of Lining	Lining fabrics			
Limited Technical Inspection				
Tyres				
Tyre size RL	205/55 R 16 91 V			
Tyre type FL	Summer			
Tyre type RL	Summer			
Tyre profile depth FR	2.0			
Tyre profile depth RR	4.0			
Tyre make FR	255			
Tyre size FR	205/55 R 16 91 V			
Tyre make RR	255			
Tyre size RR	205/55 R 16 91 V			
Summer tyres:	205/55/16/91 V			
	Fr.L.	Bridgestone: 2 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm
Tyre profile depth FL	2.0			
Tyre make FL	255			
Tyre size FL	205/55 R 16 91 V			
Tyre type FR	Summer			
Tyre profile depth RL	4.0			
Tyre type RR	Summer			
Tyre make RL	255			
Assistance equipment				
Number of charging cables (normal)	0	Compressor	Yes	
Number of charging cables (rapid charge)	0			
Repair kit	Yes			
Total cost ex VAT		289,07		
Bumper F, Scratch(es), Acceptable		0,00		




Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Bumper R, Scratch(es), Repair and paint (complete)	289,07
--	--------



Alloy rim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Roof, Scratch(es), Repair and paint (complete)	0,00
--	------

