



NISSAN Qashqai +2 Diesel
qashqai+2 2.0 dci n-tec Dpf

VIN NO SJNJDAJ10U6016673

Registration Number DT071VV



MOT Date

2025-01-23

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2009-02-06

Odometer Reading

220742 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250925162115
Inspection Date / Place	2025-09-25 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour	Black	No of Seats	7
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	174

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Alloys wheels	Sunroof	Parcel Shef
Remote central locking	Tyre Mobility Kit	Power assisted steering	Electrically folding wing mirrors
Volante multifuncion	Remote adjusting wing mirrors	Trip Computer	Stability control

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	KLEBER KLEBER-QUADRAXER 2 SUV	215/60//R17 - 96H / 3 mm
	KLEBER KLEBER-QUADRAXER 2 SUV	215/60//R17 - 96H / 3 mm
	KLEBER KLEBER-QUADRAXER 2 SUV	215/60//R17 - 96H / 3 mm
	KLEBER KLEBER-QUADRAXER 2 SUV	215/60//R17 - 96H / 3 mm

22 Danni



13 Danni



5/13 - Report Number P20250925162115

13	Panel Filling / Back Right	Interior / Scratched
14	Rim / Front Right	Out of Bodywork / Scratch
15	Fender / Front Right	Bodywork / Dent
16	Wing Expander / Front Right	Paint / Scratch / Line
17	Headlight Nozzle / Front Right	Missing Part
18	Bumper / Front	Bodywork / Dent
19	Hood	Paint / Chipping
20	Windshield / Front	Glass Break / Impact
21	Fender / Front Left	Paint / Chipping
22	Mirror Shell / Front Left	Paint / Scratch / Line
23	Door / Front Left	Paint / Scratch / Line
24	Door / Back Left	Bodywork / Dent
25	Door / Back Left	Bodywork / Dent
26	Fender / Back Left	Bodywork / Dent
27	Trunk Tailgate Handle / Back	Bodywork / Breakage
28	Bumper / Back	Bodywork / Dent
29	Roof	Bodywork / Dent / Hail Area
30	Wing Expander / Back Right	Bodywork / Breakage
31	Rim / Back Right	Out of Bodywork / Scratch
32	Fender / Back Right	Bodywork / Dent
33	Door / Back Right	Bodywork / Poor Previous Repair
34	Door / Front Right	Bodywork / Dent
35	Pillar / Front Right	Bodywork / Dent / Hail Area



1. Dashboard / Front Interior / Worn - out -



2. Panel Filling / Front Right Interior / Worn - out -



3. Seat / Front Right Interior / Worn - out -




4. Dashboard / Front Interior / Warning Light ON -




5. Roof Upholstery Interior / Ripped -



6. Center Console Interior / Broken -



7. Seat / Front Left
Interior / Ripped -



8. Steering Wheel / Front
Interior / Worn - out -



9. Floor Carpet
Interior / Worn - out -



10. Interior door handle Front left
Interior / Worn - out -



11. Panel Filling / Front Left
Interior / Worn - out -



12. Tailgate Upholstery / Back
Interior / Scratched -



13. Panel Filling / Back Right
Interior / Scratched -



14. Rim / Front Right
Out of Bodywork / Scratch -




15. Fender / Front Right
Bodywork / Dent -



16. Wing Expander / Front Right
Paint / Scratch / Line -



17. Headlight Nozzle / Front Right
Missing Part -



18. Bumper / Front
Bodywork / Dent -



19. Hood
Paint / Chipping -



20. Windshield / Front
Glass Break / Impact -



21. Fender / Front Left
Paint / Chipping -



22. Mirror Shell / Front Left
Paint / Scratch / Line -



23. Door / Front Left
Paint / Scratch / Line -



24. Door / Back Left
Bodywork / Dent -



25. Door / Back Left
Bodywork / Dent -



26. Fender / Back Left
Bodywork / Dent -



27. Trunk Tailgate Handle / Back
Bodywork / Breakage -



28. Bumper / Back
Bodywork / Dent -



29. Roof
Bodywork / Dent / Hail Area -



30. Wing Expander / Back Right
Bodywork / Breakage -



31. Rim / Back Right
Out of Bodywork / Scratch -



32. Fender / Back Right
Bodywork / Dent -



33. Door / Back Right
Bodywork / Poor Previous Repair -



34. Door / Front Right
Bodywork / Dent -



35. Pillar / Front Right
Bodywork / Dent / Hail Area -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	!	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	!
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	SPIA MOTORE ACCESA.VETRO POST DX NON FUNZIONANTE.
Equipments Test			
Steering Noise / Anomaly	!		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested