



status report

customer: Bank 11, Neuss
contract number: 84559031-INSO
reference:

vehicle data

Hyundai I30

Vehicle identification number	TMAH2811ALJ065677	mileage read:	46195 km
First Registration / construction year:	26.02.2020 / 2019	Visit Date / place of birth:	28.08.2025 Neuss
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	1349//AER
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	998 ccm / 88 kW (120 PS)	Engine:	front-wheel drive
paint:	black	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	-
smoking vehicle:	yes	Last service km / on the:	25251 / 02.02.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	25251 / 02.02.2023
		yes / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	Steel with wheel cover
1st axis - Left / states .	Nexen	195/65/R15/91T 4 mm
1st axis - right / states .	Nexen	195/65/R15/91T 4 mm
2nd axis - Left / states .	Nexen	195/65/R15/91T 5 mm
2nd axis - right / states .	Nexen	195/65/R15/91T 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

special Features

standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • ABS • Power side mirrors . anklappbar • ESP • Driver and passenger airbags • air Conditioning • PDC / H • central locking | <ul style="list-style-type: none"> • Power side mirrors . • board computer • Power windows • Driver • Multifunction steering wheel • TCS • Central locking with remote control |
|---|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage
---	--

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			examined limited	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			not possible
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat Laufleistungen und Altersbedingte Gebrauchsspuren. Kosten und Schadenserweiterung sind möglich.

damage



component	Damage	Rep kind
1. Radkappe - Vorne - Rechts	Scrape	Replace
2. maintenance	Due	Replace
3.	Odour	Ozone treatment
4. Cargo cover	Missing	Replace
5. tailgate	Scratch(es)	Paint
6. rear window	Scratch(es)	Replace
7. Rear bumper	Scratch(es)	Paint
8. Diffusor	Scratch(es)	Replace
9. Sidewall - Rear - Left	Damaged	Refurbish and paint
10. Radkappe - Hinten - Links	Damaged	Replace
11. Rear door - left	Scratch(es)	Paint
12. Türeinstieg Hinten - Links	Damaged	Refurbish and paint
13. Front door - left	Scratch(es)	Paint
14. Front door trim - left	Damaged	Replace
15. Türeinstieg Vorne - Links	Damaged	Refurbish and paint
16. side skirt - left	Scratch(es)	Paint
17. Windshield	Chipping from stones in field of view	Replace
18. Radkappe - Vorne - Links	chipped paint	Replace
19. Front left wheel housing liner	Not okay	Replace
20. exterior body		
21. Front bumper	Damaged	Replace
22. spoiler	Damaged	Replace
23. Outside mirror - right	Scrape	Smart repair
24. Front door - right	Scratch(es)	Paint
25. side skirt - right	Scratch(es)	Paint
26. roof	Deformed	Refurbish and paint
27. Sidewall - Rear - right	Damaged	Refurbish and paint
28.	Scrape	Replace
29. Door Rear - right	Scratch(es)	Paint
30. Door trim Rear - right	Damaged	Replace
31. Türeinstieg Hinten - Rechts	Scratch(es)	Paint
32. headlining	Damaged	Replace
33.	Dirty (animal hair)	
34. Rear door trim - left	Damaged	Replace
35. exterior body	Sticker	
36. Key with remote control	Wear and tear	acceptable
37. Lenkung Lenkrad	Abnormal noises	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others




Navigation system



1. Radkappe - Vorne - Rechts



1. Radkappe - Vorne - Rechts



1. Radkappe - Vorne - Rechts



4. Cargo cover



5. tailgate



5. tailgate



6. rear window



6. rear window



7. Rear bumper



7. Rear bumper



8. Diffusor




8. Diffusor



8. Diffusor



9. Sidewall - Rear - Left



9. Sidewall - Rear - Left



9. Sidewall - Rear - Left



10. Radkappe - Hinten - Links



10. Radkappe - Hinten - Links



10. Radkappe - Hinten - Links



11. Rear door - left




11. Rear door - left



11. Rear door - left



12. Türeinstieg Hinten - Links



12. Türeinstieg Hinten - Links



12. Türeinstieg Hinten - Links



13. Front door - left



13. Front door - left



14. Front door trim - left



14. Front door trim - left



14. Front door trim - left



15. Türeinstieg Vorne - Links




15. Türeinstieg Vorne - Links



16. side skirt - left



16. side skirt - left



17. Windshield



17. Windshield



18. Radkappe - Vorne - Links



18. Radkappe - Vorne - Links



19. Front left wheel housing liner



19. Front left wheel housing liner



20. exterior body



21. Front bumper



21. Front bumper



21. Front bumper



21. Front bumper



21. Front bumper



22. spoiler



22. spoiler



22. spoiler



23. Outside mirror - right



24. Front door - right



24. Front door - right



24. Front door - right




25. side skirt - right




25. side skirt - right



26. roof



26. roof



26. roof



27. Sidewall - Rear - right



27. Sidewall - Rear - right



27. Sidewall - Rear - right



27. Sidewall - Rear - right



27. Sidewall - Rear - right



28.



28.



29. Door Rear - right



29. Door Rear - right



29. Door Rear - right



29. Door Rear - right



29. Door Rear - right



30. Door trim Rear - right




30. Door trim Rear - right



31. Türeinstieg Hinten - Rechts



31. Türeinstieg Hinten - Rechts




32. headlining



33.



33.



33.



33.



34. Rear door trim - left



34. Rear door trim - left



35. exterior body



36. Key with remote control



36. Key with remote control



36. Key with remote control