

Vehicle details

VIN	TMAH3811A LJ060958	Brand	HYUNDAI	Maintenance date	-
Licence Plate	H9-89-JL	Model	i30 Wagon 1.0 T-GDI Comfort 5d	Maintenance mileage	-
Registration date	24/02/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	125 156 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	01/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓


Removable element

Load cover	✓
------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

1		<table border="1"> <tbody> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </tbody> </table>	Part	Door	Position	Front left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	2		<table border="1"> <tbody> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Door																								
Position	Front left																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Bumper																								
Position	Back																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
3		<table border="1"> <tbody> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </tbody> </table>	Part	Door	Position	Front right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	4		<table border="1"> <tbody> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Door																								
Position	Front right																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Bumper																								
Position	Front																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								