



Hüsge Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number:
reference:

vehicle data

Hyundai i30 N Project C

| | | | |
|--|--------------------------------------|------------------------------|------------------------------|
| Vehicle identification number | TMAHC51AALJ022948 | mileage read: | 36575 km |
| First Registration / construction year: | 20.05.2021 / 2020 | Visit Date / place of birth: | 23.09.2025 Heidenheim |
| Bodywork: | cars | Re - import: | unknown |
| Body type: | hatchback | KBA no. : | 1349//AEX |
| Fuel / emission class: | gasoline / € 6 | transmission type: | manual transmission |
| Displacement / power: | 1998 ccm / 202 kW (275 PS) | Engine: | front-wheel drive |
| paint: | Matte Grey / SOL | Number of previous owners: | 1 |
| Doors / seats: | 5 / 5 | number keys: | 2 |
| Next HU / AU: | - / - | cushion type: | Leather / fabric |
| Service book available: | yes | Interior Color: | black |
| smoking vehicle: | no | Last service km / on the: | - / - |
| Vehicle roadworthy: | yes | Vehicle roadworthy: | yes |
| Submitted vehicle documents: | For example, I (Fzg.Schein) | state outside: | 2 - Good |
| visit condition: | - | condition inside: | 2 - Good |
| state general: | 2 - Good | | |

Accessories (presented to the visiting time)

| | | | |
|---|---|--|--|
| GPS sat nav disk: | Fzg.Schlüssel: | Service book provided / | Last service at / on: |
| - | 2 | maintained: | - / - |
| | | yes / - | |
| <input checked="" type="checkbox"/> AHK key | <input checked="" type="checkbox"/> AHK removable | <input checked="" type="checkbox"/> AHK fixed | <input checked="" type="checkbox"/> AHK swivel |
| <input checked="" type="checkbox"/> Fernbed . entertainment | <input checked="" type="checkbox"/> Fernbed . Auxiliary heating | <input checked="" type="checkbox"/> headphone | <input checked="" type="checkbox"/> LED headlights |
| <input checked="" type="checkbox"/> Load compartment cover | <input checked="" type="checkbox"/> navigation system | <input checked="" type="checkbox"/> Persenning | <input checked="" type="checkbox"/> partition net |
| <input checked="" type="checkbox"/> Wind Deflector | <input checked="" type="checkbox"/> Xenon headlights | | |

☒ **available**

☒ **not available**

Hüsge GmbH
Ein Unternehmen der Hüsge Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsge
Dipl.- Ing. (FH) Bernd Hüsge

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



| mounted tires | | |
|-----------------------------|---------------------|-----------------------------|
| Tyre / wheel type: | summer tires | aluminum |
| 1st axis - Left / states . | Anderer | 235/35/ZR19/91W 4 mm |
| 1st axis - right / states . | Anderer | 235/35/ZR19/91W 4 mm |
| 2nd axis - Left / states . | Anderer | 235/35/ZR19/91W 6 mm |
| 2nd axis - right / states . | Anderer | 235/35/ZR19/91W 6 mm |
| traffic Safety: | roadworthy | |
| spare wheel: | - | |
| state spare wheel: | - | |

| standard equipment | |
|---|---|
| <ul style="list-style-type: none"> • 6 speakers • Airbag • Airbag driver • Anti- lock braking system (ABS) • Audio System Radio RDS • Exterior mirror glossy black • board computer • Brake calipers painted orange • roof spoiler • Electr . Brakeforce Distribution • Electron. Stability Control (ESC) with Brake Assist • Driver Assistance System Attention Assistant • Hill Start Assist • Driving Assistance System High-beam assistant • Driver information system (display 4.2 inches) • Electric window . with trap • Electric windows front • Window frame moldings shiny black • Windscreen with band filter above • Frontspoiler Carbon • Counter- steering assist (Vehicle Stability Management , VSM) • Luggage compartment cover / shade • Transmission 6-speed • Half-shell sport seats in leather / Alcantara • LED Taillights • Interior decoration stitching colored • Isofix admissions for child seat • 2-zone automatic climate control • Rear headrests adjustable • Steering wheel (leather) with multifunction | <ul style="list-style-type: none"> • cornering • Airbag switched off • alarm system • Audio Navigation System <i>Touchscreen-Farbdisplay (8,0 Zoll)</i> • Power side mirrors . adjustable and heated, both • Indicator integrated into mirrors • brake Assist • Headliner black • Off switch for driving light / light sensor • Elektron. Differentialsperre (EDS) N Corner Carving Differential • Driver assistance system Active Lane Keeping Assist (LKAS, Lane Keep Assist System) • • Driving Assistance System Driving profile selection (Drive Mode) • Driving Assistance System traffic sign assistant • Lowered chassis • Electric window . behind • Electric windows front and rear, with automatic up / down • handsfree Bluetooth • Windscreen thermally insulating • Function Package <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Umfeldleuchte, Scheibenwischer mit Regensensor, Fahrassistenz-System: Einparkhilfe vorn und hinten, Einparkhilfe hinten, Smart-Key, Start-Stop-Knopf, Induktionsladeschale für Smartphone</i> • Baggage / cargo area lamp |

- | | |
|--|---|
| <ul style="list-style-type: none"> • reading Light • Lifetime MapCare (Internet-based Services) • Rear center armrest with cupholders • 2.0 Ltr motor. - 202 kW TGD I KAT • • Cross bracing in the luggage compartment • Tire repair kit • Rear View Camera • • Gearshift / selector lever leather • Window fogging detection / control • Front Side Airbags • Carbon side skirts • Seat belts orange • Front left seat height adjustment • Smartphone interface (Apple CarPlay & Android Car) • Sun visors with mirrors (illuminated) • Start / Stop system • Body color bumpers • USB + AUX - IN connection • Immobiliser (electronic) | <ul style="list-style-type: none"> • Cruise control system (cruise control) • Cup holders front • Heckdiffusor Carbon • heated rear window • Rearview mirror with auto dip • Body 5-door • Head airbag system • Grille black (matt lacquered) • Steering wheel (Sport / Alcantara) with multifunction and switching function • Headlamp leveling • LM rims • Front center armrest with compartment • Bonnet carbon • aluminum pedals • Radio reception digital (DAB +) • Tire Pressure Monitoring System • Rear seat backrest split / folding • Gear / selector lever handle aluminum • Gear / selector lever handle and handbrake lever handle in Alcantara • LED headlights • Darkened side windows from the B-pillar • power steering • Seat belts front height adjustable • Front right seat height adjustment • Special paint finish in matt gray • sports suspension • Socket (12V) port in the trunk / cargo area • Exterior door handles body color • tinted glazing • Central locking with remote control |
|--|---|

special Features

We remind you that the data provided were taken from the DAT database.\n\nNo liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:

Conducted limited

To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.

Mileage plausible: **not testable**
 not testable

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **no detectable**

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

-
 -

reference:

Overview conducted technology audit

| | | | |
|--------------------------------|--------------------|-------------------------------|--------------------|
| Alternator / Generator: | ✓ in order | Battery / accumulator: | ✓ in order |
| oil loss: | ✓ examined limited | | |
| air conditioning: | ✓ in order | lighting system: | ✓ in order |
| coupling: | ✓ examined limited | exhaust System: | ✓ examined limited |
| engine running: | ✓ in order | shock absorber: | ✓ examined limited |
| transmission: | ✓ examined limited | | |

Performed testing technology

| | |
|--------------------------------|--|
| Alternator / Generator: | The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster . |
| Battery / accumulator: | The battery (accumulator) was examined during the inspection . |
| oil loss: | The vehicle could be checked only limited to oil leaks . |
| air conditioning: | A function of the air conditioning was found to visiting time . |
| lighting system: | The lighting system was to tour date in order. |
| coupling: | The clutch could be tested only limited within the test drive / pull test . |
| exhaust System: | The exhaust system has been tested only restricted during the visit . |
| engine running: | A field test of the engine was performed. |
| shock absorber: | The shock absorber could be tested only restricted during the visit . |
| transmission: | The transmission could be examined in the context of limited test drive / pull test . |
| reference: | *Navigation keine SD-Karte |

damage



| component | Damage | Rep kind |
|-----------------|---------|----------|
| 1. | Missing | Replace |
| 2. Front bumper | Damaged | Replace |
| 3. Service | Due | Replace |

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1.



2. Front bumper



2. Front bumper



2. Front bumper



2. Front bumper



2. Front bumper



2. Front bumper



2. Front bumper



2. Front bumper



2. Front bumper



3. Service