



## status report

<b>Customer:</b>	<b>Allane SE HCBE</b>	<b>Off. Mark :</b>	<b>EN-BO 97E</b>
<b>Report number:</b>	<b>0000000807255-EN968</b>		
<b>reference number:</b>	<b>30835404</b>		

### Vehicle Data

#### Hyundai Kona (OS)(2017->) Select Elektro 2WD

Vehicle identification number .:	<b>TMAK281HFMJ039401</b>	mileage read:	<b>37439 km</b>
First Registration /			<b>27.11.2024 09:14 45549</b>
construction Year:	<b>25.11.2021 / 2021</b>	Inspection date/place:	<b>Sprockhövel</b>
Bodywork:	<b>SUV</b>	Body type:	<b>hatchback</b>
fuel:	<b>Electric</b>	Transmission type:	<b>Automatic</b>
GPS sat nav disk:	<b>-</b>	Displacement / power:	<b>0 ccm / 100 kW (136 PS)</b>
Drive type:	<b>front-wheel drive</b>	Paint:	<b>Polar White / SOL</b>
Type of paint:	<b>Uni ( 2 layer)</b>	Doors / seats:	<b>5 / 5</b>
Number of keys:	<b>2</b>	Next HU / AU:	<b>2026-11 / 2026-11</b>
cushion type:	<b>Substance</b>	Service book available:	<b>Yes</b>
Interior Color:	<b>Gray</b>	Maintained service book:	<b>Yes</b>
smoking vehicle:	<b>No</b>	Last service km / on the:	<b>37424 / 2024-11-26</b>
Vehicle roadworthy:	<b>Yes</b>	Submitted vehicle documents:	<b>Registration Certificate</b>
State outside:	<b>2 - Good</b>	condition inside:	<b>3 - Average</b>

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



### Mounted tires

	Winter tires	Aluminium original
Tyre / wheel type:		
1st axis - Left / states .	<b>Hankook</b>	<b>215/-/R17/-- 5 mm</b>
1st axis - right / states .	<b>Hankook</b>	<b>215/-/R17/-- 5 mm</b>
2nd axis - Left / states .	<b>Hankook</b>	<b>215/-/R17/-- 5 mm</b>
2nd axis - right / states .	<b>Hankook</b>	<b>215/-/R17/-- 5 mm</b>
Traffic Safety:	<b>Roadworthy</b>	

### Unmounted tires

	Summer tires	Aluminium original
Tyre / wheel type:		
1st axis - Left / states .	-	<b>215/-/R17/-- 5 mm</b>
1st axis - right / states .	-	<b>215/-/R17/-- 5 mm</b>
2nd axis - Left / states .	-	<b>215/-/R17/-- 5 mm</b>
2nd axis - right / states .	-	<b>215/-/R17/-- 5 mm</b>
Traffic Safety:	<b>Roadworthy</b>	

### Series

- |  |  |
|--|--|
| <ul style="list-style-type: none"> <li>• 6 Lautsprecher</li> <li>• Airbag passenger side</li> <li>• Airbag driver side</li> <li>• Alarm system</li> <li>• Drive type: front-wheel drive</li> <li>• Outside mirror electr. adjustable and heated, both</li> <li>• Indicator LED integrated in the exterior mirror</li> <li>• Roof rails</li> <li>• Digital Cockpit (Instrumentenanzeige Digital)</li> <li>• Automatic switch-on for driving lights / light sensor</li> <li>• Elektromotor 100 kW (cont. 26 kW)</li> <li>• Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)</li> <li>• Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)</li> <li>• Driver assistance system: Driving profile selection (Drive Mode)</li> <li>• Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)</li> </ul> | <ul style="list-style-type: none"> <li>• Storage bag on front seat backrests</li> <li>• Airbag front passenger side can be switched off</li> <li>• Active brake light (ESS)</li> <li>• Anti-lock braking system (ABS)</li> <li>• Audio system: Radio RDS</li> <li>• Exterior mirror painted</li> <li>• Brake Assist</li> <li>• Roof spoiler</li> <li>• Rear Parking Sensors</li> <li>• Electr. Brake force distribution</li> <li>• Electron. Stability control (ESC) with brake assistant</li> <li>• Fahrassistenz-System: Aufmerksamkeits-Assistent</li> <li>• Driver assistance system: hill start assist</li> <li>• Fahrassistenz-System: Insassenalarm (ROA)</li> <li>• Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)</li> </ul> |
|--|--|

- Driving assistance system: lane departure warning system (LDWS, Lane Departure Warning System)
- Electric window lift at the front
- Handsfree Bluetooth
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Speed limiter system (speed limiter)
- Getriebe für Elektrofahrzeug
- Pretensioners
- Isofix seats for child seat
- Climate
- Headrests adjustable at the back
- Lumbar support seat front left, electr. adjustable
- Lenkrad heizbar
- Steering wheel with paddle shifters
- Steering column (steering wheel) longitudinally adjustable
- Headlamp leveling
- Center armrest front with compartment
- Notladekabel (ICCB)
- Radio reception digital (DAB +)
- Tire repair kit
- Backup camera
- Schalt-/Wählhebel (Shift by Wire)
- Window fogging detection / control
- Select-Paket
- Seatbelts height adjustable
- Seat cover / upholstery: fabric
- Smart key
- Sun visors with mirror (illuminated)
- Start / Stop system
- Touchscreen-Farbdisplay (8,0 Zoll)
- Türgriffe innen silber
- Glazed tinted
- Immobilizer (electronic)
- Wärmeschutzverglasung
- Electric window rear
- Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik
- Windscreen with band filter on top
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Cruise control system (tempomat) with distance control ACC
- Cup holder in front
- Rear window heatable
- Body: 5-door
- Head airbag system
- Kühlergrill Wagenfarbe
- Steering wheel (leather) with multifunction
- Steering wheel with multifunction
- Steering column (steering wheel) height adjustable
- Reading light
- LM rims
- Facelift
- Parking brake electric (EPB)
- Radstand 2600 mm
- Tire pressure monitoring system
- Rear seat back divided / foldable
- Shift / selector lever handle leather
- Side airbag in front
- Power steering
- Seat front left height adjustable
- Heated seats in the front
- Sonderlackierung Dive in Jeju Uni
- Start-stop button
- Daytime running light LED
- Door handles outside body color
- USB port + AUX-IN port
- Seat belt warning system, driver / passenger side
- Wireless SmartLink (Apple CarPlay)
- Central locking with remote control

## Special Features

- Charging device on-board charger (3-phase)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

### General exam

<b>test drive:</b>	<b>Conducted limited</b> Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .
<b>Subfloor Inspection:</b>	<b>Not performed</b> A visit to the underbody of the car was not performed .
<b>Mileage plausible:</b>	<b>Not testable</b> Not testable
<b>reference:</b>	
<b>Note Road Safe:</b>	

### Accident claims investigation

<b>Rep. Predamages / -height gross:</b>	
<b>Layers of paint thickness measurement:</b>	
<b>Existing collision damage:</b>	<b>Not established</b> On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
<b>reference:</b>	

### Overview of technical examination

<b>Air conditioning:</b>	Examined limited	✗	<b>Lighting system:</b>	examined limited	✗
<b>Sunroof / convertible:</b>	unavailable	✗	<b>Seat heating:</b>	In order	✓
<b>Brake system:</b>	examined limited	✗	<b>Engine running:</b>	examined limited	✗

### Implemented technical examination

<b>air conditioning:</b>	The air conditioning system could be tested only restricted during the visit .
<b>lighting system:</b>	The Lichtanlage could be considered limited to the tour date .
<b>Sunroof / convertible:</b>	unavailable
<b>Seat heating:</b>	In order
<b>brake system:</b>	The braking system has been tested by a visual inspection .
<b>engine running:</b>	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
<b>reference:</b>	*

### Damage



### Exterior and Styling

	Component	Damage	Rep kind
1.	Rear Bumper	Light scratch	Replace
2.	Sidewall - Rear - Left	Wear and tear	Without repair



### Inner body

	Component	Damage	Rep kind
3.	Door trim Front - right	Wear and tear	Without repair
4.	dashboard	Wear and tear	Without repair

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable ( small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Hüsge Gruppe®  
Die Gutachter

## Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside






mileage



center console



key



Service book / proof



engine compartment



tires



tires



tires



tires



instrument cluster



rims



1. Rear Bumper  
Light scratch - Replace





2. Sidewall - Rear - Left  
**Wear and tear - Without repair**



3. Door trim Front - right  
**Wear and tear - Without repair**



4. dashboard  
**Wear and tear - Without repair**