





status report

Customer: Allane SE HCBE

Report number: 0000000801404-EN968 Off. Mark: **PI-BS 750E**

reference number: 30816402

Vehicle Data

Hyundai Kona (OS)(2017->) Select Elektro 2WD

Vehicle identification number .: TMAK281HFPJ072917 mileage read: 16488 km

First Registration /

05.11.2024 08:17 25474 construction Year:

Inspection date/place: **Bönningstedt**

Bodywork: SUV Body type: hatchback

Transmission type: fuel: **Electric Automatic**

GPS sat nav disk: Displacement / power: 0 ccm / 100 kW (136 PS)

Drive type: front-wheel drive Paint:

28.10.2022 / 2022

Type of paint: Uni (2 layer) Doors / seats: 5/5

Number of keys: Next HU / AU: 2025-10 / 2025-10 2

cushion type: Service book available: **Substance** Yes Interior Color: Maintained service book: Gray Yes

smoking vehicle: Last service km / on the: 15869 / 2024-10-08 No

Vehicle roadworthy: Submitted vehicle documents: Yes **Registration Certificate**

State outside: condition inside: 2 - Good 2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Dive in Jeju / SOL



0000000801404-EN968 www.huesges-gruppe.de page: 1 from 9 Report number:



Mounted tires		
Tyre / wheel type:	Summer tires	Aluminium original
1st axis - Left / states .	Michelin	215/-/R17/ 6 mm
1st axis - right / states .	Michelin	215/-/R17/ 6 mm
2nd axis - Left / states .	Michelin	215/-/R17/ 6 mm
2nd axis - right / states .	Michelin	215/-/R17/ 6 mm
Traffic Safety:	Roadworthy	

Series

- 6 Lautsprecher
- Airbag passenger side
- Airbag driver side
- Alarm system
- Drive type: front-wheel drive
- Outside mirror electr. adjustable and heated, both
- Indicator LED integrated in the exterior mirror
- Roof rails
- Digital Cockpit (Instrumentenanzeige Digital)
- Automatic switch-on for driving lights / light sensor
- Elektromotor 100 kW (cont. 26 kW)
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Driver assistance system: Driving profile selection (Drive Mode)
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Driving assistance system: lane departure warning system (LDWS, Lane Departure Warning System)
- Electric window lift at the front
- Handsfree Bluetooth
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Speed limiter system (speed limiter)
- Getriebe f
 ür Elektrofahrzeug
- Pretensioners

- Storage bag on front seat backrests
- Airbag front passenger side can be switched off
- Active brake light (ESS)
- Anti-lock braking system (ABS)
- Audio system: Radio RDS
- Exterior mirror painted
- Brake Assist
- Roof spoiler
- Rear Parking Sensors
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driver assistance system: hill start assist
- Fahrassistenz-System: Insassenalarm (ROA)
- Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)
- Electric window rear
- Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik
- Windscreen with band filter on top
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Cruise control system (tempomat) with distance control ACC
- Cup holder in front
- Rear window heatable

Report number: 0000000801404-EN968 www.huesges-gruppe.de page: 2 from 9



•	Isofix	caatc	for	child	caat

- Climate
- Headrests adjustable at the back
- Ladevorrichtung On-Board-Lader (3-Phasen)
- Steering wheel (leather) with multifunction
- Steering wheel with multifunction
- Steering column (steering wheel) height adjustable
- Reading light
- LM rims
- Facelift
- Parking brake electric (EPB)
- Radstand 2600 mm
- Tire pressure monitoring system
- Rear seat back divided / foldable
- Shift / selector lever handle leather
- Side airbag in front
- Power steering
- Seat front left height adjustable
- Heated seats in the front
- Sonderlackierung Dive in Jeju Uni
- Start-stop button
- Daytime running light LED
- Door handles outside body color
- USB port + AUX-IN port
- Seat belt warning system, driver / passenger side
- Wireless SmartLink (Apple CarPlay)
- Central locking with remote control

- Body: 5-door
- Head airbag system
- Kühlergrill Wagenfarbe
- Lumbar support seat front left, electr. adjustable
- Lenkrad heizbar
- Steering wheel with paddle shifters
- Steering column (steering wheel) longitudinally adjustable
- Headlamp leveling
- Center armrest front with compartment
- Notladekabel (ICCB)
- Radio reception digital (DAB +)
- Tire repair kit
- Backup camera
- Schalt-/Wählhebel (Shift by Wire)
- Window fogging detection / control
- Select-Paket
- Seatbelts height adjustable
- Seat cover / upholstery: fabric
- Smart key
- Sun visors with mirror (illuminated)
- Start / Stop system
- Touchscreen-Farbdisplay (8,0 Zoll)
- Türgriffe innen silber
- Glazed tinted
- Immobilizer (electronic)
- Wärmeschutzverglasung

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General exam	
test drive:	Conducted limited
	Because of the conditions a short test drive could be performed only at a moderate speed .
	As part of the test drive further tests were carried out. The results are documented later in
	the report .
Subfloor Inspection:	Not performed
	A visit to the underbody of the car was not performed .

Report number: 000000801404-EN968 www.huesges-gruppe.de page: 3 from 9



Mileage plausible: Not testable

Not testable

reference:

Note Road Safe:

Accident claims investigation

Rep. Predamages / -height gross:

Layers of paint thickness

measurement:

Existing collision damage: Not established

On the vehicle body shell were on visual examination found no existing accident damages

(other than the usual signs of use) .

reference:

Overview of technical examination

Sunroof / convertible: unavailable Seat heating: In order

Brake system: examined limited Engine running: examined limited

Implemented technical examination

air conditioning: The air conditioning system could be tested only restricted during the visit .

lighting system: The Lichtanlange could be considered limited to the tour date.


Sunroof / convertible: unavailable
Seat heating: In order

brake system: The braking system has been tested by a visual inspection .

engine running: Checking the engine running was limited. Here no audible or visual abnormalities were noted.

reference: *

Damage



ComponentDamageRep kind1.Rim front - rightDamagedSmart repair2.Rim front - leftDamagedSmart repair3.Rim rear - leftWear and tearWithout repair

Others

ComponentDamageRep kind. hand toolsMissingReplace

Report number: 000000801404-EN968 www.huesges-gruppe.de page: 4 from 9



A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear, as in normal use are inevitable (small bumps, dents, scratches).

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .

Report number: 000000801404-EN968 www.huesges-gruppe.de page: 5 from 9



Photo documentation



front Left



rear Left



trunk



front Right



rear Right



Inside










key




engine compartment



center console



Service book / proof



tires









tires



rims



tires




instrument cluster



1. Rim front - right **Damaged - Smart repair**





2. Rim front - left **Damaged - Smart repair**



3. Rim rear - left **Wear and tear - Without repair**