



status report

Customer:	Allane SE HCBE	Off. Mark :	RV WW 42E
Report number:	0000000803236-EN968		
reference number:	30831517		

Vehicle Data

Hyundai Kona (OS)(2017->) Select Elektro 2WD

Vehicle identification number .:	TMAK281HFPJ073220	mileage read:	16015 km
First Registration / construction Year:	25.11.2022 / 2022	Inspection date/place:	11.11.2024 88316 Isny im Allgäu
Bodywork:	SUV	Body type:	hatchback
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	Hard Disk Drive	Displacement / power:	0 ccm / 100 kW (136 PS)
Drive type:	front-wheel drive	Paint:	Dive in Jeju / SOL
Type of paint:	Uni (2 layer)	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	2024-11 / 2024-11
cushion type:	Substance	Service book available:	Yes
Interior Color:	Black	Maintained service book:	Yes
smoking vehicle:	No	Last service km / on the:	15990 / 2024-11-07
Vehicle roadworthy:	Yes	Submitted vehicle documents:	Registration Certificate
State outside:	2 - Good	condition inside:	2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Mounted tires

	Winter tires	Aluminium original
Tyre / wheel type:		
1st axis - Left / states .	Semperit	215/55/R17/94V 7 mm
1st axis - right / states .	Semperit	215/55/R17/94V 7 mm
2nd axis - Left / states .	Semperit	215/55/R17/94V 7 mm
2nd axis - right / states .	Semperit	215/55/R17/94V 7 mm
Traffic Safety:	Roadworthy	

Series

- 6 Lautsprecher
- Airbag passenger side
- Airbag driver side
- Alarm system
- Drive type: front-wheel drive
- Outside mirror electr. adjustable and heated, both
- Indicator LED integrated in the exterior mirror
- Roof rails
- Digital Cockpit (Instrumentenanzeige Digital)
- Automatic switch-on for driving lights / light sensor
- Elektromotor 100 kW (cont. 26 kW)
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Driver assistance system: Driving profile selection (Drive Mode)
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Driving assistance system: lane departure warning system (LDWS, Lane Departure Warning System)
- Electric window lift at the front
- Handsfree Bluetooth
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Speed limiter system (speed limiter)
- Getriebe für Elektrofahrzeug
- Pretensioners
- Storage bag on front seat backrests
- Airbag front passenger side can be switched off
- Active brake light (ESS)
- Anti-lock braking system (ABS)
- Audio system: Radio RDS
- Exterior mirror painted
- Brake Assist
- Roof spoiler
- Rear Parking Sensors
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driver assistance system: hill start assist
- Fahrassistenz-System: Insassenalarm (ROA)
- Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)
- Electric window rear
- Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik
- Windscreen with band filter on top
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Cruise control system (tempomat) with distance control ACC
- Cup holder in front
- Rear window heatable

- | | |
|--|---|
| <ul style="list-style-type: none"> • Isofix seats for child seat • Climate • Headrests adjustable at the back • Ladevorrichtung On-Board-Lader (3-Phasen) • Steering wheel (leather) with multifunction • Steering wheel with multifunction • Steering column (steering wheel) height adjustable • Reading light • LM rims • Facelift • Parking brake electric (EPB) • Radstand 2600 mm • Tire pressure monitoring system • Rear seat back divided / foldable • Shift / selector lever handle leather • Side airbag in front • Power steering • Seat front left height adjustable • Heated seats in the front • Sonderlackierung Dive in Jeju Uni • Start-stop button • Daytime running light LED • Door handles outside body color • USB port + AUX-IN port • Seat belt warning system, driver / passenger side • Wireless SmartLink (Apple CarPlay) • Central locking with remote control | <ul style="list-style-type: none"> • Body: 5-door • Head airbag system • Kühlergrill Wagenfarbe • Lumbar support seat front left, electr. adjustable • Lenkrad heizbar • Steering wheel with paddle shifters • Steering column (steering wheel) longitudinally adjustable • Headlamp leveling • Center armrest front with compartment • Notladekabel (ICCB) • Radio reception digital (DAB +) • Tire repair kit • Backup camera • Schalt-/Wählhebel (Shift by Wire) • Window fogging detection / control • Select-Paket • Seatbelts height adjustable • Seat cover / upholstery: fabric • Smart key • Sun visors with mirror (illuminated) • Start / Stop system • Touchscreen-Farbdisplay (8,0 Zoll) • Türgriffe innen silber • Glazed tinted • Immobilizer (electronic) • Wärmeschutzverglasung |
|--|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General exam

test drive:

Conducted limited

Because of the conditions a short test drive could be performed only at a moderate speed .
As part of the test drive further tests were carried out. The results are documented later in the report .

Subfloor Inspection:

Not performed

A visit to the underbody of the car was not performed .

Mileage plausible: **Not testable**

Not testable

reference:

Note Road Safe:

Accident claims investigation

Rep. Predamages / -height gross:

Layers of paint thickness
measurement:

Existing collision damage: **Not established**

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview of technical examination

Air conditioning:	Examined limited	✗	Lighting system:	examined limited	✗
Sunroof / convertible:	in Order	✓	Seat heating:	Examined limited	✗
Brake system:	examined limited	✗	Engine running:	examined limited	✗

Implemented technical examination

air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
Sunroof / convertible:	in Order
Seat heating:	Examined limited
brake system:	The braking system has been tested by a visual inspection .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
reference:	*

Damage

 Others			
	Component	Damage	Rep kind
1.	Sommerreifen 4 Stk.	Missing	Replace

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Hüsches Gruppe®
Die Gutachter

Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside



mileage




center console



key



key



Service book / proof



Others



engine compartment



tires



tires



tires



tires



instrument cluster



Hüsches Gruppe®
Die Gutachter



rims