



status report

Report number:	0000000814397-EN968	Off. Mark :	NOR-DV 67E
reference number:	30849881		

Vehicle Data

Hyundai Kona (OS)(2017->) Style Elektro 2WD

Vehicle identification number .:	TMAK381GFLJ018631	mileage read:	51625 km
First Registration / construction Year:	02.03.2021 / 2020	Inspection date/place:	23.12.2024 11:41 26556 Westerholt
Bodywork:	SUV	Body type:	hatchback
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	Hard Disk Drive	Displacement / power:	0 ccm / 150 kW (204 PS)
Drive type:	front-wheel drive	Paint:	Chalk White / MET
Type of paint:	Metallic	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	2026-03 / 2026-03
cushion type:	Substance	Service book available:	Yes
Interior Color:	Gray	Maintained service book:	Yes
smoking vehicle:	No	Last service km / on the:	40237 / 2024-03-12
Vehicle roadworthy:	Yes	Submitted vehicle documents:	Registration Certificate
State outside:	2 - Good	condition inside:	2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Mounted tires

Tyre / wheel type:	Summer tires	Aluminium original
1st axis - Left / states .	Michelin	215/-R17/-- 5.5 mm
1st axis - right / states .	Michelin	215/-R17/-- 5 mm
1st axis - right / states .	Michelin	215/-R17/-- 6 mm
2nd axis - right / states .	Michelin	215/-R17/-- 6 mm
Traffic Safety:	Roadworthy	

Series

- 3rd brake light
- Cornering
- Airbag front passenger side can be switched off
- Alarm system
- Drive type: front-wheel drive
- Outside mirror electr. adjustable and heated, both
- Flashing light integrated in the exterior mirror
- Roof rails
- Automatic switch-on for driving lights / light sensor
- Electric motor 150 kW (cont. 28 kW)
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Driver assistance system: high beam assistant
- Electric window rear
- Handsfree Bluetooth
- Frontscheibe wärmedämmend
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Getriebe für Elektrofahrzeug
- Taillights LED
- Induction charger for smartphone
- Instrumente mit Farbdisplay 3,5 Zoll
- Body: 5-door
- Head airbag system
- 6 Lautsprecher
- Airbag passenger side
- Airbag driver side
- Anti-lock braking system (ABS)
- Audio system: Radio RDS
- Exterior mirror painted
- Brake Assist
- Rear Parking Sensors
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driver assistance system: hill start assist
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Electric window lift at the front
- Windscreen with band filter on top
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Cruise control system (tempomat) with distance control ACC
- Cup holder in front
- Rear window heatable
- Interior mirror with automatic dimming
- Isofix seats for child seat
- Climate
- Headrests adjustable at the back

- | | |
|--|--|
| <ul style="list-style-type: none"> • Kühlergrill Wagenfarbe • Lumbar support seat front left, electr. adjustable • Lenkrad heizbar • Reading light • LM rims • Parking brake electric (EPB) • Radstand 2600 mm • Tire pressure monitoring system • Rear seat back divided / foldable • Window fogging detection / control • Scheinwerfer Voll-LED • Darkened side windows from the B-pillar • Seat front left height adjustable • Heated seats in the front • Sonderlackierung Galaxy Gray Metallic • Start-stop button • Style-Paket • Door handles outside body color • USB port + AUX-IN port • Immobilizer (electronic) • Central locking with remote control | <ul style="list-style-type: none"> • Charging cable with Type 2 plug • Steering wheel (leather) with multifunction • Steering wheel with paddle shifters • Headlamp leveling • Center armrest front with compartment • Radio reception digital (DAB +) • Tire repair kit • Backup camera • Shift / selector lever handle leather • Rain-sensing wipers • Side airbag in front • Power steering • Seat cover / upholstery: fabric • Smart key • Sun visors with mirror (illuminated) • Start / Stop system • Daytime running light LED • Türgriffe innen verchromt • Glazed tinted • Heat pump for heating/air conditioning |
|--|--|

Special Features

- | | |
|---|--|
| <ul style="list-style-type: none"> • Driving assistance package
Outside mirror electr. anklappbar, Head-Up Display, Driving assistance system: parking assistance front and rear, Rear Parking Sensors, Driving assistance system: rear cross traffic assistant (Cross Traffic), Fahrassistenz-System: Totwinkel-Assistent • GPS package
Sound-System KRELL, 8 speakers, subwoofer, Smartphone Schnittstelle (Apple CarPlay & Android Auto), navigation system, Service system: Remote Services (Blue Link), Touchscreen color display (10.25 inch) | <ul style="list-style-type: none"> • Metallic paint |
|---|--|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General exam

test drive:	Conducted limited Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .
Subfloor Inspection:	Not performed A visit to the underbody of the car was not performed .
Mileage plausible:	Not testable Not testable
reference:	
Note Road Safe:	

Accident claims investigation

Rep. Predamages / -height gross:	
Layers of paint thickness measurement:	
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview of technical examination

Air conditioning:	Examined limited	✗	Lighting system:	examined limited	✗
Sunroof / convertible:	unavailable	✗	Seat heating:	Examined limited	✗
Brake system:	examined limited	✗	Engine running:	examined limited	✗

Implemented technical examination

air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
Sunroof / convertible:	unavailable
Seat heating:	Examined limited
brake system:	The braking system has been tested by a visual inspection .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
reference:	*

Damage



Exterior and Styling

	Component	Damage	Rep kind
1.	Front door - left	Wear and tear	Without repair
2.	Rim front - right	Wear and tear	Without repair
3.	Windshield	Wear and tear	Without repair



Others

	Component	Damage	Rep kind
4.	hand tools	Missing	Replace

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Hüsches Gruppe®
Die Gutachter

Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside



instrument cluster




mileage



center console



key



Service book / proof



engine compartment



rims



tires



tires



tires




tires



1. Front door - left
Wear and tear - Without repair



2. Rim front - right
Wear and tear - Without repair



3. Windshield
Wear and tear - Without repair