



## status report

Customer:	Allane SE HCBE	Off. Mark :	MB-MR 604E
Report number:	0000000806347-EN968		
reference number:	30829568		

### Vehicle Data

#### Hyundai Kona (OS)(2017->) Trend Elektro 2WD

Vehicle identification number .:	<b>TMAK381HFNJ042458</b>	mileage read:	<b>30443 km</b>
First Registration / construction Year:	<b>23.11.2021 / 2021</b>	Inspection date/place:	<b>22.11.2024 14:07 83703 Gmund</b>
Bodywork:	<b>SUV</b>	Body type:	<b>hatchback</b>
fuel:	<b>Electric</b>	Transmission type:	<b>Automatic</b>
GPS sat nav disk:	<b>Hard Disk Drive</b>	Displacement / power:	<b>0 ccm / 100 kW (136 PS)</b>
Drive type:	<b>front-wheel drive</b>	Paint:	<b>Teal Blue / MET</b>
Type of paint:	<b>Metallic</b>	Doors / seats:	<b>5 / 5</b>
Number of keys:	<b>2</b>	Next HU / AU:	<b>2026-11 / 2026-11</b>
cushion type:	<b>Substance</b>	Service book available:	<b>Yes</b>
Interior Color:	<b>Gray</b>	Maintained service book:	<b>-</b>
smoking vehicle:	<b>No</b>	Last service km / on the:	<b>- / -</b>
Vehicle roadworthy:	<b>Yes</b>	Submitted vehicle documents:	<b>Registration Certificate</b>
State outside:	<b>3 - Average</b>	condition inside:	<b>2 - Good</b>

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



## Mounted tires

	Summer tires	Aluminium original
Tyre / wheel type:	<b>Marangoni</b>	<b>215/-R17/-- 5.5 mm</b>
1st axis - Left / states .	<b>Marangoni</b>	<b>215/-R17/-- 5.5 mm</b>
1st axis - right / states .	<b>Marangoni</b>	<b>215/-R17/-- 4 mm</b>
2nd axis - Left / states .	<b>Marangoni</b>	<b>215/-R17/-- 4 mm</b>
2nd axis - right / states .	<b>Marangoni</b>	<b>215/-R17/-- 4 mm</b>
Traffic Safety:	<b>Roadworthy</b>	

## Series

- 3rd brake light
- Storage bag on front seat backrests
- Airbag front passenger side can be switched off
- Active brake light (ESS)
- Ambient lighting
- Drive type: front-wheel drive
- Outside mirror electr. anklappbar
- Exterior mirror painted
- Brake Assist
- Roof spoiler
- Rear Parking Sensors
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Driver assistance system: hill start assist
- Driver assistance system: Driving profile selection (Drive Mode)
- Fahrassistenz-System: Insassenalarm (ROA)
- Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)
- Electric window rear
- Fensterheber elektrisch vorn, mit Auf-/Ab-Automatik
- 6 Lautsprecher
- Airbag passenger side
- Airbag driver side
- Alarm system
- Anti-lock braking system (ABS)
- Audio system: Radio RDS
- Outside mirror electr. adjustable and heated, both
- Indicator LED integrated in the exterior mirror
- Roof rails
- Digital Cockpit (Instrumentenanzeige Digital)
- Automatic switch-on for driving lights / light sensor
- Elektromotor 100 kW (cont. 26 kW)
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including cyclist detection (FCA-Cyc.)
- Driving assistance system: Autonomous emergency braking function including pedestrian detection (FCA-Ped.)
- Driving assistance system: parking assistance front and rear
- Driver assistance system: high beam assistant
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Driving assistance system: lane departure warning system (LDWS, Lane Departure Warning System)
- Electric window lift at the front
- Handsfree Bluetooth

- Windscreen with band filter on top
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Speed limiter system (speed limiter)
- Getriebe für Elektrofahrzeug
- Pretensioners
- Rear window heatable
- Induction charger for smartphone
- Isofix seats for child seat
- Climate
- Headrests adjustable at the back
- Charging cable with Type 2 plug
- Steering wheel (leather) with multifunction
- Steering wheel with multifunction
- Steering column (steering wheel) height adjustable
- Reading light
- LM-Felgen 7x17
- Notladekabel (ICCB)
- Radio reception digital (DAB +)
- Tires 215/55 R17 ..V
- Tire pressure monitoring system
- Rear seat back divided / foldable
- Shift / selector lever handle leather
- Rain-sensing wipers
- Side airbag in front
- Seatbelts height adjustable
- Seat cover / upholstery: fabric
- Smart key
- Sun visors with mirror (illuminated)
- Start / Stop system
- Touchscreen-Farbdisplay (8,0 Zoll)
- Door handles outside body color
- USB port + AUX-IN port
- Verglasung hinten abgedunkelt (Privacy Glass)
- Immobilizer (electronic)
- Heat pump for heating/air conditioning
- Central locking with remote control
- Frontscheibe wärmedämmend
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Cruise control system (tempomat) with distance control ACC
- Cup holder in front
- Taillights LED
- Tweeter
- Interior mirror with automatic dimming
- Body: 5-door
- Head airbag system
- Kühlergrill Wagenfarbe
- Lumbar support seat front left, electr. adjustable
- Lenkrad heizbar
- Steering wheel with paddle shifters
- Steering column (steering wheel) longitudinally adjustable
- Headlamp leveling
- Center armrest front with compartment
- Parking brake electric (EPB)
- Radstand 2600 mm
- Tire repair kit
- Backup camera
- Schalt-/Wählhebel (Shift by Wire)
- Window fogging detection / control
- Scheinwerfer Voll-LED
- Power steering
- Seat front left height adjustable
- Heated seats in the front
- Sonderlackierung Dive in Jeju Uni
- Start-stop button
- Daytime running light LED
- Trend-Paket
- Türgriffe innen silber
- Glazed tinted
- Seat belt warning system, driver / passenger side
- Wireless SmartLink (Apple CarPlay)
- Wärmeschutzverglasung

## Special Features

- Metallic paint
- GPS package  
Sound-System KRELL, subwoofer, 8 speakers, Lifetime MapCare (Internetbasierende Dienste), navigation system, Service system: Remote Services (Blue Link), Touchscreen color display (10.25 inch), Driver assistance system: traffic sign assistant

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

## General exam

test drive:	<b>Conducted limited</b> Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .
Subfloor Inspection:	<b>Not performed</b> A visit to the underbody of the car was not performed .
Mileage plausible:	<b>Not testable</b> Not testable
reference:	
Note Road Safe:	

## Accident claims investigation

Rep. Predamages / -height gross:	
Layers of paint thickness measurement:	
Existing collision damage:	<b>Not established</b> On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

## Overview of technical examination

Air conditioning:	Examined limited	✗	Lighting system:	examined limited	✗
Sunroof / convertible:	unavailable	✗	Seat heating:	Not checked	✗
Brake system:	examined limited	✗	Engine running:	examined limited	✗

## Implemented technical examination

air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
Sunroof / convertible:	unavailable
Seat heating:	Not checked
brake system:	The braking system has been tested by a visual inspection .

**engine running:** Checking the engine running was limited. Here no audible or visual abnormalities were noted .  
**reference:** \*

## Damage



### Exterior and Styling

	Component	Damage	Rep kind
1.	Rear Door - Right	Dented	Gentle refurbishing
2.	Front door - left	Deep scratch	Paint

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable ( small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



## Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside





Huesges Gruppe®  
Die Gutachter



mileage



center console



key



engine compartment



tires



tires



tires



tires



instrument cluster



rims



1. Rear Door - Right  
Dented - Gentle refurbishing



1. Rear Door - Right  
Dented - Gentle refurbishing





1. Rear Door - Right  
**Dented - Gentle refurbishing**



2. Front door - left  
**Deep scratch - Paint**