



HYUNDAI ix20 Diesel
ix20 1.6 crdi Comfort

VIN NO TMAPU81SAEJ152240
Registration Number EV940VT



MOT Date

2025-05-23

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2014-06-30

Odometer Reading

91130 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251009111209
Inspection Date / Place	2025-10-09 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1582
Engine Size	1.6	No of Doors	5
Body Type	MPV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	125

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Volante multifuncion	Remote adjusting wing mirrors
Trip Computer	Stability control	Power assisted steering	Digital Radio
Parcel Shef	Remote central locking	Tyre Mobility Kit	


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons	
	YOKOHAMA	205/55//R16 - 91V / 2 mm
	YOKOHAMA	205/55//R16 - 91V / 2 mm
	YOKOHAMA	205/55//R16 - 91V / 3 mm
	YOKOHAMA	205/55//R16 - 91V / 3 mm

Cosmetic Damage

28 Danni



3 Danni



46


1

Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Steering Wheel / Front	Interior / Worn - out	
3	Bumper / Back	Bodywork / Dent	
4	Door / Back Right	Bodywork / Dent	
5	Door / Back Left	Bodywork / Poor Previous Repair	
6	Ignition Key	Interior / Broken	
7	Door / Front Left	Bodywork / Poor Previous Repair	
8	Door / Front Right	Bodywork / Dent	
9	Fender / Front Right	Bodywork / Poor Previous Repair	
10	Mirror Shell / Front Right	Paint / Scratch / Line	
11	Fender / Back Right	Bodywork / Dent	
12	Roof	Bodywork / Dent	

13	Hood	Bodywork / Poor Previous Repair
14	Fender / Front Left	Bodywork / Poor Previous Repair
15	Rim / Front Right	Out of Bodywork / Scratch
16	Fender / Back Left	Bodywork / Dent
17	Pillar / Front Right	Bodywork / Dent / Hail Area
18	Tailgate	Paint / Scratch / Line
19	Gear Knob	Interior / Worn - out
20	Roof	Paint / Scratch / Line
21	Rocker Panel / Center Right	Bodywork / Dent
22	Rim / Back Left	Out of Bodywork / Scratch
23	Rim / Front Left	Out of Bodywork / Scratch
24	Rim / Back Right	Out of Bodywork / Scratch
25	Bumper / Back	Bodywork / Assembly
26	Bumper / Front	Bodywork / Assembly
27	Bumper / Front	Bodywork / Assembly
28	Rocker Panel / Center Left	Bodywork / Dent
29	Fog Light / Back Right	Glass Break



1. Windshield / Front
Glass Break / Impact -



2. Steering Wheel / Front
Interior / Worn - out -




3. Bumper / Back
Bodywork / Dent -




4. Door / Back Right
Bodywork / Dent -




5. Door / Back Left
Bodywork / Poor Previous Repair -



6. Ignition Key
Interior / Broken -



7. Door / Front Left
Bodywork / Poor Previous Repair -



8. Door / Front Right
Bodywork / Dent -



9. Fender / Front Right
Bodywork / Poor Previous Repair -



10. Mirror Shell / Front Right
Paint / Scratch / Line -




11. Fender / Back Right
Bodywork / Dent -



12. Roof
Bodywork / Dent -



13. Hood
Bodywork / Poor Previous Repair -




14. Fender / Front Left
Bodywork / Poor Previous Repair -



15. Rim / Front Right
Out of Bodywork / Scratch -



16. Fender / Back Left
Bodywork / Dent -



17. Pillar / Front Right
Bodywork / Dent / Hail Area -



18. Tailgate
Paint / Scratch / Line -



19. Gear Knob
Interior / Worn - out -



20. Roof
Paint / Scratch / Line -



21. Rocker Panel / Center Right
Bodywork / Dent -




22. Rim / Back Left
Out of Bodywork / Scratch -



23. Rim / Front Left
Out of Bodywork / Scratch -



24. Rim / Back Right
Out of Bodywork / Scratch -



25. Bumper / Back
Bodywork / Assembly -



26. Bumper / Front
Bodywork / Assembly -



27. Bumper / Front
Bodywork / Assembly -



28. Rocker Panel / Center Left
Bodywork / Dent -



29. Fog Light / Back Right
Glass Break -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	!		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

General			
Test Driven Status	✓		
Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested