



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 1186738830
reference:

vehicle data

Skoda Fabia Cool Edition

Vehicle identification number	TMBAC65J193091310	mileage read:	166265 km
First Registration / construction year:	17.02.2009 / 2008	Visit Date / place of birth:	18.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	8004//AFK
Fuel / emission class:	gasoline / € 4	transmission type:	manual transmission
Displacement / power:	1390 ccm / 63 kW (86 PS)	Engine:	front-wheel drive
paint:	Brilliant-Silber Metallic	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	02.2026 / 02.2026	cushion type:	substance
Service book available:	no	Interior Color:	gray
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	steel
1st axis - Left / states .	Continental	165/70/R14/81T 4 mm
1st axis - right / states .	Continental	165/70/R14/81T 4 mm
2nd axis - Left / states .	Continental	165/70/R14/81T 2 mm
2nd axis - right / states .	Continental	165/70/R14/81T 2 mm
traffic Safety:	roadworthy	
spare wheel:	vorhanden	
state spare wheel:	Vollwertig	

Unmounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Nokian	165/70/R14/81T 4 mm
1st axis - right / states .	Nokian	165/70/R14/81T 4 mm
2nd axis - Left / states .	Nokian	165/70/R14/81T 4 mm
2nd axis - right / states .	Nokian	165/70/R14/81T 4 mm
traffic Safety:	roadworthy	

standard equipment	
• 3-point rear center seat belt • Airbag switched off • Anti- lock braking system (ABS) • brake Assist • Electric windows front • Belt tensioners • Dust and pollen filter • Body 5-door • Head airbag system • Front head restraints • Make TRW Steering Gear • Engine 1.4 ltr. - 63 kW 16V • Smokers Package • Front Side Airbags • power steering • Seat cover / upholstery fabric Stone • immobilizer • Central	• 3rd brake light • Airbag Driver / passenger side <i>Airbag Fahrerseite, Airbag Beifahrerseite</i> • Acceleration skid control (ASR) • Electron. Stability Program (ESP) • Transmission 5-speed • rear window wiper • Isofix admissions for child seat • air Conditioning • Rear headrests (3- fold) • Radiator grille with chrome edge • Steering column (steering wheel) adjustable (vertical / axial) • radio preparation • Spare wheel • Side moldings • Seat belts front height adjustable • Body color bumpers • Tinted heat insulating glass

special Features	
• Metallic paint	• Front left seat height adjustment

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable Wartungsnachweise fehlen
reference:	
Note Road Safe:	Batterie Defekt

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			Out of order		
oil loss:			examined limited		
air conditioning:			Out of order	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning was not okay for visiting time . **No cooling effect.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. dashboard		Replace
2.	Damaged	Replace
3. proof of maintenance	Missing	Replace
4. battery	Defective	Replace
5. air conditioning	No functionality	Carry out a fault diagnosis
6. maintenance	Due	Replace
7. Zweitschlüssel	Missing	Replace
8. motor insulation	Damaged	Replace
9.	Damaged	Replace
10. spoiler	Damaged	Replace
11. Front bumper	Scratch(es)	Paint
12. Outside mirror - left	Damaged	Replace
13. Front door - left	Damaged	Refurbish and paint
14. Rear door - left	Scratch(es)	Paint
15. Sidewall - Rear - Left	Deformed	Refurbish and paint
16. Rear bumper	Damaged	Refurbish and paint
17. Taillight right	Breakage	Replace
18. Sidewall - Rear - right	Delle	Smart repair
19. Door Rear - right	Scratch(es)	Paint
20. Front door - right	Scratch(es)	Paint
21. Front fender - right	Scratch(es)	Paint
22. tailgate	Rust	Replace
23. A-pillar Front - Left	Scratch(es)	

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



1. dashboard



1. dashboard



2.



6. maintenance



8. motor insulation



9.



10. spoiler



11. Front bumper



11. Front bumper



11. Front bumper



12. Outside mirror - left



13. Front door - left



13. Front door - left



13. Front door - left



14. Rear door - left




14. Rear door - left



14. Rear door - left



15. Sidewall - Rear - Left



15. Sidewall - Rear - Left




15. Sidewall - Rear - Left



15. Sidewall - Rear - Left



15. Sidewall - Rear - Left



16. Rear bumper



16. Rear bumper



16. Rear bumper




17. Taillight right




18. Sidewall - Rear - right



18. Sidewall - Rear - right



19. Door Rear - right



19. Door Rear - right



19. Door Rear - right




20. Front door - right



20. Front door - right



20. Front door - right



21. Front fender - right



22. tailgate



22. tailgate



22. tailgate



23. A-pillar Front - Left