



status report

customer: Bank 11, Neuss
contract number: 718773430
reference:

vehicle data

Skoda Superb Lim. Style

Vehicle identification number	TMBAJ9NP7G7092477	mileage read:	259827 km
First Registration / construction year:	27.10.2016 / 2016	Visit Date / place of birth:	18.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	unknown
Body type:	limousine	KBA no. :	8004//APO
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 140 kW (190 PS)	Engine:	front-wheel drive
paint:	Business Grau Metallic	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	Leather / Alcantara
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	4 - moderate
documents:		condition inside:	4 - moderate
visit condition:	-		
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	1	no / -	- / -

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Anderer	235/45/R18/98V 6 mm
1st axis - right / states .	Anderer	235/45/R18/98V 6 mm
2nd axis - Left / states .	Hankook	235/45/R18/98V 5 mm
2nd axis - right / states .	Hankook	235/45/R18/98V 5 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Vollwertig	

standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Storage compartment for umbrella • Airbag Driver / passenger side • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Equipment package Green tec • Body color door mirrors • brake Assist • goggle pocket • Durchladeeinrichtung (rear center armrest) • Electron. Transverse differential lock (XDS) • Driving Assistance System Collision Warning with City Emergency Braking (Front Radar Assistant) • Driving Assistance System Multi Collision Brake • Control for central locking • Footwell lights, front and rear • Transmission 6-speed - DSG • Interior Decor inlays Anthracite - Brushed • Isofix admissions for child seat in back seat • Knee airbag , driver's side • Rear headrests • Backrest of the rear seat back in the trunk • Steering wheel (leather - 3-spoke) with multifunction and switching function • Steering column (steering wheel) longitudinally adjustable • Line-in audio jack in center console • Maxi - DOT color display • Engine 2.0 ltr. - 140 kW TDI • Radio reception digital (DAB +) • Tire Pressure Monitoring System • Rear seat backrest split / folding | <ul style="list-style-type: none"> • Airbag switched off • Acoustic glass door windows in front • Acceleration skid control (ASR) • Bolero audio system (Radio / CD changer integrated) • Outside mirror electr. adjustable, heatable and foldable, with automatic dimming and memory • Bi - xenon headlamps with LED daytime running lights
<i>Leuchtweitenregelung, Fahrassistentz-System: Einschaltautomatik für Fahrlicht (Fahrlichtassistent), Heckleuchten LED (Kristallglas-Optik), Scheinwerfer-Reinigungsanlage (SRA)</i> • Brake Energy Regeneration • Chrome trim on side windows • rear Parking Sensors • Electron. Stability Program (ESP) • Driving Assistance System Hill Start Assist (Hill Holder) • Electric windows front + rear • Hands-free phone with Bluetooth • Cruise control system (cruise control) • illuminated glove compartment • Rearview mirror with auto dip • Body 5-door • Head airbag system • Front head restraints • Lumbar support front left seat
<i>Lendenwirbelstütze Sitz vorn rechts</i> • Steering column (steering wheel) adjustable in height |
|--|---|

• Heated windshield washer nozzles • Windscreen wipers with rain sensor • power steering • Front left seat height adjustment • Electric front seats . adjustable (left with memory) • Seatback front right hinged • Sun visor with mirror left • Start / Stop system • Socket (12V connection) in front center console • Lashing luggage / cargo area • Central	• Beam Assist (Coming Home , Leaving Home) • • Front center armrest • Fog lights with static cornering light • Tire repair kit • Rußpartikelfilter • Low emissions Euro 6 emission standards • Aero windscreen wipers , front • Front Side Airbags • Power steering electronically (Servotronic) • Front right seat height adjustment • Heated front seats • SmartLink (Mirror Link , Apple and Android carplay car) • Sun visor with mirror right • Socket (12V) port in the trunk / cargo area • tinted glazing • immobilizer
--	--

special Features	
• Ambient lighting LED • Business Package Columbus <i>Fahrassistenz-System: Verkehrszeichenerkennung, Seitenscheiben hinten und Heckscheibe abgedunkelt (SunSet), Freisprechanlage Premium, Maxi-DOT Farbdisplay, Audio-Navigationssystem Columbus, Kofferraum / Heckklappe elektrisch betätigt (öffnen + schliessen), Steckdose 230V, Fahrassistenz-System: Müdigkeitserkennung</i> • Driving Assistance System Autom . Cruise Control (ACC) with front radar Assistant (up to 210 km / h) • rear window wiper • Climatronic air conditioning 3-zone • Lounge -Step (carpet floor mats with footrests) • backup camera • Seat cover / upholstery Alcantara / Leather • Roller blind on rear window • Auxiliary heater (heater)	• Towbar with stability control • <i>Fahrassistenz-System: Fahrprofilwahl</i> • Driving Assistance System High-beam assistant • Occupant protection system proactively <i>Seitenairbag hinten</i> • Comfort opening for elec. Tailgate / lids <i>Kofferraum / Heckklappe elektrisch betätigt (öffnen + schliessen)</i> • Metallic paint • Close / start system KESSY • Heated rear • Sound system Canton

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable Wartungsnachweise fehlen
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Sidewall - Rear - right	Subsequently painted	acceptable
2. Door Rear - right	Subsequently painted	acceptable
3. Front door - right	Subsequently painted	acceptable
4. Front fender - right	Subsequently painted	acceptable
5. Sitz Vorne Links Lehne	Damaged	Replace
6. Sitz Vorne Links Kissen	Damaged	Smart repair
7. Zweitschlüssel	Missing	Replace
8. proof of maintenance	Missing	Replace
9. Bremsen	Worn	Replace
10. Vorglühanlage	Error message	Carry out a fault diagnosis
11. Motorkontrollleuchte	Error message	Carry out a fault diagnosis
12. Reifendruckkontrollleuchte	Error message	Carry out a fault diagnosis
13. Rim front - left	Scratch(es)	Smart repair
14. Rim rear - left	Scratch(es)	Smart repair
15. Rim rear - right	Scratch(es)	Smart repair
16. Rim front - right	Scratch(es)	Smart repair
17. Front grill bumper Below	Damaged	Replace
18. hood	Scratch(es)	Paint
19. Windshield	Scratch(es)	Replace
20. Front door - left	Damaged	Refurbish and paint
21. Outside Door Handle Front - Left	Scratch(es)	Paint
22. Türeinstieg Vorne - Links	Scratch(es)	Paint
23. roof		Smart repair
24. Rear door - left	Scratch(es)	Paint
25.	Damaged	Replace
26. Sitz Hinten Mitte Kissen	Damaged	Replace
27. tailgate	Damaged	Refurbish and paint
28. Rear bumper	Damaged	Refurbish and paint
29. Sidewall - Rear - right	Damaged	Refurbish and paint
30. side skirt - right	Deformed	Refurbish and paint
31. Door Rear - right	Damaged	Refurbish and paint
32. Front door - right	Deformed	Refurbish and paint
33.	Scrape	Paint
34. Türeinstieg Vorne - Rechts	Damaged	Refurbish and paint
35. Sitz Vorne Rechts	Damaged	Smart repair
36. Front fender - right	Deformed	Refurbish and paint
37. Front bumper	Damaged	Refurbish and paint
38. headlining	Dirty	
39. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Sidewall - Rear - right



2. Door Rear - right



3. Front door - right



4. Front fender - right



5. Sitz Vorne Links Lehne



6. Sitz Vorne Links Kissen



9. Bremsen



10. Vorglühanlage



11. Motorkontrollleuchte



12. Reifendruckkontrollleuchte



13. Rim front - left



14. Rim rear - left



14. Rim rear - left



15. Rim rear - right



15. Rim rear - right



16. Rim front - right



16. Rim front - right



17. Front grill bumper Below



17. Front grill bumper Below



18. hood




18. hood



18. hood



19. Windshield




19. Windshield



19. Windshield



20. Front door - left



20. Front door - left



20. Front door - left



21. Outside Door Handle Front - Left



21. Outside Door Handle Front - Left




22. Türeinstieg Vorne - Links




22. Türeinstieg Vorne - Links



22. Türeinstieg Vorne - Links



23. roof




23. roof



24. Rear door - left



25.



26. Sitz Hinten Mitte Kissen




26. Sitz Hinten Mitte Kissen




27. tailgate



27. tailgate



28. Rear bumper



28. Rear bumper



28. Rear bumper



29. Sidewall - Rear - right



29. Sidewall - Rear - right



30. side skirt - right



30. side skirt - right



31. Door Rear - right



31. Door Rear - right



32. Front door - right



32. Front door - right



32. Front door - right



32. Front door - right



33.



34. Türeinstieg Vorne - Rechts



34. Türeinstieg Vorne - Rechts



35. Sitz Vorne Rechts



35. Sitz Vorne Rechts



36. Front fender - right



36. Front fender - right



37. Front bumper



37. Front bumper



37. Front bumper



38. headlining



38. headlining