

Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Skoda Rapid Ambition

Vehicle identification number	TMBAN6NH5F4020723	mileage read:	95093 km
First Registration / construction year:	09.03.2015 / 2014	Visit Date / place of birth:	15.09.2025 Neuss
Bodywork:	cars	Re - import:	yes
Body type:	limousine	KBA no. :	8004//AMU
Fuel / emission class:	gasoline / € 5	transmission type:	manual transmission
Displacement / power:	1197 ccm / 77 kW (105 PS)	Engine:	front-wheel drive
paint:	Candy-Weiss	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	digital	Interior Color:	-
smoking vehicle:	yes	Last service km / on the:	32347 / 03.09.2019
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	digital / -	32347 / 03.09.2019

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	polished aluminum
1st axis - Left / states .	Fortuna	215/40/ZR17/87W 3 mm
1st axis - right / states .	Fortuna	215/40/ZR17/87W 3 mm
2nd axis - Left / states .	Continental	215/40/R17/87V 3 mm
2nd axis - right / states .	Continental	215/40/R17/87V 3 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3-point rear seat belts • Airbag Driver / passenger side • Acceleration skid control (ASR) • Power side mirrors . adjustable and heated • board computer • goggle pocket • Electr . Brake force distribution (EBD) • Electron. Stability Program (ESP) • Control for central locking • Cup holders front • Dust and pollen filter • Body 4 doors • Head airbag system • Steering wheel (4 -spoke) • Steering column (steering wheel) longitudinally adjustable • Engine 1.2 ltr. - 77 kW TSI • Multi-function display • Tire repair kit • Rear seat backrest split / folding <i>Rücksitzbank klappbar 1/3-2/3</i> • Front Side Airbags • Power steering electronically (Servotronic) • Front left seat height adjustment • Sun visor with mirror left • Socket (12V connection) in front center console • Daytime running lights switched off • Door release and activation of hazard warning lights automatically at impact • tinted glazing • Warning system for seat belt , driver's side	• Airbag switched off • Anti- lock braking system (ABS) • Audio system Swing (Radio / CD player with MP3 capability) <i>6 Lautsprecher, Line-In-Audioanschluss in Mittelkonsole</i> • Body color door mirrors • brake Assist • roof antenna • Electron. Differential lock (EDL) • Electric windows front • Transmission 6-speed • Belt tensioners • Isofix admissions for child seat in back seat • air Conditioning • Rear headrests • Steering column (steering wheel) adjustable in height • reading Light • Positive Torque Regulator (MSR) • Fog Lights • Tire Pressure Monitoring System • Low emissions Euro 5 emissions standard • power steering • Seat belts front height adjustable • Seat cover / upholstery fabric • Sun visor with mirror right • Body color bumpers • Doors with warning light • Exterior door handles body color • Lashing luggage / cargo area • Central

special Features	
- Steering wheel with multifunction - Rear side windows and rear windscreen blackened (SunSet) - Special paint candy white - Xenon headlights <i>Scheinwerfer-Reinigungsanlage (SRA), Wasserstandsanzeige SRA / SWA</i>	- Front center armrest - Front right seat height adjustment - Reversible mat Luggage Storage

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifen beschädigt.

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:	✓	examined limited	Battery / accumulator:	✓	examined limited
oil loss:	✓	examined limited			
air conditioning:	✗	Out of order	lighting system:	✓	examined limited
coupling:	✓	examined limited	exhaust System:	✓	examined limited
engine running:	✗	Out of order	shock absorber:	✗	not possible
transmission:	✓	examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning was not okay for visiting time . **Further diagnostic required.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **It rattles were found.
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat Laufleistungs und Altersbedingte Gebrauchsspuren. Kosten und Schadenserweiterung sind möglich.

damage



component	Damage	Rep kind
1. tire front - right	Worn	Replace
2.	Damaged	Replace
3. tire rear - right	Damaged	Replace
4.	Scratch(es)	Replace
5. tire rear - left	Worn	Replace
6.	Scratch(es)	Replace
7. tire front - left	Worn	Replace
8.	Scratch(es)	Replace
9. maintenance	Due	Replace
10. Key with remote control	Missing	Replace
11. motor	Abnormal noises	Carry out a fault diagnosis
12. motor insulation		Replace
13. Rear spoiler	Scratch(es)	Paint
14. Rear bumper	Scratch(es)	Refurbish and paint
15. Diffusor	Scrape	Replace
16. Sidewall - Rear - Left	Damaged	Refurbish and paint
17. Rear door - left	Damaged	Refurbish and paint
18. Front door - left	Scratch(es)	Paint
19. Türeinstieg Vorne - Links	Damaged	Refurbish and paint
20. Steering wheel (leather)	Scratch(es)	Replace
21. hood	Damaged	Refurbish and paint
22. Front grille top	Damaged	Replace
23. Windshield	Chipping from stones in field of view	Replace
24. Front door - right	Damaged	Refurbish and paint
25. Türeinstieg Vorne - Rechts	Damaged	Refurbish and paint
26. Door Rear - right	Damaged	Refurbish and paint
27. side skirt - right	Damaged	Refurbish and paint
28.	Damaged	Replace
29. Taillight right	Breakage	Replace
30. Sidewall - Rear - right	Damaged	Refurbish and paint
31. exterior body	Sticker	
32. Seitenscheibe - Hinten - Rechts Dichtung	Damaged	Replace
33. exterior body	Damaged	
34.	Dirty	
35.	Sticker	
36. warning light	Error message	Carry out a fault diagnosis
37. instrument cluster	Scratch(es)	Replace
38. Klimaanlage	Odour	Carry out a fault diagnosis

39.	flooring	Burn hole	Smart repair
40.		Burn hole	Replace
41.	tailgate	Scratch(es)	Paint
42.	Xenon headlights - left	Damaged	Replace
43.	Front bumper	Scrape	Refurbish and paint
44.	Xenon headlights - right	Damaged	Replace
45.		Wear and tear	acceptable
46.		Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record




front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



1. tire front - right



1. tire front - right



2.



2.



2.



3. tire rear - right



3. tire rear - right



4.



4.



4.



5. tire rear - left



5. tire rear - left



6.



6.



7. tire front - left



7. tire front - left



8.



8.



8.



12. motor insulation




12. motor insulation



13. Rear spoiler



13. Rear spoiler



14. Rear bumper



14. Rear bumper



14. Rear bumper



14. Rear bumper




15. Diffusor



15. Diffusor



16. Sidewall - Rear - Left



16. Sidewall - Rear - Left




16. Sidewall - Rear - Left




17. Rear door - left



17. Rear door - left



17. Rear door - left



17. Rear door - left



18. Front door - left



18. Front door - left



18. Front door - left



19. Türeinstieg Vorne - Links



19. Türeinstieg Vorne - Links



19. Türeinstieg Vorne - Links



20. Steering wheel (leather)




20. Steering wheel (leather)



21. hood



21. hood



21. hood



22. Front grille top



22. Front grille top



23. Windshield



23. Windshield



23. Windshield



23. Windshield



24. Front door - right



24. Front door - right



24. Front door - right




25. Türeinstieg Vorne - Rechts




25. Türeinstieg Vorne - Rechts



26. Door Rear - right



26. Door Rear - right



26. Door Rear - right



27. side skirt - right



27. side skirt - right



28.




29. Taillight right




29. Taillight right



30. Sidewall - Rear - right



30. Sidewall - Rear - right



30. Sidewall - Rear - right



30. Sidewall - Rear - right



30. Sidewall - Rear - right



31. exterior body



31. exterior body



31. exterior body



32. Seitenscheibe - Hinten - Rechts Dichtung




32. Seitenscheibe - Hinten - Rechts Dichtung



33. exterior body



34.



34.



34.



35.



36. warning light



37. instrument cluster




37. instrument cluster



39. flooring



40.



40.



41. tailgate



41. tailgate



42. Xenon headlights - left



42. Xenon headlights - left



43. Front bumper



43. Front bumper



43. Front bumper



43. Front bumper




44. Xenon headlights - right




44. Xenon headlights - right




45.



46.



46.



46.