

Vehicle details

VIN	TMBAP7NE9 L0104973	Brand	SKODA	Maintenance date	-
Licence Plate	B135GTS	Model	Octavia2-2004	Maintenance mileage	-
Registration date	13/01/2020	Year	2020	Exterior Color	Alb
Odometer	101 520 km	Engine size	1968	interior Color	
Fuel	Petrol	Body Type	Saloon / Hatchback	Next technical inspection	08/01/2027
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	16/01/2025	Inspection loc.	Benga / ARVAL EOT
-----------------	------------	-----------------	-------------------



Generic equipment

Automated air-conditioning	✓
Rain and light sensor	✓
Anti-fog lights	✓
Alloy wheel rims	✓
Reversing radars	✓
Heating seats	✓

Removable element

Spare wheel (wheel & tyre)	✓
Jack	✓
Load cover	✓
Rear parcel shelf	✓

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓
Spare key	✓
Key	✓
Title / License document	✓

Tyres

Winter kit

Semperit 205/55/16 Winter 4.0 mm		Semperit 205/55/16 Winter 4.0 mm			Continental 205/55/16 Winter 6.0 mm Vara
Semperit 205/55/16 Winter 4.0 mm		Semperit 205/55/16 Winter 4.0 mm			

Exterior

1



Part

Position

Damages

Severity

Repair mode

Door

Front left

Scratched

-

Repair

2



Part

Position

Damages

Severity

Repair mode

Exterior door mirror shell

Front left

Scratched

-

Repair

3



Part

Position

Damages

Severity

Repair mode

Bumper

Front

Scratched

-

For info

4



Part

Position

Damages

Severity

Repair mode

Bonnet

Front

Not conform

-

For info

5



Part

Position

Damages

Severity

Repair mode

Windscreen

Front

Scratched

-

For info

6



Part

Position

Damages

Severity

Repair mode

Door

Back right

Scratched

-

Repair

7



Part

Position

Damages

Severity

Repair mode

Wing

Back right

Dented

-

Repair

8



Part

Position

Damages

Severity

Repair mode

Wheelcap

Back right

Missing

-

Replace

9



Part

Position

Damages

Severity

Repair mode

Tyre

Back right

Pierced

-

Replace

10



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Scratched

-

For info

11



Part

Position

Damages

Severity

Repair mode

Wing

Back left

Scratched

-

Repair

12



Part

Position

Damages

Severity

Repair mode

Door

Back left

Scratched

-

Repair

13



Part

Position

Damages

Severity

Repair mode

Sill

Left

Dented

-

Repair

22



Part

Position

Damages

Severity

Repair mode

Alloy wheel 16"

Back left

Scratched

-

For info

23



Part

Position

Damages

Severity

Repair mode

Door Frame seal

Front left

Perforated

-

Replace

Interior damage

14



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

15



Part	Air vent
Position	Front left
Damages	Broken
Severity	-
Repair mode	Replace

16




Part	Fabric seat
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

17



Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

18



Part	Interior roof lining
Position	Inside
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

19



Part	Isofix cover
Position	Back right
Damages	Missing
Severity	-
Repair mode	For info

20



Part	Isofix cover
Position	Back left
Damages	Missing
Severity	-
Repair mode	For info

21



Part	Fabric door lining
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

Comments

Auto poate fi condus.A/C nefunctional.Ornamente plastic interior usor zgariate.Auto prezinta multiple zgarieturi superficiale.