



SKODA Octavia
Octavia 1.4 TSI iV DSG

VIN NO TMBAW8NX4PY012185
Registration Number X4PY012185



MOT Date

2025-09-01

Last Service



Number of Owners

1

Last Service Mileage



Number of Keys

2

First Registration Date

2022-09-06

Odometer Reading

90637 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251010083825
Inspection Date / Place	2025-10-10 / BCA Neuss	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1395
Engine Size	1.4	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	anthrazit	Seat Covering	Cloth
Charging Cables	Occasional Use Charge	NEDC CO2 Rating (q/km)	28
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	USB Socket	Airbag Status	Ambientlighting
Bluetooth telephone interface	Digital Radio	Fatiguewarningsystem	Front parking sensors
Remote adjusting wing mirrors	Reversing Camera	Stability control	Emergencybrakeassist
Leather steering wheel	Radio	Trafficsignrecognition	Adaptivecruisecontrol
Alloys wheels	Anti-lock braking	Cruise control	Digitaldashboard
Front fog lamps	Heated wing mirrors	Remote central locking	Satellite navigation
Electrically folding wing mirrors	Laneassist	LED Headlamps	Rear parking sensors


Equipment Details

Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front and Rear

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5
Right Front Tyre Depth	5	Right Rear Tyre Depth	5
Left Front Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage



Component	Damage	Comments
1 Rim / Back Right	Out of Bodywork / Scratch	
2 Other	Paint / Poor Previous Repair	
3 Rim / Front Right	Out of Bodywork / Scratch	
4 Rocker Panel / Center Left	Paint / Scratch / Scuff	
5 Fender / Back Right	Bodywork / Dent / Dent	




1. Rim / Back Right
Out of Bodywork / Scratch -




2.
Paint / Poor Previous Repair -



3. Rim / Front Right
Out of Bodywork / Scratch -



4. Rocker Panel / Center Left
Paint / Scratch / Scuff -



5. Fender / Back Right
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)