

# SKODA Octavia Octavia Combi 1.8 TSI

BCA

VIN NO TMBGK61Z6A2083707 Registration Number Z6A2083707

MOT Date

**2**026-01-01

Last Service

**=**-

Number of Owners

**23:** 1

Last Service Mileage

**?** 

Number of Keys

**P**2

First Registration Date

2010-01-28

**Odometer Reading** 

**✓** 133797 km

Country First Registered

Germany

### **Inspection Report Summary**

Customer	BCA Online	Report Number	P20251010085049
Inspection Date / Place	2025-10-10 / BCA Oberndorf	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1798
Engine Size	1.8	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/ Grau	Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	158
Gearbox Type	Manual		

### Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			




























# Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Front fog lamps
Remote adjusting wing mirrors	Roof rails	Stability control	CD Player
Leather steering wheel	Rear parking sensors	Tow ball	Alloys wheels
Auxiliary Socket	Heated wing mirrors	Remote central locking	Split folding rear seats
Xenon headlamps	Central locking	Radio	


## **Equipment Details**

Tow Ball Type	Detachable	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	16	Seat Heating	Front

## Wheels & Tyres

Left Rear Tyre Depth	5	Right Front Tyre Depth	4
Left Front Tyre Depth	4	Right Rear Tyre Depth	5

#### Cosmetic Damage



14 Hood Bodywork / Dent / Dent



1. Fender / Back Right Paint / Scratch / Line -

2. Paint / Scratch / Scuff -




3. Rocker Panel / Center Left Paint / Scratch / Line -




4. Tailgate Paint / Scratch / Line -



5. Bumper / Back Paint / Scratch / Scuff -



6. Door / Back Left Paint / Scratch / Line -



7. Seat / Front Left Interior / Scratched -

8. Fender / Front Right Bodywork / Dent -



9. Fender / Front Left Paint / Scratch / Line -



10. Gear Knob Interior / Scratched -



11. Door / Front Right Paint / Scratch / Line -



12. Paint / Other -



13. Door / Front Left Paint / Scratch / Line -

14. Hood Bodywork / Dent / Dent -

#### **Mechanical Condition**

Equipments Test			
Central Locking	<b>⊘</b>	Electric Windows	<b>⊘</b>
Audio Equipment	<b>⊘</b>	AC / Heating System	•
Main & Spare Keys Functioning	•	Parking Sensors / Cameras Functioning	•
Other Equipments	•		
Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Airbag Warning Light	<b>⊘</b>	Oil Pressure Warning Light	•
Brake Warning Light	•	Power Steering Warning Light	•
Alternator / Battery	•	No Dashboard Lights	•
Display Defect	•	Service Light	•
Tire Pressure Monitoring System	•		
Engine			
Engine Status / EML	<b>⊘</b>	Engine Leak Visible	
Engine Starts	<b>⊘</b>		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	<b>Ø</b>	Coolant Fluid	

#### **Test Drive Inspection**

description.

# Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** Clutch **Clutch Functioning** General Not Performed **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

**User Guide**