



status report

customer: Bank 11, Neuss
contract number: 868551730-INSO
reference:

vehicle data

Skoda Kamiq Ambition

Vehicle identification number	TMBGP9NW8M3126090	mileage read:	90200 km
First Registration / construction year:	23.03.2022 / 2021	Visit Date / place of birth:	16.05.2025 Heidenheim
Bodywork:	SUV	Re - import:	yes
Body type:	Road /	KBA no. :	8004//AUE
Fuel / emission class:	gasoline / € 6	transmission type:	5 speed manual transmission
Displacement / power:	999 ccm / 70 kW (95 PS)	Engine:	front-wheel drive
paint:	Schwarz-Magic Perleffekt	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	-	state outside:	3 - Average
visit condition:	in the parking garage	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	- / -
		no / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	original aluminum
1st axis - Left / states .	Anderer	205/60/R16/96V 8 mm
1st axis - right / states .	Anderer	205/60/R16/96V 8 mm
2nd axis - Left / states .	Anderer	205/60/R16/96V 8 mm
2nd axis - right / states .	Anderer	205/60/R16/96V 8 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Siehe Gutachten	

standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • 3. LED brake light • Storage bag on front seat backrests • Airbag Driver / passenger side • Acceleration skid control (ASR) • Power side mirrors . adjustable and heated • Indicator lights LED integrated in exterior mirrors • Brake Energy Regeneration • roof rails • Electr . Brake force distribution (EBD) • Electron. Transverse differential lock (XDS) • Driving Assistance System Collision Warning with City Emergency Braking (Front Radar Assistant) • Driving Assistance System Multi Collision Brake • Electric windows front + rear • Hands-free phone with Bluetooth • Luggage security / luggage attachment (cargo elements) • Transmission 5-speed • Rear lights, partial LED (tail light and brake light) • Infotainment-Swing Package • Isofix admissions for child seat in the passenger seat • Body 5-door • air Conditioning • trunk lighting • Lumbar support front left seat • Steering wheel (leather - 2 spokes) with multifunction • Steering column (steering wheel) adjustable (vertical / axial) • Front center armrest | <ul style="list-style-type: none"> • • Airbag switched off • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Body color door mirrors • brake Assist • goggle pocket • rear Parking Sensors • Electron. Differential lock (EDL) • Electron. Stability Program (ESP) • Driving Assistance System Hill Start Assist (Hill Holder) • Driver assistance system Lane Assist • Control for central locking • Luggage compartment cover / shade • Speed control system (cruise control) incl. Speed limiter system • illuminated glove compartment • heated rear window • Dust and pollen filter • Isofix admissions for child seat in back seat • License plate light LED • Knee airbag , driver's side • Head airbag system • Lumbar support front right seat • Steering wheel (leather - 2 spokes) with multifunction and switch function • Beam Assist (Coming Home , Leaving Home) • Motor 1,0 Ltr. - 70 kW RIGHT • emergency call system • Radio reception digital (DAB +) |
|--|---|

• Multi-function display • Otto Particle Filter (OPF) • Wheelbase 2651mm • Tire Pressure Monitoring System • Low-pollutant according to the Euro 6d emissions standard • Front Side Airbags • Front left seat height adjustment • Sun visor with mirror left • Start / Stop system • Front and rear bumper cover, platinum grey • Exterior door handles body color • Lashing luggage / cargo area	• Tire repair kit • Rear seat back split/foldable (1/3-2/3) • Part LED headlights (daytime running lights and low beam) • power steering • Seat relation / upholstery fabric Ambition Black • Sun visor with mirror right • Socket (12V) port in the trunk / cargo area • LED daytime running lights • USB interface at the front (2-way, type C) • Central
--	---

special Features	
• Ambiente-Beleuchtung LED in weiß • Occupant protection system proactively <i>Seitenairbag hinten</i> • Pearl effect paint • Heated front seats <i>Scheibenwaschdüsen heizbar</i>	• Interior inlays in silver • LM-Felgen 6x16 (Orion) • Front right seat height adjustment • SmartLink (Mirror Link , Apple and Android carplay car)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifendruckkontrolle leuchtet

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			examined limited	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug war zum Zeitpunkt der Begutachtung Verschmutzt/Nass/Vereist/Zugeparkt oder wurde bei unzureichender bzw schlechter Beleuchtung besichtigt.Manche Bereiche waren unter Umständen verdeckt oder zugesagt.Unter Umständen waren nicht alle Fahrzeugsysteme und Ausstattung prüfbar.Versteckte Schäden oder Schadensenerweiterung möglich.

damage



	component	Damage	Rep kind
1.	Wartung		Replace
2.	Amaturen Brett	Delle	Replace
3.	hood	Scratch(es)	Smart repair
4.	Front bumper	Scratch(es)	Paint
5.	Spiegelkappe links	Scratch(es)	Smart repair
6.	Front door - left	Scratch(es)	Smart repair
7.	Rear door - left	Sticker	
8.	Sidewall - Rear - Left	Deformed	Smart repair
9.	Roof frame - left		Smart repair
10.	Rear bumper	Scratch(es)	Paint
11.	tailgate	Scratch(es)	Smart repair
12.	Sidewall - Rear - right	Deformed	Smart repair
13.	Side window - Rear - right	Damaged	Replace
14.	Door Rear - right	Scratch(es)	Paint
15.	Front door - right	Scratch(es)	Smart repair
16.	Innenraum	Dirty	
17.	Türeinstieg Hinten rechts	Scratch(es)	Smart repair
18.	Türverkleidung Hinten rechts	Scratch(es)	Smart repair
19.	Türeinstieg Hinten links	Scratch(es)	Smart repair
20.	Fahrersitz Sitzposter	Scratch(es)	Smart repair
21.	Fahrersitz Lehne	Crack	Replace
22.	Dachhimmel		Smart repair
23.	Leder Lenkrad	Scratch(es)	Smart repair
24.	reifendichtmittel	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. Wartung



2. Amaturenbrett



2. Amaturenbrett



3. hood



3. hood



3. hood



4. Front bumper



4. Front bumper



5. Spiegelkappe links



5. Spiegelkappe links



6. Front door - left



6. Front door - left



6. Front door - left




7. Rear door - left




7. Rear door - left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



9. Roof frame - left



9. Roof frame - left



10. Rear bumper



10. Rear bumper



10. Rear bumper



11. tailgate



11. tailgate



11. tailgate



12. Sidewall - Rear - right



12. Sidewall - Rear - right



12. Sidewall - Rear - right



13. Side window - Rear - right



13. Side window - Rear - right



13. Side window - Rear - right




14. Door Rear - right



14. Door Rear - right



15. Front door - right



15. Front door - right



16. Innenraum



16. Innenraum



16. Innenraum



16. Innenraum



17. Türeinstieg Hinten rechts



18. Türverkleidung Hinten rechts



18. Türverkleidung Hinten rechts



19. Türeinstieg Hinten links



19. Türeinstieg Hinten links



20. Fahrersitz Sitzposter



20. Fahrersitz Sitzposter



21. Fahrersitz Lehne



22. Dachhimmel



23. Leder Lenkrad



23. Leder Lenkrad



24. reifendichtmittel