



Expertise

Protocol number: 41667837
Order No. / Reference: 25150159
Inspection date: 22 Sept 2025

Manufacturer: Skoda
VIN: TMBJH7NP8M7067647

Model: Superb Combi 2.0 TDI Ambition



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Superb Combi 2.0 TDI Ambition	
Vehicle Identification number	TMBJH7NP8M7067647
Mileage (Read)	99,965 km
First registration	8 Jun 2021
Number of holders	1
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Lava Blau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	11,300 km
Last maintenance on / at	08/2025 at 97,965 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	GA540850
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / APL 01095		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	2,070 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94V	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	215/55 R17 94V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2025		

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- Storage compartments closed, behind the wheel arches in the trunk including cargo elements
- Airbag, driver and switchable passenger airbag
- Airbag, head airbags
- Anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black
- Exterior mirrors and door handles in body color
- Illuminated glove compartment
- Hydraulic brake assist (HBA)
- Roof rails, black
- diesel particulate filter
- Third brake light
- Electronic transverse differential lock (XDS+)
- Headlight assistant and rain sensor
- Front radar assistant including city emergency braking function
- Transmission: 6-speed manual transmission
- Green tec: Automatic start/stop system including brake energy recovery
- ISOFIX preparation on the outer rear seats, including top tether
- Headrests height adjustable front and rear
- LED taillights
- Steering wheel: Leather steering wheel with multifunction buttons
- Front center armrest with storage compartment
- Multifunctional display with Maxi-Dot display
- Fog lights with integrated cornering light
- Upholstery: Cloth
- Radio accessories: Digital radio reception DAB+
- Umbrella compartments in the front doors
- Tire pressure monitoring
- Heated windscreen washer nozzles
- Seat belts Superb
- Seats: Height-adjustable front seats
- SKODA Care Connect
- 12-V socket in the center console front and rear
- Telephone: Comfort hands-free telephone system
- Chrome-plated elements
- Immobiliser
- Shelves
- Removable LED battery flashlight in the trunk
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Traction control (ASR)
- Exterior mirrors electrically adjustable and heated
- Exterior mirrors, electrically folding
- Hill start assist
- Grey headliner
- Decorative inlay silver brushed
- tachometer
- Electronic parking brake including auto-hold function
- Electronic Stabilization Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control including speed limiter
- Tinted windows
- Heated rear window
- Rear window wiper including windscreen washer system
- Climatronic air conditioning (2 zones)
- Trunk cover, roll-up and removable, semi-automatic
- Metal loading sill protection
- Steering wheel: height and length adjustable
- Rear center armrest with cup holders and through-loading option
- Engine drag torque control (MSR)
- Multi-collision brake assistant (MKB)
- Rear parking sensors
- Radio: Swing 6.5" music system including SD card slot
- Radio accessories: Line-in audio connection (3.5 mm) and USB port in the center console
- Tire mobility set
- Power steering, electromechanical
- Seats: Adjustable lumbar supports in the front seats
- Seats: Rear seat backrest 60:40 split folding
- 12-V socket in the trunk
- Daytime running lights integrated into the main headlights
- Time display on the rear center console
- Lashing eyes in the trunk
- Central locking with radio remote control

Extra equipment



- Paint finish: metallic
- Wheels: 17" Drakon alloy wheels
- Seats: Heated front seats

- Package: Business Columbus (Ambition, GreenLine) (Combi)
(dynamic radio navigation system Columbus capacitive 9.2" touchscreen color Maxi-Dot display, traffic sign recognition, Smartlink + including Apple Car Play, Android Auto, in-car communication, Wi-Fi hotspot, DVD drive, 2 SD card slots, premium hands-free system rSAP with SIM card slot, phone box with inductive charging, voice control, fatigue detection, 230 V socket with USB port, electric tailgate, Sunset luggage net partition, multifunctional shelf, LED taillights, crystal glass optics.)

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Interior	Sun visor - right side - Damaged - Replace
3	Instrument panel	Air nozzle - centre - Damaged - Replace
4	Front bumper	Front bumper - Scratched - Repair and paint
5	Rear bumper	Rear bumper - Scratched - Repair and paint
6	Boot lid / rear door	Boot lid - Scratch(es) - Paint
7	Door - front left side	Door - Scratch(es) - Paint
8	Bonnet	Bonnet - Scratch(es) - Paint
9	Vehicle glazing	Windscreen - Damaged - Replace
10	Roof	Roof (+ Kratzer) - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Cargo area - lining -left side - Scratched - No deduction
2	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - No deduction
3	Roof	Roof rail - left side - Scratch(es) - No deduction
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
5	Door - front right side	Brightware - lower - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 29 Oct 2023	1.585,77 €



Accident damages

No. Accident

- 1 Side - left
- 2 Side right

Repainting

No. Repainting

- 1 Side panel - rear right side, Door - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	1,830 µm	Door - rear right side	212 µm
------------------------------	-------------	------------------------	--------

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.



Comments

- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkter Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden

Minderwerte höher als HEK



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Interior: Sun visor - right side - Damaged - Replace



Damage 2: Interior: Sun visor - right side - Damaged - Replace



Damage 3: Instrument panel: Air nozzle - centre - Damaged - Replace



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint




Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Damage 4: Front bumper: Front bumper - Scratched - Repair and paint



Damage 5: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 5: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 5: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 6: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 6: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 6: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 6: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 6: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 6: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint




Damage 8: Bonnet: Bonnet - Scratch(es) - Paint



Damage 8: Bonnet: Bonnet - Scratch(es) - Paint




Damage 9: Vehicle glazing: Windscreen - Damaged - Replace




Damage 9: Vehicle glazing: Windscreen - Damaged - Replace



Damage 10: Roof: Roof (+ Kratzer) - dent(s) - Repair and paint



Damage 10: Roof: Roof (+ Kratzer) - dent(s) - Repair and paint



Damage 10: Roof: Roof (+ Kratzer) - dent(s) - Repair and paint



Wear and tear 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 5: Door - front right side: Brightware - lower - Scratch(es) - No deduction



Wear and tear 5: Door - front right side: Brightware - lower - Scratch(es) - No deduction



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left




Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left




Accident 1: Side - left



Accident 2: Side right



Accident 2: Side right




Accident 2: Side right




Accident 2: Side right



Accident 2: Side right



Accident 2: Side right




Accident 2: Side right



Accident 2: Side right




Accident 2: Side right



Repainting 1: Side panel - rear right side, Door - rear right side



Repainting 1: Side panel - rear right side, Door - rear right side



Repainting 1: Side panel - rear right side, Door - rear right side



Repainting 1: Side panel - rear right side, Door - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJH7NP8M7067647
Hersteller / Modell: SKODA SKODA Superb Combi 2.0 TDI Ambition

Datum	KM-Stand	Beschreibung
18.08.2025	97.965	Regelwartungsdienst; Wartung Sonstiges
27.02.2025	86.820	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Reparatur Sonstiges; Systemtest/ Eigendiagnose; Wartung Sonstiges
15.07.2024	72.363	AU
24.01.2024	62.548	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
24.05.2023	43.354	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
18.10.2022	31.007	Regelwartungsdienst
25.05.2022	21.746	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges