

Vehicle details

VIN	TMBJH7NP9 N7018202	Brand	SKODA	Maintenance date	-
Licence Plate	KU524XH	Model	SUPERB 150 Ps Tdi Ambition 7-Gang Dsg Combi 110	Maintenance mileage	-
Registration date	03/12/2021	Year	1000	Exterior Color	Grey Metallic
Odometer	96 764 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/12/2024
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	03/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element




Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Dunlop 215/60/16 H Winter 7.6 mm		Dunlop 215/60/16 H Winter 7.7 mm	
Dunlop 215/60/16 H Winter 5.2 mm		Dunlop 215/60/16 H Winter 5.3 mm	

Exterior

2		Part	Bumper	3		Part	Door sill
		Position	Front			Position	Back left
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair

4



Part

Position

Damages

Severity

Repair mode

Wing

Back left

Dented

-

Repair

●

●

5



Part

Position

Damages

Severity

Repair mode

Roof post A/B/C

Left

Hail damaged

-

Repair

●

●

●

6



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Scratched

-

Repair

●

●

7



Part

Position

Damages

Severity

Repair mode

Tailgate / Boot door

-

Dented

-

Repair

●

●

●

●

●

●

9



Part

Position

Damages

Severity

Repair mode

Roof

-

Hail damaged

-

Repair

●

●

●

●

10



Part

Position

Damages

Severity

Repair mode

Roof post A/B/C

Right

Improper repair

-

Repair

●

●

●

●

Interior damage

1



Part	Interrupteur Start/Stop
Position	-
Damages	Broken
Severity	-
Repair mode	Replace

8



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

Others

11



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

12



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint