

SKODA Octavia Octavia Combi 2.0 TDI DSG



VIN NO TMBJJ7NE3J0356040 Registration Number E3J0356040

MOT Date

Number of Keys

Odometer Reading

2026-06-01

2

P2

255399 km

Last Service

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

2025-02-19 230448 2018-08-07

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924111518
Inspection Date / Place	2025-09-24 / BCA Oberndorf	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Light Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	118
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			






























Equipment

Tinted Glass	USB Socket	AndroidAuto	AppleCarPlay
Cruise control	Digital Radio	Heated wing mirrors	Remote central locking
Roof rails	Split folding rear seats	Central locking	Electrictailgate
Leather steering wheel	Radio	Tow ball	Airbag Status
Anti-lock braking	Bluetooth telephone interface	e Diesel particulate filter	Front fog lamps
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Stability control
Distancewarningsystem	Emergencybrakeassist	LED Headlamps	Rear parking sensors


Equipment Details

Tow Ball Type	Detachable	Air Conditioning	Yes
Seat Heating	Front		


Wheels & Tyres

Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage



	Component	Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Roof	Bodywork / Dent / Dent	
3	Center Console	Interior / Ripped	
4	B Pillar / Center Left	Paint / Scratch / Line	
5	Fender / Front Left	Bodywork / Dent / Dent	
6	Reflector / Back Left	Bodywork / Breakage / Crack	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Fender / Back Right	Bodywork / Dent / Dent	



1. Bumper / Front Paint / Scratch / Scuff -

2. Roof Bodywork / Dent / Dent -



3. Center Console Interior / Ripped -

4. B Pillar / Center Left Paint / Scratch / Line -



5. Fender / Front Left Bodywork / Dent / Dent -

6. Reflector / Back Left Bodywork / Breakage / Crack -



7. Bumper / Back Paint / Scratch / Scuff -

8. Fender / Back Right Bodywork / Dent / Dent -

Mechanical Condition

Equipments Test			
		Floatria Windows	
Central Locking	•	Electric Windows	•
Navigation System	•	Audio Equipment	⊘
AC / Heating System	•	Main & Spare Keys Functioning	•
Parking Sensors / Cameras Functioning	•	Other Equipments	•
Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	⊘	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	•	Display Defect	•
Service Light	•	Tire Pressure Monitoring System	⊘
Engine			
Engine Status / EML	⊘	Engine Leak Visible	②
Engine Starts	⊘		
Gearbox			
Gear Box	⊘		
Levels			
Brakes Fluid	•	Coolant Fluid	•

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** Not Performed No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide