



Expertise

Protocol number: 39967748
Order No. / Reference: 24798987
Inspection date: 30 May 2025

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG Style
VIN: TMBJJ7NX0MY141190	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG Style	
Vehicle Identification number	TMBJJ7NX0MY141190
Mileage (Read)	119,400 km
First registration	28 Apr 2021
Number of holders	1
Next periodical technical inspection	04/2026
(Report on hand)	
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Blau Race Metallic (F5W)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	19,400 km
Last maintenance on / at	02/2025 at 113,039 km		
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	GA530942
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	Sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / AWL 00078		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	1,990 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91V	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	205/55 R17 91V	Summer tyres on Light alloy	Pirelli	6mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	205/60 R16 92H	Winter tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2025		

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Dashboard center section with fabric cover
- Exterior mirrors electrically adjustable and heated
- Exterior mirrors, electrically folding
- hill start assist including auto-hold function
- Hydraulic brake assist (HBA)
- Grey headliner
- diesel particulate filter
- tachometer
- Electronic parking brake
- Electronic Stabilization Control (ESC)
- Driving profile selection
- Front radar assistant including city emergency braking function and person and cyclist detection
- Transmission: 7-speed direct shift gearbox (DSG)
- Green tec: Automatic start/stop system including brake energy recovery
- Rear window wiper including windscreen washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2 zones)
- Headrests (5) front and rear height adjustable
- LED rear lights
- LED headlights with LED daytime running lights
- Steering wheel: height and length adjustable
- Manual headlight range adjustment
- rear center armrest with through-loading option
- Engine drag torque control (MSR)
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports at the front
- Radio accessories: 8 speakers
- Radio accessories: voice control
- Tire pressure monitoring
- Wheels: 17" Rotare AERO alloy wheels (7J x 17, ET 46 with 205/55 R17 tires)
- Safety lights in the front side doors
- Seats: Height-adjustable driver and passenger seats
- SKODA Care Connect
- Lane keeping assistant (Lane Assist)
- 12-V socket in the trunk
- Phone: SmartLink (MirrorLink, Apple CarPlay, Android Auto)
- Phone: Wireless SmartLink for Apple CarPlay
- Lashing eyes in the trunk
- Shelves
- Airbag, driver and passenger
- Airbag, head airbags
- Ambient lighting
- Traction control (ASR)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors with memory function
- Heated windscreen washer nozzles including 5l washer fluid reservoir
- Glasses compartment on the roof lining
- Roof rails, anodized
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Tinted windows
- Taillights in crystal glass look and animated indicators
- Heated rear window
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Electronic child lock
- Removable trunk cover
- LED fog lights
- LED license plate lighting
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Leather steering wheel with multifunction buttons with shift paddles
- Front center armrest, including storage compartment
- Parking sensors front and rear
- Radio: Bolero music system with capacitive 10" color display
- Radio accessories: Digital radio reception DAB+
- Rain sensor
- Tire mobility kit (tire repair spray including compressor)
- Power steering, electromechanical
- Seat belts
- Seats: Heated front seats
- Seats: Rear seat backrest 60:40 split folding
- Speed limiter
- lane change and parking assistant
- Telephone: Phonebox with inductive charging function (connection via the external antenna)
- Bluetooth hands-free phone system
- Immobiliser



- Central locking including radio remote control integrated in the key and EASY Start

Extra equipment

- Trailer coupling, pivoting including trailer stabilization and adapter
- Comfort opening with electric tailgate operation (including semi-automatic luggage compartment blind)
- Package: Infotainment Columbus Plus (Combi) (Columbus navigation system - Infotainment Online (term 3 years) - Head-Up Display - Luggage net partition)
- Package: Parking & Visibility (cornering light in the fog lights - headlight cleaning system - LED ambient lighting - LED main headlights matrix and dynamic high beam assistant (AFS) - taillights in crystal glass look with animated indicators - rear view camera - park assist)
- Package: Travel (DSG) (Traveler assistance system: - Traffic sign recognition - Predictive and adaptive cruise control (pACC) - Adaptive lane keeping assistant - Emergency and traffic jam assistant - Capacitive steering wheel with hands-off detection - Adaptive cruise control (ACC) (control range 210 km/h) - Drowsiness detection - Driving profile selection - Automatically dimming exterior mirror (driver's side))
- Chassis: Chassis raised (15 mm increased ground clearance - modified damper tuning - engine underbody protection)
- Paint finish: metallic
- Package: Comfort & Relax (Combi) (3-zone Climatronic - Sunset (rear window and rear side windows dark tinted) - Acoustic glazing in the front side windows - Heated front and outer rear seats - Heated steering wheel - 230 V socket and 3 x USB charging ports - Sun blinds in the rear doors - Multifunctional storage in the trunk - Sleeping headrests in the rear - Semi-automatic luggage compartment blind)
- Package: Simply Clever (Double-sided trunk mat - Media holder - Tablet holder - Waste bin - 3rd vehicle key)
- Electric panoramic sunroof (no glasses compartment on the roof lining)
- Seats: Manually adjustable Ergo seats in the front (massage function - electrically adjustable lumbar support - pull-out leg rest)
- Auxiliary heating

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate part 2 (letter) was available, but the registration certificate part 1 (certificate) was not available. (Copy)
VIN comparison	The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Instrument panel	Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis
3	Rear bumper	Rear bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Scratch(es) - No deduction
2	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
3	2nd wheel set	1 alloy rim - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.



Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 8 Feb 2022	3.221,62 €
2	Front, Side - left, Side right, Provided by user / customer, from 12 Apr 2022	20.195,86 €

Repainting

No.	Repainting
1	Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side, Professionally carried out

Paint coat thickness measurement

Roof rail - left side	187 µm	Roof rail - right side	163 µm
Mudguard - left side	199 µm	Mudguard - right side	209 µm
Bonnet	214 µm	Side panel - rear left side	730 µm
Door - front left side	288 µm		

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis




Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis




Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis




Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 2: Instrument panel: Indicator light (Mehrkosten können entstehen) - on - Perform diagnosis



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side




Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Repainting 1: Roof rail - left side, Roof rail - right side, Mudguard - left side, Mudguard - right side, Bonnet, Side panel - rear left side, Door - front left side



Roof rail - left side: 187 µm



Roof rail - left side: 187 µm



Roof rail - right side: 163 µm




Roof rail - right side: 163 µm



Mudguard - left side: 199 µm




Mudguard - left side: 199 µm



Mudguard - right side: 209 µm



Mudguard - right side: 209 µm




Bonnet: 214 µm



Bonnet: 214 µm



Side panel - rear left side: 730 µm



Side panel - rear left side: 730 µm



Door - front left side: 288 μm



Door - front left side: 288 μm