Inspection location Hartmann Fleet Professionals GmbH Industriestraße 11 36272 Niederaula



Expertise

Protocol number: 41551879
Order No. / Reference: 25227074
Inspection date: 15 Sept 2025

Manufacturer: Skoda

Model: Octavia Combi 2.0 TDI DSG Style

VIN: TMBJJ7NX7MY107974





Vehicle details				
Manufacturer / Type / Model / Equipment				
Skoda Octavia Combi 2.0 TDI DSG Style				
Vehicle Identification number	TMBJJ7NX7MY107974			
Mileage (Read)	184,252 km			
First registration	26 Feb 2021			
Number of holders	1			
Power / Engine displacement	110 kw / 1,968 ccm			
Fuel type / Cylinder	Diesel / 4			
Gearbox / Number of gears	Automatic / 7			
Type of drive	Front drive			
Type of vehicle	Station wagon			
Colour / colour code	Moon-Weiß Perleffekt			
	(S9R)			
Doors / Seats	5/5			
Upholstery type	Cloth			
Colour of upholstery	Black-Grey			

Inspection location Hartmann Fleet Professionals GmbH Industriestraße 11 36272 Niederaula



Veh	icle details				
Main	tenance booklet / proof	Non-existent	Next maintenance in	2,300 km	
Key i	s / should be	2/2	FZG documents	ZB#2 (B) was ava	ailable (copy), ZB#1 (S
				was not available	
			Letter No.	GA498958	
Previ	ous damage / Accident	None detectable	Repainting None detectable		
Inspe	pection conditions sufficient Lifting equipment / pit		yes		
Test	drive	Not performed	Engine function test	Performed	
Manu	ıfacturer key number/	8004 / AWL 00063			
type	code number				
Emission standard		EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker		
Perm	itted total weight	1,990 kg	Empty weight		
Tyre	es				
Mou	nted tyres				
#	Tyre size	Type of tyre	Manufacture	er	Tread depth
1)	225/45 R18 91Y	Summer tyres on Light alloy	Pirelli		4mm / 4mm
2)	225/45 R18 91Y	Summer tyres on Light alloy	Uniroyal		7mm / 7mm
Addi	itional tyres				
#	Tyre size	Type of tyre	Manufacture	er	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Continental		5mm / 5mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Continental		5mm / 5mm
Repl	acement				
Тур	Tyre size	Type of tyre	Manufacture	er	Tread depth
	Tirefit	Expiration date 11/2024			

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- · Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- · Dashboard center section with fabric cover
- · Exterior mirrors electrically adjustable and heated
- · Exterior mirrors, electrically folding
- · Hill start assist including auto-hold function
- · Hydraulic brake assist (HBA)
- · Grey headliner
- · diesel particulate filter
- · tachometer
- · Electronic parking brake
- · Electronic Stabilization Control (ESC)
- · Driving profile selection
- Front radar assistant including city emergency braking function and person and cyclist detection
- · Transmission: 7-speed direct shift gearbox (DSG)
- Green tec: Automatic start/stop system including brake energy recovery
- · Rear window wiper including windscreen washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- · Climatronic air conditioning (2 zones)
- · Headrests (5) front and rear height adjustable
- · LED rear lights
- · LED headlights with LED daytime running lights
- · Steering wheel: height and length adjustable
- · Manual headlight range adjustment
- · Rear center armrest with through-loading option
- Engine drag torque control (MSR)
- · Upholstery: Cloth
- · Radio accessories: 2 USB-C ports at the front
- · Radio accessories: 8 speakers
- Radio accessories: voice control
- · Tire pressure monitoring
- Wheels: 17" Rotare AERO alloy wheels
- · Seat belts
- Seats: Heated front seats
- · Seats: Height-adjustable driver and passenger seats
- · Seats: Rear seat backrest 60:40 split folding
- Speed limiter
- · Lane change and rear parking assistant
- Telephone: Phonebox with inductive charging function (connection via the external antenna)
- · Bluetooth hands-free phone system

- · Shelves
- · Airbag, driver and passenger
- · Airbag, head airbags
- · Ambient lighting
- · Traction control (ASR)
- · Automatically dimming exterior mirror (driver's side)
- Exterior mirrors with memory function
- Heated windscreen washer nozzles including 5l washer fluid reservoir
- · Glasses compartment on the roof lining
- · Roof rails, anodized
- · Digital instrument cluster (Virtual Cockpit) 10.2"
- · Third brake light
- · Electronic transverse differential lock (XDS+)
- · Driving light assistant
- Electric windows front and rear, including anti-pinch protection and child safety lock
- · Cruise control system
- Tinted windows
- · Taillights in crystal glass look and animated indicators
- · Heated rear window
- · Interior mirror automatically dimming
- · Kessy, keyless entry and start-stop system
- · Electronic child lock
- · Removable trunk cover
- · LED fog lights
- · LED license plate lighting
- · Remote release of the rear seat backrests in the trunk
- Steering wheel: Leather steering wheel with multifunction buttons with shift paddles
- · Front center armrest, including storage compartment
- · Parking sensors front and rear
- · Radio: Bolero music system with capacitive 10" color display
- · Radio accessories: Digital radio reception DAB+
- Rain sensor
- · Tire mobility set
- · Power steering, electromechanical
- · Safety lights in the front side doors
- Seats: Electrically adjustable front seats with memory function
- SKODA Care Connect
- · Lane keeping assistant (Lane Assist)
- · 12-V socket in the trunk
- Phone: SmartLink (MirrorLink, Apple CarPlay, Android Auto)
- Phone: Wireless SmartLink for Apple CarPlay
- · Lashing eyes in the trunk
- Central locking including remote control integrated in the key and EASY Start

TÜV SÜD Auto Partner GmbH

Gutenbergstr. 13

70771 Leinfelden-Echterdingen

Inspection location Hartmann Fleet Professionals GmbH Industriestraße 11 36272 Niederaula



Immobiliser

Extra equipment

- · Decorative strips in piano black
- · Finish: pearl effect
- Package: Lights & Vision (cornering light in the fog lights headlight cleaning system - LED ambient lighting - LED main headlights matrix and dynamic high beam assistant (AFS) - taillights in crystal glass look and animated indicators)
- Seats: Manually adjustable ergonomic front seats (massage function
 - electrically adjustable lumbar support extendable leg rest)

- · Comfort opening with electric tailgate operation
- Package: Infotainment Columbus Plus (Combi) (Columbus navigation system - Infotainment Online (3-year term) - Head-Up Display - Luggage net partition)
- Electric panoramic sunroof (no glasses compartment on the roof lining)
- Wheels: 18" Vega AERO alloy wheels, black, high-sheen finish (7.5J x 18, ET 48 with 225/45 R18 tires)
- Auxiliary heating

Brief expert findings

Documents submitted At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate

Part 1 (certificate) was not. (Copy)

VIN comparison The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted

documents was verified during the inspection by the undersigned.

Inspection The inspection conditions were sufficient for the assessment of the vehicle.

Lifting equipment and a pit were available for examining the vehicle.

Test drive No test drive/maneuvering was carried out during the inspection of the vehicle.

Engine function test An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Holes - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
4	Front bumper	Front bumper - Scratch(es) - Smart repair
5	Trim / covers	Carpet - front left side - Holes - Loss in value
6	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - Paint

Wear and tear

NO.	Component group	Description
1	Rear bumper	Rear bumper (Ladekante) - Scratched - No deduction

December

The vehicle shows signs of wear commensurate with its age and use.

Missing parts

Description

Documents - Service book

Inspection location Hartmann Fleet Professionals GmbH Industriestraße 11 36272 Niederaula



Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- · Description of core relevant information about the vehicle
- Documentation of equipment features
 (Delivery by third-party service providers)
- · Documentation of damage, defects, missing parts
- · Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
 (Functional tests of driver assistance systems are not included in the scope of services!)
- · a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Apparently, no repaired previous damage could be found on the vehicle.

Comments

- Der 2.Radsatz gehört nicht zur Ausstattung und wurde nicht in der Bewertung berücksichtigt.





Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view (Online link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres






Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Navigation






Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.





Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Damage 1: Trim / covers: Floor mats - Holes - Replace



Damage 1: Trim / covers: Floor mats - Holes - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace





Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 4: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 5: Trim / covers: Carpet - front left side - Holes - Loss in value



Damage 5: Trim / covers: Carpet - front left side - Holes - Loss in value





Damage 6: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Paint



Damage 6: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Paint



Damage 6: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Paint